



# Product Change Notification - SYST-08NHAV192

---

**Date:** 10 Jan 2018  
**Product Category:** Interface- Controller Area Network (CAN)  
**Affected CPNs:**    
**Notification subject:** ERRATA - MCP2515 Silicon Errata Errata Document Revision  
**Notification text:** SYST-08NHAV192

---

Microchip has released a new DeviceDoc for the MCP2515 Silicon Errata of devices. If you are using one of these devices please read the document located at [MCP2515 Silicon Errata](#) .

**Notification Status:** Final

**Description of Change:** Updated work around for transmit buffer reprioritization in CAN Module.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 10 Jan 2018

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

---

**Attachment(s):** [MCP2515 Silicon Errata](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers(CPN)
MCP2515-WMAAA
MCP2515T-I/STV11
MCP2515T-I/STRB4
MCP2515T-I/STRB2
MCP2515T-I/STG
MCP2515T-I/ST
MCP2515T-I/SOVAO
MCP2515T-I/SOV14
MCP2515T-I/SOV02
MCP2515T-I/SORB4
MCP2515T-I/SORB2
MCP2515T-I/SO
MCP2515T-I/ML
MCP2515T-E/STV13
MCP2515T-E/STV10
MCP2515T-E/STV07
MCP2515T-E/STV04
MCP2515T-E/STV03
MCP2515T-E/STRB4
MCP2515T-E/STRB2
MCP2515T-E/ST
MCP2515T-E/SOVAO
MCP2515T-E/SORB4
MCP2515T-E/SORB2
MCP2515T-E/SONS1
MCP2515T-E/SO
MCP2515T-E/MLVAO
MCP2515T-E/MLV12
MCP2515T-E/ML
MCP2515T-E/MF
MCP2515T-E/6NV08
MCP2515-I/STVAO
MCP2515-I/STRB4
MCP2515-I/STRB2
MCP2515-I/ST
MCP2515-I/SOVAO
MCP2515-I/SORB4
MCP2515-I/SORB2
MCP2515-I/SOGRB2
MCP2515-I/SO
MCP2515-I/PRB4
MCP2515-I/PRB2

MCP2515-I/P
MCP2515-I/MLV09
MCP2515-I/ML
MCP2515-E/STVAO
MCP2515-E/STRB4
MCP2515-E/STRB2
MCP2515-E/ST
MCP2515-E/SOVAO
MCP2515-E/SOV06
MCP2515-E/SOV05
MCP2515-E/SORB4
MCP2515-E/SORB2
MCP2515-E/SO
MCP2515-E/PRB4
MCP2515-E/PRB2
MCP2515-E/P
MCP2515-E/MLVAO
MCP2515-E/ML
MCP2515-E/6NV08
MCP25625T-E/SSVAO
MCP25625T-E/SS
MCP25625T-E/MLVAO
MCP25625T-E/MLV01
MCP25625T-E/ML
MCP25625-E/SSVAO
MCP25625-E/SS
MCP25625-E/MLVAO
MCP25625-E/ML

---

## MCP2515 Silicon Errata

---

The functionality of the MCP2515 device is described in the Device Data Sheet (DS20001801H), except for the anomalies described below.

### 1. Module: CAN Module

Under one specific condition, a transmit buffer can become corrupted.

1. A lower priority buffer (as configured via TXBnCTRL.TXP<1:0>) is "pending" transmission (not actually transmitting).
2. A higher priority buffer becomes "pending" during the trigger pulse ( $1t_{OSC}$  wide), which starts the transmission of the lower priority buffer.
3. The buffers attempt to reprioritize because the message has not actually started transmission. There is a small window ( $1t_{OSC}$  wide) where the buffer has been committed to transmit, but is still viewed as "pending" by the logic. If the higher priority buffer becomes "pending" during this window, the buffers will not reprioritize successfully and corruption will occur.

#### Work around

There are a few possible work arounds:

- Request-To-Send (RTS) the higher-priority buffer first to avoid the possibility of reprioritization errors.  
This could be implemented as follows:  
Configure Transmit Buffer 2 (TXB2), TXB1, and TXB0 with the same priority. Since all buffers are configured with the same priority, TXB2 will be transmitted first, followed by TXB1 and TXB0.  
Now follow the sequence:  
1) Load the first message to transmit in TXB2 and RTS TXB2.  
2) Load the second message to transmit in TXB1 and RTS TXB1.  
3) Load the third message to transmit in TXB0 and RTS TXB0.  
4) Now wait until TXB0 has transmitted its message, before reloading TXB2. This ensures that all three messages are transmitted in the correct order and the highest priority buffer is always requested first.  
Afterwards, restart the sequence from Step 1.

- RTS of all full buffers at the same time. The internal buffer priority will determine the transmission sequence.
- Send messages one at a time (i.e., check TXnIF before sending the next message).

### 2. Module: SPI Module

Holding  $\overline{CS}$  low for a long time after an SPI command, which initiates a CAN message, may keep the CAN transmit request "pending", causing the CAN message to be repeated.

Two scenarios:

1. Generating an "SPI RTS" command while in SPI Mode 11 (Mode 00 is not affected): If an "SPI RTS" command is generated and  $\overline{CS}$  is held low for longer than it takes for the CAN message to transmit, the message will be transmitted again. This occurs because the SPI module will keep the message "pending" either until it detects a final rising edge on SCK (Mode 11 does not provide this edge) or until  $\overline{CS}$  goes high.
2. Generating an "SPI Byte Write" to set the transmit request (TXREQ) bit directly while in either SPI mode: This scenario is the same as the previous, except that the condition will occur in either mode (Mode 00 or Mode 11). This occurs because, for byte writes, the SPI module will release the pending status to the CAN module when  $\overline{CS}$  is high.

#### Work around

There are a few possible solutions:

- Raise  $\overline{CS}$  before the CAN message has "completed" transmission, which is an absolute minimum of 47  $\mu$ s.
- If  $\overline{CS}$  cannot be raised in a timely manner (rare), Use the "SPI RTS" command on Mode 00.
- Use hardware pins ( $\overline{TXnRTS}$ ) to request transmission.

## 3. Module: Oscillator Module

**In silicon revisions prior to revision B2:** The oscillator module may continue to operate when the device is placed in Sleep mode if the DC voltage on the OSC1 pin is too low. The rest of the device enters Sleep mode normally. This scenario results in higher-than-specified standby current (IDDs).

### **Work around**

This issue was addressed and no longer occurs in silicon revision B2. See [Appendix B: “Silicon Revision History”](#) to determine how to identify silicon revision(s) prior to revision B2.

**Revision B0 and earlier:** Configure the crystal circuit such that the maximum input signal is achieved on the OSC1 pin without overdriving the crystal. This can be accomplished by using crystals that require minimal or no series resistance (Rs), as shown in the crystal circuit diagram of the Device Data Sheet. In addition, matching the capacitors (C1 and C2) may help.

## 4. Module: RAM Module

**In silicon revisions prior to revision B2:** Transmit buffer 1 and/or 2 could become corrupted if, while receiving a CAN message, an RTS occurs during the first oscillator cycle of TQ0 of selected bits in the CAN message. This corresponds to the MCP2515's internal CAN clock high time, which is 1 TOSC wide.

### **Work around**

This issue was addressed and no longer occurs in silicon revision B2. See [Appendix B: “Silicon Revision History”](#) to determine how to identify silicon revision(s) prior to revision B2.

**Revision B0 and earlier:** If using only one transmit buffer, use buffer 0. Otherwise, to ensure the correct message is transmitted 100% of the time, read the transmit buffer after the successful transmission to verify the contents.

## 5. Module: CAN Module

**In silicon revisions prior to revision B4:** Under one condition, the device will make the first five identifier bits all dominant (logic 0) regardless of the value in the transmit buffer ID register.

If the MCP2515 detects a Start-of-Frame (SOF) in the third bit of interframe space and if the MCP2515 is pending transmission of a message, the first five bits of the identifier will become dominant.

### **Work around**

**Revision B4 and later:** This issue was addressed and no longer occurs in silicon revisions B4 and later. See Appendix B to determine how to identify silicon revisions prior to revision B4.

**Revision B2 and earlier:** If possible, have the other nodes in the system filter out messages where the first five bits are dominant

## Clarifications/Corrections to the Data Sheet:

In the MCP2515 Data Sheet (DS20001801H), the following clarifications and corrections should be noted:

None.

## APPENDIX A: REVISION HISTORY

### Revision H (January 2018)

- Updated work around for transmit buffer reprioritization in CAN Module

### Revision G (March 2007)

- Added SPI Module

### Revision F (July 2006)

- Added CAN Module

### Revision E (October 2005)

- Updated CAN Module information in this document

### Revision D (February 2005)

- Added CAN Module to this document

### Revision C (September 2004)

- Added additional information to RAM Module
- Added Oscillator Module to this document

### Revision B (May 2004)

- Added RAM Module to this document

### Revision A (January 2004)

- Initial release of this document, silicon issue (Oscillator Module)

# MCP2515

## APPENDIX B: SILICON REVISION HISTORY

The following table and package marking information indicates how to determine the revision of the MCP2515 device. The revision information can be determined by the Year and Week Code of the manufacturer printed on the device.


**TABLE B-1: SILICON REVISION/DEVICE MARKING**

Silicon Revision	YYWWNNN		Comments
	Start Date	End Date	
Rev B4	0538NNN	—	In Production
Rev B2	0450NNN	0537NNN	
Rev B0	—	0449NNN	


**Legend:** "N" is any alphanumeric character.

### Package Marking Information


18-Lead PDIP



18-Lead SOIC



20-Lead TSSOP



<b>Legend:</b>	XX...X	Customer-specific information
	Y	Year code (last digit of calendar year)
	YY	Year code (last 2 digits of calendar year)
	WW	Week code (week of January 1 is week '01')
	NNN	Alphanumeric traceability code
	(e3)	Pb-free JEDEC designator for Matte Tin (Sn)
	*	This package is Pb-free. The Pb-free JEDEC designator (e3) can be found on the outer packaging for this package.
<b>Note:</b>	In the event the full Microchip part number cannot be marked on one line, it will be carried over to the next line, thus limiting the number of available characters for customer-specific information.	

---

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELoQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949 ==**

### Trademarks

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BeaconThings, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Helder, JukeBlox, KEELoQ, KEELoQ logo, Kleer, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, RightTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntelliMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PureSilicon, QMatrix, RightTouch logo, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2018, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-2547-2





# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-67-3636

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7289-7561

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820