




A Leading Provider of Microcontrollers & Analog Semiconductors

Product Change Notification - SYST-22DREG067

Date: 22 May 2010

Product Category: 8-bit Microcontrollers

Device Family: 

Notification subject: ERRATA - PIC16F631/677/685/687/689/690 Family Silicon Errata and Data Sheet Clarification

Notification text: SYST-22DREG067
Microchip has released a new DeviceDoc for the PIC16F631/677/685/687/689/690 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC16F631/677/685/687/689/690 Family Silicon Errata and Data Sheet Clarification](#).

Attachment(s): [PIC16F631/677/685/687/689/690 Family Silicon Errata and Data Sheet Clarification](#)

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), [click here to go to microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

PIC16F677

PIC16F631

PIC16F685

PIC16F687

PIC16F689

PIC16F690



PIC16F631/677/685/687/689/690

PIC16F631/677/685/687/689/690 Family Silicon Errata and Data Sheet Clarification

The PIC16F631/677/685/687/689/690 family devices that you have received conform functionally to the current Device Data Sheet (DS41262E), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in Table 1. The silicon issues are summarized in Table 2 through Table 6.

The errata described in this document will be addressed in future revisions of the PIC16F631/677/685/687/689/690 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of Table 2 through Table 6 apply to the current silicon revision.

Data Sheet clarifications and corrections start on page 12, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2, MPLAB ICD 3, PICKit™ 2 or PICKit™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger, PICKit™ 2 or PICKit™ 3.
2. From the main menu in MPLAB IDE, select Configure>Select Device, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (Programmer>Select Tool).
4. Perform a "Connect" operation to the device (Programmer>Connect). Depending on the development tool used, the part number and Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The Device ID values for the various devices and silicon revisions are shown in Table 1.

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾				
		A1	A3	A4	A5	A6
PIC16F631	142x	1				
PIC16F677	132x	1				
PIC16F685	04Ax		3	4	5	6
PIC16F687	132x		3	4	5	6
PIC16F689	134x		3	4	5	6
PIC16F690	134x		3	4	5	6

- Note 1:** The device and revision data is stored in the Device ID located at 2006h in program memory.
Note 2: Refer to the "PIC12F6XX/16F6XX Memory Programming Specification" (DS41204) for detailed information.

PIC16F631/677/685/687/689/690

TABLE 2: SILICON ISSUE SUMMARY (PIC16F631)

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾			
				A1	A2	A3	A4
Timer1	Ext. Crystal	5.1	Overflow may take additional count.	X			
Timer1	Ext. Crystal	5.2	Oscillator may stop running at low temps.	X			
Timer1	Ext. Crystal	5.3	Sleep in LP mode disables T1OSC.	X			
WDT/Timer0	Prescaler	6.	Spurious Reset may occur.	X			

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

TABLE 3: SILICON ISSUE SUMMARY (PIC16F677)

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾			
				A1	A2	A3	A4
SSP	Start Bit	2.1	Fail to recognize Start bit.				
SSP	SSPIF Flag	2.2	SSPIF flag set on first reception only.	X			
ADC/INTOSC	Freq. Disturbance	4.	Oscillator may stop running at low temps.	X			
Timer1	Ext. Crystal	5.1	Overflow may take additional count.	X			
Timer1	Ext. Crystal	5.2	Oscillator may stop running at low temps.	X			
Timer1	Ext. Crystal	5.3	Sleep in LP mode disables T1OSC.	X			
WDT/Timer0	Prescaler	6.	Spurious Reset may occur.	X			

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

TABLE 4: SILICON ISSUE SUMMARY (PIC16F685)

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾			
				A3	A4	A5	A6
ECCP	Auto-Shutdown	3.	Overflow may take additional count.	X	X		
ADC/INTOSC	Freq. Disturbance	4.	Oscillator may stop running at low temps.	X	X	X	X
Timer1	Ext. Crystal	5.1	Overflow may take additional count.	X	X	X	X
Timer1	Ext. Crystal	5.2	Oscillator may stop running at low temps.	X	X	X	X
Timer1	Ext. Crystal	5.3	Sleep in LP mode disables T1OSC.	X	X	X	X
WDT/Timer0	Prescaler	6.	Spurious Reset may occur.	X	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC16F631/677/685/687/689/690

TABLE 5: SILICON ISSUE SUMMARY (PIC16F687/PIC16F689)

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾			
				A3	A4	A5	A6
EUSART	Wake-up	1.1	WUE bit not clearing.	X	X		
EUSART	Auto-Baud	1.2	Incorrect baud rate after a break.	X	X		
EUSART	Auto-Baud	1.3	Baud rate value +2.	X	X		
EUSART	Auto-Baud	1.4	Delay after auto-baud before transmit.	X	X		
EUSART	Auto-Baud	1.5	R/W bit on $\overline{\text{ACK}}$.	X	X		
EUSART	Reset	1.6	Clock-stretching handling.	X	X		
EUSART	Extra Character	1.7	Multi-byte transmission.	X	X		
SSP	Start Bit	2.1	Fail to recognize Start bit.	X	X	X	
SSP	SSPIF Flag	2.2	SSPIF flag set on first reception only.	X	X	X	X
ADC/INTOSC	Freq. Disturbance	4.	Oscillator may stop running at low temps.	X	X	X	X
Timer1	Ext. Crystal	5.1	Overflow may take additional count.	X	X	X	X
Timer1	Ext. Crystal	5.2	Oscillator may stop running at low temps.	X	X	X	X
Timer1	Ext. Crystal	5.3	Sleep in LP mode disables T1OSC.	X	X	X	X
WDT/Timer0	Prescaler	6.	Spurious Reset may occur.	X	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

TABLE 6: SILICON ISSUE SUMMARY (PIC16F690)

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾			
				A3	A4	A5	A6
EUSART	Wake-up	1.1	WUE bit not clearing.	X	X		
EUSART	Auto-Baud	1.2	Incorrect baud rate after a break.	X	X		
EUSART	Auto-Baud	1.3	Baud rate value +2.	X	X		
EUSART	Auto-Baud	1.4	Delay after auto-baud before transmit.	X	X		
EUSART	Auto-Baud	1.5	R/W bit on $\overline{\text{ACK}}$.	X	X		
EUSART	Reset	1.6	Clock-stretching handling.	X	X		
EUSART	Extra Character	1.7	Multi-byte transmission.	X	X		
SSP	Start Bit	2.1	Fail to recognize Start bit.	X	X	X	
SSP	SSPIF Flag	2.2	SSPIF flag set on first reception only.	X	X	X	X
ECCP	Auto-Shutdown	3.	Overflow may take additional count.	X	X	X	X
ADC/INTOSC	Freq. Disturbance	4.	Oscillator may stop running at low temps.	X	X	X	X
Timer1	Ext. Crystal	5.1	Overflow may take additional count.	X	X	X	X
Timer1	Ext. Crystal	5.2	Oscillator may stop running at low temps.	X	X	X	X
Timer1	Ext. Crystal	5.3	Sleep in LP mode disables T1OSC.	X	X	X	X
WDT/Timer0	Prescaler	6.	Spurious Reset may occur.	X	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC16F631/677/685/687/689/690

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision.

1. Module: EUSART (PIC16F687/689/690 only)

1.1 WUE Bit is not clearing.

After a wake-up due to a Break character, the WUE bit is not automatically cleared.

Work around

Clear the WUE bit after waking up.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

1.2 Auto-baud captures the incorrect baud rate after a break.

The SPBRGH:SPBRG registers are not being initialized correctly. If WUE and ABDEN are set at the same time and a Break character followed by a Sync character are received, then the calculated baud rate will be random.

Work around

Set WUE and wait for the wake-up to occur.

Clear SPBRGH:SPBRG after waking up with the break.

Set ABDEN to begin the auto-baud process.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

1.3 Auto-baud calculates a baud rate value that is +2.

The SPBRGH:SPBRG are not initialized correctly when ABDEN is set. This causes the measured baud rate to be high by two counts.

Work around

Clearing the SPBRGH:SPBRG registers will correctly initialize the baud rate counter. After the auto-baud has been completed, the baud rate will now be +1. The firmware should now subtract 1 from the Baud Rate Generator to produce the correct baud rate.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

1.4 Delay after auto-baud before transmit is allowed.

After the auto-baud Sync character has been received and the RCIF flag is set, there is approximately 17 ms of delay before the transmitter is enabled.

Work around

After the RCIF flag is set indicating the baud rate has been measured, read the SPBRG register and write the value back to SPBRG. This will terminate the delay, and enable the transmitter module.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

PIC16F631/677/685/687/689/690

1.5 Auto-baud sequence cannot be aborted in some cases.

If an auto-baud is started but no edges are received, there is no way to leave Auto-Baud mode.

Work around

Use the Watchdog Timer to reset the entire device.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

1.6 Clearing SPEN does not reset EUSART state machine correctly.

When SPEN is cleared, the entire EUSART is frozen. When SPEN is set, the EUSART resumes where it left off. This can cause some unexpected behavior.

Work around

To reset the EUSART, toggle TXEN and CREN after clearing SPEN. This will reset the transmit and receive state machines.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

1.7 Extra character transmitted after auto-baud.

If TXEN is high when ABDEN is set, it will be cleared as soon as the auto-baud process begins, and reset as soon as the auto-baud process completes. When TXEN is reset, the character in the transmit queue will be transmitted.

Work around

Before starting auto-baud, clear TXEN. This will reset the transmit state machine correctly. After the auto-baud is complete and the firmware has brought TXEN high, no character will be transmitted.

Fix

Rev. A5 Silicon and later revisions.

Affected Silicon Revisions

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X						

PIC16F631/677/685/687/689/690

2. Module: SSP (PIC16F687/689/690 only)

2.1 SSP module does not recognize first Start bit received.

In any of the I²C™ modes, the SSP module will fail to recognize the first Start bit received after a transition from module disable to module enable. Subsequent Stop bits and Start bits are detected properly.

Work around

Enable the SSP module in SSPMSK Access mode before changing the mode to the desired I²C operation.

EXAMPLE 1: CODE EXAMPLE

```

MOVLW B'00111001' ;Module enable, clock
MOVWF SSPCON      ;enable, SSPMSK access.
                  ;Optionally load
                  ;address mask value
                  ;into SSPMSK register.
MOVLW B'00110110' ;Module enable, clock
MOVWF SSPCON      ;enable, 7-bit address
                  ;I2C slave.
    
```

Fix

Rev. A6 Silicon and later revisions.

Affected Silicon Revisions

PIC16F677

A1							

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X	X					

2.2 Under certain conditions, the SSPIF flag sets on reception of the first byte.

When all of the following conditions are met:

- The module is configured as a SPI slave
- CKP = 1
- CKE = 1
- Multiple bytes are sent with the \overline{SS} line remaining low between bytes

The SSPIF flag will only be set on reception of the first byte and the following bytes will not be correctly received.

Work around

- Toggle the \overline{SS} line between bytes
or
- On reception of the first byte modify the SSPM bits in the SSPCON register to configure the module as a SPI slave with \overline{SS} pin disabled. Then restore the SSPM bits to the configuration for SPI slave with \overline{SS} pin enabled. The module is then ready for reception of the following byte.

Fix

None.

Affected Silicon Revisions

PIC16F677

A1							
X							

PIC16F687/PIC16F689/PIC16F690

A3	A4	A5	A6				
X	X	X	X				

PIC16F631/677/685/687/689/690

3. Module: ECCP with Auto-Shutdown (Silicon Rev. A4 and previous revisions) (PIC16F685 and PIC16F690 only)

The PIC16F631/677/685/687/689/690 Rev. A4 silicon for the ECCP auto-shutdown is connected to the C1IF and C2IF flags. See Figures 8-2 and 8-3 on the following page.

The auto-shutdown connection (Rev. A4 and previous) to C1IF and C2IF causes the auto-shutdown to incorrectly operate synchronously. Additionally, reads of CMxCON0 will incorrectly clear an auto-shutdown event.

Work around

Rev. A4 Silicon and previous revisions.

- 1) Poll the CxOUT bit until it is low.
- 2) Read CMxCON0 to precondition CxIF.
- 3) If CMxCON0 is read while CxOUT is changing, repeat steps 1 and 2.

Fix

Rev. A5 Silicon and later revisions.

The Silicon Rev. A5 (now shipping) and later revision devices have moved the auto-shutdown connection from CxIF to CxOUT. This will eliminate the synchronous shutdown and simplify the use of the comparator for a shutdown event. Figure 1 shows the function of auto-shutdown before and after the device revision.

Affected Silicon Revisions


PIC16F685

A3	A4	A5	A6				
X	X						

PIC16F690

A3	A4	A5	A6				
X	X	X	X				

FIGURE 8-2: COMPARATOR C1 SIMPLIFIED BLOCK DIAGRAM



PIC16F631/677/685/687/689/690

FIGURE 8-3: COMPARATOR C2 SIMPLIFIED BLOCK DIAGRAM





FIGURE 1: SILICON REVISION A4 AND PREVIOUS VS. REVISION A5



PIC16F631/677/685/687/689/690

4. Module: Analog-To-Digital Converter (ADC) Module (PIC16F685/687/689/690 Only)

Selecting the VP6 reference as the analog input source (CHS<3:0> = 1101) for the ADC conversion after sampling another analog channel with input voltages approximately greater than 1.2V can temporarily disturb the HFINTOSC oscillator.

Note: This only occurs when selecting the VP6 reference ADC channel using the CHS<3:0> bits in the ADCON0 register and NOT during the start of an actual ADC conversion using the GO/DONE bit in the ADCON0 register.

Work around

Select an ADC channel with input voltages lower than 1.2V prior to selecting the VP6 reference voltage input. Any analog channel can be used, even if that channel is configured as a digital I/O (configured as an output) that is driving the output pin low. An alternative is to configure the CVREF module to output a voltage less than 1.2V and then selecting that analog channel CHS<3:0> = 1100 as the analog input source.

EXAMPLE 2: AVOID DISTURBING THE HFINTOSC OSCILLATOR

```
BANKSEL    ADCON0    ;
MOVLW     B'XX110001' ;Select ADC
MOVWF     ADCON0     ;Channel CVREF
MOVLW     B'XX110101' ;Select ADC
MOVWF     ADCON0     ;Channel VP6
```

Silicon Fix

None.

Affected Silicon Revisions

PIC16F677

A1								
X								

PIC16F685/PIC16F687/PIC16F689/
PIC16F690

A3	A4	A5	A6				
X	X	X	X				

5. Module: Timer1

5.1 Asynchronous Timer1

This Errata supersedes Errata DS80233 and DS80329.

When Timer1 is started or updated, the timer needs to see a falling edge from the external clock source before a rising edge can increment the counter. If writes to TMR1H and TMR1L are not completed while the external clock pulse is still high, Timer1 will not count the first clock pulse after the update.

When using an external crystal, the pulse width from rising to falling edge is temperature dependent and may decrease with temperature. As a result, the timer may require an additional oscillation to overflow.

Work around

Switching to the HFINTOSC after reloading, the timer ensures the Timer1 will see a falling edge before switching back to the external clock source.

Due to the time from Timer1 overflow to the reload being application specific, wait for the timer to increment before beginning the reload sequence. This ensures the timer does not miss a rising edge during reload.

Affected Silicon Revisions

PIC16F631/PIC16F677

A1							
X							

PIC16F685/PIC16F687/PIC16F689/
PIC16F690

A3	A4	A5	A6				
X	X	X	X				

PIC16F631/677/685/687/689/690

EXAMPLE 3:

```

BTFSF    TMR1L,0
GOTO     $-1
BTFSF    TMR1L,0
GOTO     $-1           ;Timer has just incremented, 31 μs before next rising edge to
                       ;complete reload

Update:

BCF      T1CON,TMR1CS ;Select HFINTOSC for Timer1
BSF      TMR1H,7      ;Timer1 high byte 0x80
BCF      T1CON,TMR1ON ;Timer1 off
BSF      T1CON,TMR1CS ;Select external crystal
BCF      T1CON,TMR1ON ;Timer1 on

Critical Timing of code sequence for instructions following last write to TMR1L or TMR1H.

```

5.2 LP/Timer1 Oscillator Operation Below 25°C

1-2% of devices experience reduced drive as temperatures approach -40°C. This will result in a loss of Timer1 counts or stopped Timer1 oscillation.

This can also prevent Timer1 oscillator start-up under cold conditions.

Work around

Use of low-power crystals properly matched to the device will reduce the likelihood of failure. A 1MΩ resistor between OSC2 and VDD will further improve the drive strength of the circuit.

Affected Silicon Revisions

PIC16F631/PIC16F677

A1							
X							

PIC16F685/PIC16F687/PIC16F689/
PIC16F690

A3	A4	A5	A6				
X	X	X	X				

5.3 LP/Timer1 Oscillator Shared Operation

When using LP oscillator as the system clock and enabling Timer1 external oscillator, the shared crystal will clock both the core and Timer1. On execution of the SLEEP instruction, the oscillator amplifier will be disabled and Timer1 will not be clocked while the device is in Sleep.

Work around

None.

Affected Silicon Revisions

PIC16F631/PIC16F677

A1							
X							

PIC16F685/PIC16F687/PIC16F689/
PIC16F690

A3	A4	A5	A6				
X	X	X	X				

PIC16F631/677/685/687/689/690

6. Module: Timer0 and WDT Prescaler Assignment Spurious Reset

A spurious Reset may occur if the Timer0/Watchdog Timer (WDT) prescaler is assigned from the WDT to Timer0 and then back to the WDT.

Summary

The issue only arises when all of the below conditions are met:

- Timer0 external clock input (TOCKI) is enabled.
- The Prescaler is assigned to the WDT, then to the Timer0 and back to the WDT.
- During the assignments, the TOCKI pin is high when bit TOSE is set, or low when TOSE is clear.
- The 1:1 Prescaler option is chosen.

Description

On a POR, the Timer0/WDT prescaler is assigned to the WDT.

If the prescaler is reassigned to Timer0 and Timer0 external clock input (TOCKI) is enabled then the prescaler would be clocked by a transition on the TOCKI pin.

On power-up, the TOCKI pin is (by default) enabled for Timer0 in the OPTION register.

If the TOCKI pin is:

- High and Timer0 is configured to transition on a falling edge (TOSE set), or
- Low and Timer0 is configured to transition on a rising edge (TOSE clear)

Then, if the prescaler is reassigned to the WDT, a clock pulse to the prescaler will be generated on the reassignment.

If the prescaler is configured for the 1:1 option, the clock pulse will incorrectly cause a WDT Time-out Reset of the device.

Work around

1. Disable the Timer0 external clock input by clearing the TOCKI bit in the OPTION register.
2. Modify the TOSE bit in the OPTION register to the opposite configuration for the logic level on the TOCKI pin.
3. Select a prescaler rate other than 1:1 and issue a CLRWDT instruction before switching to the final prescaler rate.

Affected Silicon Revisions

PIC16F631/PIC16F677

A1							
X							

PIC16F685/PIC16F687/PIC16F689/
PIC16F690

A3	A4	A5	A6				
X	X	X	X				

PIC16F631/677/685/687/689/690

Data Sheet Clarifications

The following typographical corrections and clarifications are to be noted for the latest version of the device data sheet (DS41262E):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Peripheral Features

Corrections to Table 1: PIC16F631 Pin Summary.

TABLE 1: PIC16F631 PIN SUMMARY

I/O	Pin	Analog	Comparators	Timers	Interrupt	Pull-up	Basic
RA0	19	AN0/ULPWU	C1IN+	—	IOC	Y	ICSPDAT
RA1	18	—	C12IN0-	—	IOC	Y	ICSPCLK
RA2	17	—	C1OUT	T0CKI	IOC/INT	Y	—
RA3	4	—	—	—	IOC	Y ⁽¹⁾	$\overline{\text{MCLR}}/\text{VPP}$
RA4	3	—	—	$\overline{\text{T1G}}$	IOC	Y	OSC2/CLKOUT
RA5	2	—	—	T1CKI	IOC	Y	OSC1/CLKIN
RB4	13	—	—	—	IOC	Y	—
RB5	12	—	—	—	IOC	Y	—
RB6	11	—	—	—	IOC	Y	—
RB7	10	—	—	—	IOC	Y	—
RC0	16	—	C2IN+	—	—	—	—
RC1	15	—	C12IN1-	—	—	—	—
RC2	14	—	C12IN2-	—	—	—	—
RC3	7	—	C12IN3-	—	—	—	—
RC4	6	—	C2OUT	—	—	—	—
RC5	5	—	—	—	—	—	—
RC6	8	—	—	—	—	—	—
RC7	9	—	—	—	—	—	—
—	1	—	—	—	—	—	VDD
—	20	—	—	—	—	—	VSS

Note 1: Pull-up enabled only with external $\overline{\text{MCLR}}$ configuration.

PIC16F631/677/685/687/689/690

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (7/2005)

Original release of this document.
Clarifications/Corrections to the Data Sheet:
Added Modules 1 through 7:
Module 1: Device VDD Range
Module 2: 4x4 QFN Package Marking
Module 3: Table 1-1: Pinout Description – PIC16F685
Module 4: Register 10-5: EECON1
Module 5: Table 11-2: Registers Associated with Capture, Compare and Timer1
Module 6: Section 12.0 EUSART
Module 7: Section 14.2.2 MCLR

Rev B Document (8/2005)

Silicon Section:
Added Module 1: EUSART (PIC16F687/689/690 only).
Clarifications/Corrections to the Data Sheet:
Added Modules 8 and 9:
Module 8: SSP Module Overview
Module 9: Electrical Specifications.

Rev C Document (11/2005)

Silicon Section:
Added Module 2: SSP (PIC16F687/689/690 only)

Rev D Document (01/2006)

Clarifications/Corrections to the Data Sheet:
Replaced the 20-Lead QFN package diagram in Module 2: 4x4 QFN Package Marking.

Rev E Document (7/2006)

Data Sheet Clarifications/Corrections Section:
Removed Items 1 through 9, which have been incorporated into the data sheet. Added Item 1, 20-pin QFN Pin Diagram Title change.

Rev F Document (11/2006)

Data Sheet Clarifications/Corrections Section: Added Item 2, Product Identification System, Examples change.

Added Module 3: ECCP with Auto-Shutdown (Silicon Rev. B2). Updated Module1: EUSART (PIC16F687/689/690 only) and Module2: SSP (PIC16F687/689/690 only) with Fix information.

Rev G Document (01/2007)

Removed Rev. A6 reference from Module 2 (SSP).
Data Sheet Clarifications/Corrections Section: Added Module 3, Comparator and Voltage Reference Modules Associated Registers, removed REFCON register reference. Added Module 4: DC Characteristics, Table 17.3, revised Max values.

Rev H Document (07/2007)

Added Module 4: Analog-to-Digital Converter (ADC) Module. Module 2: Added Fix.

Rev J Document (09/2008)

Added Module 2.2: Under certain conditions, the SSPIF flag sets on reception of the first byte (under new 2. SSP (PIC16F687/689/690 only)), while changing Module 2. to 2.1. Revised Module 5: LP/Timer1 Oscillator Operations Below 25°C. Added Module 6: SSP.

Clarifications/Corrections to the Data Sheet:
Removed Modules 1 through 4, which have been included in the latest data sheet revision.

Rev K Document (04/2009)

Updated Errata to new format.
Deleted Module 6: SSP (PIC16F687/689/690).

Added Module 5: Timer1; Added Module 6: Timer0 and WDT Prescaler Assignment Spurious Reset.

Rev L Document (07/2009)

Data Sheet Clarifications: Added Module 1: Peripheral Features (Table 1: PIC16F631 Pin Summary).

Rev M Document (05/2010)

Added Module 5.3.

PIC16F631/677/685/687/689/690

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Octopus, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICTail, REAL ICE, rLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2010, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-60932-223-6

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland

Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara

Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney

Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing

Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hong Kong SAR

Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing

Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao

Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan

Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian

Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen

Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai

Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore

Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi

Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama

Tel: 81-45-471-6166
Fax: 81-45-471-6122

Korea - Daegu

Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang

Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila

Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu

Tel: 886-3-6578-300
Fax: 886-3-6578-370

Taiwan - Kaohsiung

Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei

Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok

Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels

Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen

Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich

Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan

Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen

Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid

Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham

Tel: 44-118-921-5869
Fax: 44-118-921-5820