



09-Sep-2013

PCN #:P-13-009483

Subject:0.64MM FEMALE CONTACT,AU,18-20; 0.64MM FEMALE CONTACT,AU,22A

Description of Change: TE Global Automotive Division will be updating the customer to reflect changing the location of the gold identifier from the receptacle box opening to the helper spring (Note 3). There will be no change to raw material composition nor will electrical, mechanical, and environmental performance be affected. This activity will be completed once all due diligence is performed (ex. PSW, Prints, etc)

Reason: Part status change.This product uses flash gold as a visual aid. The location of the gold identifier is independent of product function and therefore making this a very low risk change. The helper spring is clearly visible through an opening in the receptacle box which is located in close proximity to the transition area of the receptacle. Moving the gold identifier closer to the crimping area will provide our Customers with improved gold verification since the crimping process is the first step in harness manufacturing.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:01-Dec-2013

Implementation Date:01-Dec-2013

Product Affected

1326028-2

1326028-1

1326028-5

1326028-6

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.