

## Product Change Notification

[Home](#)

The information below reflects a change that is being implemented.

Notice Date: 03/12/2003  
Product Category: In Circuit Debuggers  
Notification Subject: MPLAB ICD 2 Self -Test Failures

Notification Body:

We have had some reports of problems with MPLAB ICD 2 self-test failures after upgrading from MPLAB 6.12 to 6.13 (there was an MPLAB ICD 2 firmware change in v6.13). As a result, we are posting new firmware on our FTP site that does not exhibit these issues. Please download these files into the \ICD2 folder under your MPLAB installation directory and restart MPLAB. The update should be automatic, but you can also select "Debugger>Download ICD2 Operating System" to manually update your firmware.

These files are  
for PIC12F/16F Devices ICD01020007.hex  
for PIC18F Devices ICD04020005.hex

Access to the FTP site:

- go to: ftp.microchip.com
- select folder: devtools
- use password: needtools

Close