

Product/Process Change Notifications



PCN - 18 059

Amphenol Information Communication and Commercial Products Group
www.amphenol-icc.com

Release Date: July 27 2018

Product Name:	USB2.0 Receptacle Connector			
	87583 / 72309 / 87520 series			
Product Manager:	Loke, Chung-Ling			
Subject:	Notification of Planned Change			
Distribution:	Global			
Type of Change:	Design Change			
Change Description:	Plating Change for shell from "over all bright tin plating" to "selected matt tin plating on solder legs"			
Reason for Change:	Performance Improvement			
Affected Parts:	See Affected Parts file			
Effective Date of Change:	November 20, 2018			
Last Time Buy Date:	NA			
Earliest Disty Return Date:	NA			
Last Time Shipment Date	NA			
Datasheet Attached?	NA			
Qual/Test Data Attached?	NA			
Samples Availability Date:	August	20	2018	
Available Alternatives?	N/A			
Questions?	<i>Contact your local FCI Representative, or Product Manager</i>			
	<i>Loke, Chung-Ling/ Product Manager</i>			
	<i>+65 65496674 / chung-ling.loke@fci.com</i>			

Note:

Customers should contact Product Manager (or their local AFCI /AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date	Last Disty Return date	Last Shipment date	Alternative Parts	Product Family	Primary MU	Product Manager	Status
PCN18059	55917-000LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	OBSOLETE
PCN18059	55917-001LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	55917-500LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	55917-501LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	SMARTER SERVICE
PCN18059	55917-600LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	55917-601LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	55917-700LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	SMARTER SERVICE
PCN18059	55917-800LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	OBSOLETE
PCN18059	55917-801LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	OBSOLETE
PCN18059	55917-900LF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	OBSOLETE
PCN18059	72309-5023BPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-5023QPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	PRE-PRODUCTION
PCN18059	72309-5034BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	KILLED
PCN18059	72309-7013BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7013BPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7013RPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7014BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	SMARTER SERVICE
PCN18059	72309-7014BPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7014RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7024BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7024RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7033RPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7034BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7043BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7043RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7043RPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7044BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7044BPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	KILLED
PCN18059	72309-7044RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-7044RPSLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8014BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	SMARTER SERVICE
PCN18059	72309-8014RLF	Design Change	November 20,2018				511-527F-USB+POWER	4543-45430	CHUNG-LING.LOKE@FCI.COM	PRE-PRODUCTION
PCN18059	72309-8023BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8023RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8024BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	KILLED
PCN18059	72309-8024RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8033BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8034BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8034RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-8043BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	KILLED
PCN18059	72309-8044BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	SMARTER SERVICE
PCN18059	72309-8044RLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-9013RPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	72309-9043BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-0110ALF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-0110APLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-0110BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	SMARTER SERVICE
PCN18059	87520-0112ALF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-0112BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-1110ALF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-1110BLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-1110BPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-1112APLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87520-1112BPLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87583-0010BHLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87583-0010BLF	Design Change	November 20,2018				REMOVED FROM GPS	4340-43400	OTTO YANG	TO BE REMOVED
PCN18059	87583-0010RHLF	Design Change	November 20,2018				511-526F-USB	4543-45430	CHUNG-LING.LOKE@FCI.COM	ACTIVE
PCN18059	87583-0010RLF	Design Change	November 20,2018				REMOVED FROM GPS	4340-43400	OTTO YANG	TO BE REMOVED
Count:	58									