

## Product Change Notice

Alps PCN: LO022823\_Disti

Date: February 28, 2023

<b>Type of Change:</b>	Discontinuation of Products
<b>Title of Change:</b>	2023 Notice of Discontinuation – Sensors, Switches, and Variable Resistors
<b>Description of Change:</b>	<p>Products will be discontinued due to the following reasons:</p> <ol style="list-style-type: none"> <li>1) Demand for this product became very low and we have had very few orders recently.</li> <li>2) The production equipment (Jigs/tools) get too old, or difficult to purchase materials.</li> <li>3) We have not received your PO for a long time.</li> </ol>

**Contact Information:** Sales and Marketing Contact  
[Sales@alps.com](mailto:Sales@alps.com)  
 Alps Alpine North America, Inc.

**Product Affected:** Sensors, Switches, and Variable Resistors

### AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Suggested Alternative	Part Number	Suggested Alternative
EC05E1220202	-	EC11E183440C	-
EC05E1220203	-	EC11E2434403	-
EC05E1220401	-	EC11EBB24C03	-
EC09E1520407	-	EC11G1564411	EC11M1565403
EC09E1524404	-	EC11J0920404	-
EC09E1524418	-	EC11J0924411	-
EC10E1220501	-	EC11J0925403	-
EC10E1220503	-	EC11J152040F	-
EC10E1260502	-	EC11J1524404	-
EC10E1260507	-	EC11J1524413	-
EC1110120005	-	EC11J1525402	-
EC111012000U	-	EC11K0920404	-
EC111012010H	-	EC11K0924401	-
EC1110120201	-	EC11K0924404	-
EC11B15242AF	-	EC11K0925401	-
EC11E09204A4	-	EC11K1520401	-
EC11E09244AQ	-	EC11K1524406	-
EC11E09244BS	-	EC11K1525413	-
EC11E0B2LB01	-	EC12D1524406	-
EC11E15244B2	-	EC12D1564402	-
EC11E15244G1	-	EC12D1564404	-
EC11E1534408	-	EC12E1220301	-
EC11E153440D	-	EC12E1220405	-
EC11E1820402	-	EC12E1220406	-
EC11E1834403	-	EC12E1220407	-

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**AFFECTED ALPS ALPINE PART NUMBERS**

Part Number	Suggested Alternative	Part Number	Suggested Alternative
EC12E1220813	-	EC35CH120401	-
EC12E1240301	-	EC40A1520403	-
EC12E1240405	-	EC40A1520405	-
EC12E1240406	-	EC50A0920404	-
EC12E24104A6	-	EM11B16140A4	-
EC12E2420301	-	EM11B16140AE	-
EC12E24204A2	-	EM20B4014000	-
EC12E24204A7	-	HGDEDM021A	-
EC12E24204A9	-	RD6R1A0008	-
EC12E2420801	-	RD7081015A	-
EC12E2420802	-	RD708A029A	-
EC12E2420803	-	RD7091008A	-
EC12E2430401	-	RD7121008A	-
EC12E2430404	-	RD712A028A	-
EC12E2430803	-	RDC1010A12	-
EC12E2430804	-	RDC1014A09	-
EC12E2440301	-	RDC1022A05	-
EC12E24404A8	-	RDC10320RB	-
EC12E2460802	-	RDC1047A03	-
EC18AGA20402	-	RDC501015A	-
EC18AGA20403	-	RDC502012A	-
EC18AGB20401	-	RDC503051A	-
EC20A1820401	-	RDC503052A	-
EC20A1824401	-	RDC506002A	-
EC21A0920401	-	RDC803001A	-
EC21A0950402	-	RDC803101A	-
EC21A1520401	-	RDC9010006	-
EC21A1520407	-	RDC9010007	-
EC21C1520402	-	RK08H11100UD	-
EC28A1520401	-	RK08H11100X7	-
EC28A1550407	-	RK08H11100XC	-
EC28A1560401	-	RK08H1110A04	-
EC28A1560501	-	RK08H1120A05	-
EC28A1850402	-	RK08H113003G	-
EC35A1520402	-	RK08H12100GP	-
EC35A1550502	-	RK08H122005A	-
EC35AH120401	-	RK08H123002K	-
EC35AH220403	-	RK09711100F8	-
EC35AH220502	-	RK09711100RA	-

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**AFFECTED ALPS ALPINE PART NUMBERS**

Part Number	Suggested Alternative	Part Number	Suggested Alternative
RK097111020N	-	RK09D1130A1N	-
RK097111080R	-	RK09D1130C2P	-
RK0971110909	-	RK09D117000B	-
RK097111091M	-	RK09D117000C	-
RK0971110D7F	-	RK09K11100E9	-
RK0971110D88	-	RK09K1110A2S	-
RK09711110AL	-	RK09K1110AK4	-
RK09711110EL	-	RK09K1110AY2	-
RK0971111Z0P	-	RK09K1110B1R	-
RK0971111Z32	-	RK09K1110B26	-
RK097111202Q	-	RK09K113004U	-
RK097111401U	-	RK09K1130081	-
RK0971114D0B	-	RK09K1130A5R	-
RK0971114Z07	-	RK09K1130A6S	-
RK0971114Z1J	-	RK09K1130A70	-
RK097111T064	-	RK09K1130A8G	-
RK097111TD44	-	RK09K1130AAU	-
RK097111TZ17	-	RK09K1130ACL	-
RK097111TZ29	-	RK09K1130ACM	-
RK097111U00S	-	RK09K1130AH1	-
RK097111UZ03	-	RK09K1130AJ3	-
RK0971210097	-	RK09K1130AP5	-
RK09712100AV	-	RK09K1130AU2	-
RK0971210Z2M	-	RK09K1130BM4	-
RK0971214Z06	-	RK09K1130D1U	-
RK097121TD57	-	RK09K1130D62	-
RK097122008T	-	RK09K12A0A6R	-
RK09712200HA	-	RK09K12A0B0W	-
RK09712200MC	-	RK09K12C0A19	-
RK09712200MT	-	RK09K12C0A8K	-
RK09712200MY	-	RK09K12C0A8P	-
RK0971221Z05	-	RK09L112003P	-
RK0971221Z11	-	RK09L1120A2S	-
RK097122200G	-	RK09L1120A69	-
RK0971224Z01	-	RK09L114001T	-
RK097122T017	-	RK09L1140A2U	-
RK097122TZ0A	-	RK09L1140A5E	-
RK097221004C	-	RK09L1140A5P	-
RK097221005C	-	RK09L1140A65	-

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**AFFECTED ALPS ALPINE PART NUMBERS**

Part Number	Suggested Alternative	Part Number	Suggested Alternative
RK09L1140A66	-	RK11K1140A9L	-
RK09L122002M	-	RK12L1210C0R	-
RK09L1220A1B	-	RK12L1210C1N	-
RK09L124000Z	-	RK12L123000E	-
RK09L1240A12	-	RK12L1230C0K	-
RK09L1240C2K	-	RK12L1230C1M	-
RK09L12B0A31	-	RK12L1270009	-
RK09L12B0A3Z	-	RK12L12C0A0A	-
RK09L12D0A1T	-	RK12L12C0A0E	-
RK09L12D0A1W	-	RK12L12C0A0G	-
RK09L12D0C0G	-	RK12L12C0C0V	-
RK09L12D0C1L	-	RK14K1210A1B	-
RK09L12D0C1M	-	RK14K122001W	-
RK09Y11L0001	-	RK14K1220024	-
RK10J11E002Y	-	RK14K1220A0F	-
RK10J11E0034	-	RK14K1220A25	-
RK10J11E0A0A	-	RK14K1230A0X	-
RK10J11R0A0H	-	RK14K1230A2X	-
RK10J12E0024	-	RK14K1240036	-
RK10J12E002L	-	RK14K1240062	-
RK10J12E0A0A	-	RK14K1240A4R	-
RK10J12R0052	-	RK14K1240D04	-
RK10J12R0A0B	-	RK14K12A0A3C	-
RK1191114001	-	RK14K12B0A0E	-
RK1191124001	-	RK14K12B0A0R	-
RK11K1110A3D	-	RK14K12C0A1S	-
RK11K1120060	-	RK14K12D0A18	-
RK11K1120A31	-	RK14K12D0A1X	-
RK11K1120A5T	-	RK1631110TBK	-
RK11K1130040	-	RK1631110TNP	-
RK11K1130A07	-	RK1631110TT3	-
RK11K1130A0M	-	RK1631110U0Q	-
RK11K1130A2X	-	RK1631110U1Q	-
RK11K114001Z	-	RK16312101A2	-
RK11K114003Y	-	RK1631210AWN	-
RK11K1140A23	-	RK1631210AX9	-
RK11K1140A2S	-	RK16312A0B85	-
RK11K1140A3L	-	RK16312A0BKH	-
RK11K1140A4Q	-	RK16312A0BKR	-

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**AFFECTED ALPS ALPINE PART NUMBERS**

Part Number	Suggested Alternative	Part Number	Suggested Alternative
RK16812MG097	-	RS20111A9A03	-
RK16812MG099	-	RS20H111C009	-
RK16812MG09T	-	RS20H113C008	-
RK16812MG0AQ	-	RS20H11AA015	-
RK16812MGA14	-	RS20H11AA019	-
RK16814MGA0K	-	RS20H11AA01U	-
RK271111001T	-	RS20H11AA02T	-
RK2711120026	-	RS20H12AC002	-
RK27112A00AK	-	RS3011114A02	-
RK27112A00B9	-	RS301111A01G	-
RK27112A00CC	-	RS301111C01L	-
RK27112B0A19	-	RS301111J00P	-
RK27114A0A0A	-	RS301111JA07	-
RK27114A0A0F	-	RS30111A602N	-
RK39A1A00007	-	RS30111A9012	-
RK39A1A00027	-	RS30111AC00V	-
RK39A1A00028	-	RS30111AJ01K	-
RK45C1A00003	-	RS30111AJ01R	-
RKJXK122400Y	-	RS3011246A02	-
RKJXM1015001	-	RS30112AC00J	-
RKJXM2E13004	-	RS30112AJA02	-
RKJXS1004001	-	RS30H111A00D	-
RKJXU1210006	-	RS30H11AA009	-
RKJXV1220001	-	RS30H11AA00G	-
RKJXV1224005	-	RS30H11AA00P	-
RKJXW1014002	-	RS30H11AAA02	-
RS08U11AZ001	-	RS30H11AAA0B	-
RS15111A900B	-	RS30H121A00B	-
RS15H111CA04	-	RS30H12AA003	-
RS15H113C001	-	RS4511166000	-
RS15H113CA05	-	RS45111A6A06	-
RS15H11AA008	-	RS45111A900F	-
RS15H11AA00G	-	RS45111ABA02	-
RS15H11AA04M	-	RS45111AJ00L	-
RS15H121A009	-	RS45111F9002	-
RS15H12AA009	-	RS451121400A	-
RS15H12AA00F	-	RS45112A400G	-
RS15M113CA02	RS15H	RS45112A600J	-
RS201111J011	-	RS60112A600N	-

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**AFFECTED ALPS ALPINE PART NUMBERS**

Part Number	Suggested Alternative
RS60112A600U	-
RS6011DP6002	-
RS6011DP6003	-
RS6011SP6003	-
RS6011SP6004	-
RS6011Y19004	-
RS6011Y64005	-
RS6011YA600M	-
RS6011YA9A06	-
RS60K11A9010	-
RS60K11K9A13	-
RS60N11M9A0F	-

Part Number	Suggested Alternative
RS60N11M9A0K	-
RS60N1219A04	-
RSA0K11A901L	-
RSA0K11K9A16	-
RSA0K11V901S	-
RSA0K12A1013	-
RSA0K12K9A14	-
RSA0N111900Q	-
RSA0N11M9A0J	-
RSA0N1219A03	-
RSA0N1269A04	-
SPVN110101	SPVN110107

---

<b>Alps Alpine Sites Affected:</b>	Americas
<b>Last Time Buy:</b>	March 30, 2023
<b>Last Time Ship:</b>	June 30, 2023

---

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.