



A Leading Provider of Microcontrollers & Analog Semiconductors

Product Change Notification - CYER-10JNWA553

Date: 11 Jan 2012

Product Category: Memory

Device Family: 

Notification subject: CCB 1059 Final Notice: Qualification of 48L TSOP at PTI_SZ Assembly Site.

Notification text:

PCN Status:
Final notification

Microchip Parts Affected:
See attachments of affected catalog part numbers (CPN) labeled as...
PCN_CYER-10JNWA553_Affected_CPN.xls
PCN_CYER-10JNWA553_Affected_CPN.pdf

Description of Change:
Qualification of 48L TSOP package at PTI_SZ assembly site.

Impacts to Data Sheet:
None

Reason for Change:
To Improve On-Time Delivery Performance

Change Implementation Status:
In Progress

Estimated First Ship Date:
January 30, 2012 (date code: 1203)

NOTE: Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

Markings to Distinguish Revised from Unrevised Devices:
Traceability code

Revision History:
June 22, 2011: Issued initial notification.
December 14, 2011: Issued final notification. Revised estimated first ship date from 10/5/2011 to 1/30/2012.

Note:
Qualification data will be made available upon request.

Attachment(s): [PCN_CYER-10JNWA553_Affected_CPN.xls](#)
[PCN_CYER-10JNWA553_Affected_CPN.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

SST38VF6401
SST38VF6402
SST38VF6403
SST38VF6404
SST39LF200A
SST39LF400A
SST39LF800A
SST39VF1601
SST39VF1601C
SST39VF1602
SST39VF1602C
SST39VF1681
SST39VF1682
SST39VF200A
SST39VF3201
SST39VF3201B
SST39VF3202
SST39VF3202B
SST39VF400A
SST39VF6401B
SST39VF6402B
SST39VF800A