

PRODUCT CHANGE NOTIFICATION

Product Category POWER CONNECTORS **20230908-4**

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: 08-Sep-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Introduction of more parts per box for our CB, LAM2, LAMA, LIAS, LICC power and grounding mechanical connector families. They will be moving from 3 -100 pcs per box to 5 -250 pcs per box and will not be able to be ordered in smaller increments.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	9	15
Old product discontinuation date*	2023	12	15

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		

LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
CB175-38-QY	Direct	CB175-38-L			15-SEP-2023
CB70-14-CY	Direct	CB70-14-190			15-SEP-2023
LAM2A1/0-14-6Y	Direct	LAM2A1/0-14-Q			15-SEP-2023
LAM2A2/0-14-6Y	Direct	LAM2A2/0-14-Q			15-SEP-2023
LAM2A250-38-6Y	Direct	LAM2A250-38-X			15-SEP-2023
LAM2A350-12-6Y	Direct	LAM2A350-12-5			15-SEP-2023
LAM2B350-12-3Y	Direct	LAM2B350-12-8			15-SEP-2023
LAMA1/0-14-QY	Direct	LAMA1/0-14-L			15-SEP-2023
LAMA2/0-14-QY	Direct	LAMA2/0-14-L			15-SEP-2023
LAMA2-14-QY	Direct	LAMA2-14-C			15-SEP-2023
LAMA500-38-6Y	Direct	LAMA500-38-5			15-SEP-2023
LAMA6-14-QY	Direct	LAMA6-14-C			15-SEP-2023
LIAS250-56-Q	Direct	LIAS250-56-X			15-SEP-2023
LICC4-22-C	Direct	LICC4-22-TL			15-SEP-2023
LICC4-22TP-C	Direct	LICC4-22TP-TL			15-SEP-2023

Replacement Type Definition

DIRECT
REPLACEMENT

Exact same part in a different package size, or has any other update that doesn't change the product itself

COMPATIBLE

The replacement part is different in a way that allows it to be used for some applications, but it is not the same part. The difference can be in color, size, material, or performance (like *CAT5 to CAT6*), etc.

COMPLEX

The replacement part(s) are too dissimilar to assume it can easily replace the discontinued part, however Panduit can offer a replacement which may be used in certain applications. Customer Experience should be contacted.

NO REPLACEMENT

No replacement product is available.