

SCHURTER INC
447 Aviation Boulevard
Santa Rosa, CA 95403



TEL 707 636 3000
FAX 707 636 3033
www.schurter.com

February 23, 2018

Hello,

You are receiving this notification because SCHURTER is requesting our distributors to return their inventory of the following part numbers:

Part Number	Description
0031.1659	FEU SICHERUNGSHALTER 6.3X32 IP 40
0031.1661	FEU Kopf 6.3x32 IP40
0031.1672	FEU FUSEHOLDER 6.3X32 IP 40
0031.3822	FAC FUSEHOLDER 6.3X32 IP 40
0031.1764	FEU SICHERUNGSHALTER 6.3X32 IP 40
0031.3581	FAU SICHERUNGSHALTER 6.3X32 IP 40

The affected date codes range is from only 1747 through 1807. Other date codes are not impacted by this issue.

The SCHURTER Quality department informed us today that there could be an issue with the pressure-spring on these parts which could lead to insufficient contact between the fuse and fuseholder.

Please contain the part numbers that fall within the **1747 through 1807 date code range**, and confirm the quantity you have in inventory. Once I receive your confirmation, I will issue a RMA to return the parts at SCHURTER's expense, and work with you on getting you replacements.

We will follow-up with another letter with how to address this issue with your end customers.

Thank you for your help with this and please feel free to call me if you have any questions.

Best regards,



Gisela Babb
Quality Manager

SCHURTER Inc
Santa Rosa CA
707 636 5493

www.schurter.com