1 **Products affected**

| Product hierarchy no. * | Part no. | SBU | Type / Description | n | Customer part no. | | |
|---|-------------------|------------|--------------------|----------------|-------------------|--|--|
| SBU PG PUG Type | | | | | | | |
| 02 007 013 000000229 | 97 See list below | Connectors | 4797 Appliance | Outlet 16A 70° | | | |
| *SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit) | | | | | | | |
| List of part numbers affected | | | | | | | |
| | | 4707.04 | | | 1707 0005 | | |
| 4797.0000 | 4797.0010 | 4797.00 | J12 4 | 4797.0015 | 4797.0025 | | |
| 4797.0030 | 4797.0100 | 4797.01 | 110 4 | 4797.0112 | 4797.0115 | | |
| 4797.0120 | 4797.0125 | 4797.01 | 130 4 | 4797.3010 | 4797.3012 | | |
| 4797.3015 | 4797.3020 | 4797.30 | 030 | 4797.3100 | 4797.3110 | | |
| 4797.3112 | 4797.3115 | 4797.31 | 120 | 4797.3125 | 4797.3130 | | |

The part numbers 4797.0020, 4797.3000 and 4797.3025 are not part of this change. The change for said three part numbers will be executed at a later stage.

2 Type of change

Two laterally positioned notches added to the molding body.

3 Detailed description of change

| Old product appearance Screw-on version | New product appearance Screw-on version |
|--|---|
| Screw-on version | Screw-on version |
| | |
| | |
| Snap-in version | Snap-in version |
| | |
| Product Change Notification | PCN - 4797 Cord Retention Notches Added |

| Product Change Notification | | | PCN - 4797 Cord Retention Notches Added | | | | |
|-----------------------------|---------------|--------------|---|-----------------|-----|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-034-720 |
| vettersa | 08.07.2019 | 14.08.2019 | limachcl | 2017298 | В | 1 of 2 | |

4 Reason of change

The notches are implemented as a standard feature to be compatible with side latching cord retention systems such as P-Lock, SecureLock or TwyLock.

5 Release date

The change takes effect in production in ww36/2019 (Production date code 1936 or higher on label). The validity of the approval certificates is not affected by this change.

6 Impact of change and recommended action

| Form | Yes | Laterally positioned notches. Fully backwards compatible |
|---------------|-----|--|
| Fit | No | - |
| Function | Yes | Compatibility with side latching cord retention systems |
| Manufacturing | No | - |
| Label | No | - |
| Packaging | No | |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|---------------------|---------|
| 4797 - Data Sheet | |
| 4797-5 - Data Sheet | |

| Product Change Notification | | | PCN - 4797 Cord Retention Notches Added | | | | |
|-----------------------------|---------------|--------------|---|-----------------|-----|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-034-720 |
| vettersa | 08.07.2019 | 14.08.2019 | limachcl | 2017298 | В | 2 of 2 | |