

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU Type				
02	007	043	0000002295	4795.0000	Connectors	4795 Cord connector


*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

With the production of the new tool the opening for the cable guard has changed too.

3 Detailed description of change

The flange of the cable guard was round, what caused an insufficient hold of the cable guard.



NEW the flange of the cable guard is square, what improves the holding of the cable guard.



4 Reason of change

To pass the stronger test requirements according to IEC 60320-1 (Sect. 22: Cords and their connection), flange and slot on the cable guard had to be reinforced. As there have been made new tools for the moulding parts the holding of the cable guard got improved with a round opening.

5 Release date

Release of production

Ww 37/2012

6 Impact of change and recommended action

Form: Square flange on the cable guard
Fit: n/a
Function: Better holding of the cable guard
Production Site: n/a
Product Label: n/a

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
PCN	0118.2109	Cable guard new with square flange

4795					0118.2126	
creation date	created by	release date	released by	notification no.	revision	page
2012-09-13	haechlsa	2013-04-11	haechlsa	24635	a	1 of 1