

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.	
SBU / PG	PGU	Type					
02	007	038	0000002296	4796.0000	Connector	4796 Cord connector	
02	007	038	0000002365	4310.0008	Connector	0106 Cord connector	
02	007	038	0000002365	4310.0009	Connector	0106 Cord connector	

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

**2 Type of change**


A new tool has been made.  
Modification of the Approval marks.  
With the production of the new tool the opening for the cable guard has changed too.

**3 Detailed description of change**

Old Version (Approval marks)




The flange of the cable guard was round, what caused an insufficient hold of the cable guard.



New Version (Approval marks)



NEW the flange of the cable guard is square, what improves the holding of the cable guard.



**4 Reason of change**

With the production of the new tool the approval marks got updated according to UL/ CSA/ IEC/ CCC.

To pass the stronger test requirements according to IEC 60320-1 (Sect. 22: Cords and their connection), flange and slot on the cable guard had to be reinforced. As there have been made new tools for the moulding parts the holding of the cable guard got improved with a round opening.

4796					0118.2127	
creation date	created by	release date	released by	notification no.	revision	page
2012-09-13	haechlsa	2013-04-11	haechlsa	24635	a	1 of 2

**5 Release date**

Release of production

Ww 38/2012

**6 Impact of change and recommended action**

Form: Square flange on the cable guard / New approval marks  
 Fit: n/a  
 Function: Better holding of the cable guard  
 Production Site: n/a  
 Product Label: n/a

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks
PCN	0118.2109	cable guard new with square flange

<b>4796</b>					<b>0118.2127</b>	
creation date	created by	release date	released by	notification no.	revision	page
2012-09-13	haechlsa	2013-04-11	haechlsa	24635	a	2 of 2