



# Product Change Notification

Current Date: 21-Oct-2020

## TE Connectivity

**Product Change Notification:** P-20-019873

**PCN Date:** 20-OCT-20

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Manufacturing location change product change notification

### Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

### Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	31-DEC-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	31-DEC-2021

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">004289-000</a>	NO			7-1190032-9, TXR54AC00-1207AI			
<a href="#">004845-000</a>	NO		RAY004845-000	1190037-3, 209M410-19B			
<a href="#">026735-000</a>	NO			2-1190207-3, STXR40AB00-1412AI			
<a href="#">084983-000</a>	NO			7-1190627-1, TXR41AB00-2416AI			
<a href="#">092113-000</a>	NO			2-1190675-1, TX54SJ00-1206			
<a href="#">122913-000</a>	NO		RAY122913-000	1-1190894-7, TXR40AB90-1610BI			
<a href="#">169309-000</a>	NO		RAY169309-000	5-1191232-9, TXR40AB00-2416AI			
<a href="#">213685-000</a>	NO			1191544-5, STXR54AB00-1410AI			
<a href="#">263535-000</a>	NO		RAY263535-000	7-1191939-2, STXR40AB00-1008AI			
<a href="#">293973-000</a>	NO		RAY293973-000	7-1192227-3, TXR40AB00-1612AI			
<a href="#">300967-000</a>	NO			4-1192279-3, TXR41AB00-2012AI			
<a href="#">404609-000</a>	NO			9-1193053-0, TXR54AB90-1812AI			
<a href="#">411971-000</a>	NO		RAY411971-000	9-1193106-9, TXR40AB90-1007AI			
<a href="#">412750-000</a>	NO		RAY412750-000	5-1193112-4, TXR40AB00-2010AI			
<a href="#">487367-000</a>	NO			7-1193646-3, TXR40AC00-2008AI			
<a href="#">501405-000</a>	NO		RAY501405-000	5-1193748-3, TXR76AB00-1610AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">533821-000</a>	NO			7-1194190-3, <b>TXR21AB00-0804AI</b>			
<a href="#">548799-000</a>	NO			4-1194319-2, <b>TX54AB00-1408</b>			
<a href="#">562469-000</a>	NO		RAY562469-000	2-1194444-3, <b>TXR40AB00-2008AI</b>			
<a href="#">574151-000</a>	NO			4-1194557-3, <b>208M720-19B14</b>			
<a href="#">597099-000</a>	NO		RAY597099-000	1-1194722-4, <b>TXR54SJ00-1408BI</b>			
<a href="#">664529-000</a>	NO		RAY664529-000	5-1195236-1, <b>TXR40AB00-1206AI</b>			
<a href="#">672917-000</a>	NO			2-1195294-4, <b>201M110-62C</b>			
<a href="#">703855-000</a>	NO			8-1195521-8, <b>TXR41AB90-1206BI</b>			
<a href="#">739529-000</a>	NO			4-1195772-7, <b>TXR40BW00-1004AI</b>			
<a href="#">740625-000</a>	NO			8-1195780-0, <b>TXR40SJ00-1208AI</b>			
<a href="#">801953-000</a>	NO		RAY801953-000	6-1196200-5, <b>TXR21AB00-1408AI</b>			
<a href="#">809481-000</a>	NO			8-1196290-9, <b>201M110-01W</b>			
<a href="#">819955-000</a>	NO			6-1196389-2, <b>TXR40AB00-2205AI</b>			
<a href="#">893991-000</a>	NO			9-1196952-7, <b>STXR40SJ00-1412AI</b>			
<a href="#">908313-000</a>	NO			8-1197055-2, <b>204M110-19B04-40</b>			
<a href="#">919073-000</a>	NO		RAY919073-000	3-1197132-7, <b>TXR40AC00-1004AI</b>			
<a href="#">CF0572-000</a>	NO		RAYCF0572-000	1-1899174-3, <b>STXR40BW00-1008AI</b>			
<a href="#">CN7199-000</a>	NO			1899495-2, <b>TXS127AB00-0804BI</b>			
<a href="#">CX9353-000</a>	NO			<b>TX40AZ00-2016</b>			
<a href="#">E47391-000</a>	NO			9-1200500-0, <b>TXR40AU00-1006BI</b>			
<a href="#">E65325-000</a>	NO			8-1201360-3, <b>204M108-19B04-40</b>			
<a href="#">EG1540-000</a>	NO			<b>BND40AB00-0804W</b>			
<a href="#">EG6594-000</a>	NO			<b>BND40AC00-0804V</b>			
<a href="#">EG9666-000</a>	NO			<b>BND40SC00-1408V</b>			
<a href="#">EJ0956-000</a>	NO			<b>STXR40BW00-0807AI</b>			
<a href="#">F71931-000</a>	NO		RAYF71931-000	8-1200929-5, <b>208M712-19B09</b>			



# Product Change Notification

Current Date: 21-Oct-2020

## TE Connectivity

**Product Change Notification:** P-20-019873

**PCN Date:** 20-OCT-20

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Manufacturing location change product change notification

### Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

### Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	31-DEC-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	31-DEC-2021

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">004289-000</a>	NO			7-1190032-9, TXR54AC00-1207AI			
<a href="#">004845-000</a>	NO		RAY004845-000	1190037-3, 209M410-19B			
<a href="#">026735-000</a>	NO			2-1190207-3, STXR40AB00-1412AI			
<a href="#">084983-000</a>	NO			7-1190627-1, TXR41AB00-2416AI			
<a href="#">092113-000</a>	NO			2-1190675-1, TX54SJ00-1206			
<a href="#">122913-000</a>	NO		RAY122913-000	1-1190894-7, TXR40AB90-1610BI			
<a href="#">169309-000</a>	NO		RAY169309-000	5-1191232-9, TXR40AB00-2416AI			
<a href="#">213685-000</a>	NO			1191544-5, STXR54AB00-1410AI			
<a href="#">263535-000</a>	NO		RAY263535-000	7-1191939-2, STXR40AB00-1008AI			
<a href="#">293973-000</a>	NO		RAY293973-000	7-1192227-3, TXR40AB00-1612AI			
<a href="#">300967-000</a>	NO			4-1192279-3, TXR41AB00-2012AI			
<a href="#">404609-000</a>	NO			9-1193053-0, TXR54AB90-1812AI			
<a href="#">411971-000</a>	NO		RAY411971-000	9-1193106-9, TXR40AB90-1007AI			
<a href="#">412750-000</a>	NO		RAY412750-000	5-1193112-4, TXR40AB00-2010AI			
<a href="#">487367-000</a>	NO			7-1193646-3, TXR40AC00-2008AI			
<a href="#">501405-000</a>	NO		RAY501405-000	5-1193748-3, TXR76AB00-1610AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">533821-000</a>	NO			7-1194190-3, <b>TXR21AB00-0804AI</b>			
<a href="#">548799-000</a>	NO			4-1194319-2, TX54AB00- <b>1408</b>			
<a href="#">562469-000</a>	NO		RAY562469-000	2-1194444-3, <b>TXR40AB00-2008AI</b>			
<a href="#">574151-000</a>	NO			4-1194557-3, 208M720- <b>19B14</b>			
<a href="#">597099-000</a>	NO		RAY597099-000	1-1194722-4, TXR54SJ00- <b>1408BI</b>			
<a href="#">664529-000</a>	NO		RAY664529-000	5-1195236-1, <b>TXR40AB00-1206AI</b>			
<a href="#">672917-000</a>	NO			2-1195294-4, 201M110- <b>62C</b>			
<a href="#">703855-000</a>	NO			8-1195521-8, <b>TXR41AB90-1206BI</b>			
<a href="#">739529-000</a>	NO			4-1195772-7, <b>TXR40BW00-1004AI</b>			
<a href="#">740625-000</a>	NO			8-1195780-0, TXR40SJ00- <b>1208AI</b>			
<a href="#">801953-000</a>	NO		RAY801953-000	6-1196200-5, <b>TXR21AB00-1408AI</b>			
<a href="#">809481-000</a>	NO			8-1196290-9, 201M110- <b>01W</b>			
<a href="#">819955-000</a>	NO			6-1196389-2, <b>TXR40AB00-2205AI</b>			
<a href="#">893991-000</a>	NO			9-1196952-7, <b>STXR40SJ00-1412AI</b>			
<a href="#">908313-000</a>	NO			8-1197055-2, 204M110- <b>19B04-40</b>			
<a href="#">919073-000</a>	NO		RAY919073-000	3-1197132-7, <b>TXR40AC00-1004AI</b>			
<a href="#">CF0572-000</a>	NO		RAYCF0572-000	1-1899174-3, <b>STXR40BW00-1008AI</b>			
<a href="#">CN7199-000</a>	NO			1899495-2, TXS127AB00- <b>0804BI</b>			
<a href="#">CX9353-000</a>	NO			<b>TX40AZ00-2016</b>			
<a href="#">E47391-000</a>	NO			9-1200500-0, <b>TXR40AU00-1006BI</b>			
<a href="#">E65325-000</a>	NO			8-1201360-3, 204M108- <b>19B04-40</b>			
<a href="#">EG1540-000</a>	NO			<b>BND40AB00-0804W</b>			
<a href="#">EG6594-000</a>	NO			<b>BND40AC00-0804V</b>			
<a href="#">EG9666-000</a>	NO			<b>BND40SC00-1408V</b>			
<a href="#">EJ0956-000</a>	NO			<b>STXR40BW00-0807AI</b>			
<a href="#">F71931-000</a>	NO		RAYF71931-000	8-1200929-5, 208M712- <b>19B09</b>			