



04-Mar-2015

PCN #:E-15-003129

Subject:CPC connectors with 4-40 threaded bushings

Description of Change: Add a note to the production drawing stating the 4-40 bushings are to be assembled from the mating side of the housing flange during the assembly operation in the TE manufacturing plant.

Reason: Product Improvement. The note is required to ensure the bushings are assembled in a consistent manner. Although all of the part numbers listed on this notice will receive a revision change, the only parts which contain bushings and may be impacted by the note change are the following:
206934-9, 1-206934-3, 1-206934-4, 1-206934-7, 2-206934-7, 2-206934-8

Impact of Change:form - fit - function

Key Dates:

Contact By Date:30-May-2015

Implementation Date:30-May-2015

Product Affected

1-206934-3

1-206934-1

2-206934-7

1-206934-4

2-206934-2

1-206934-8

2-206934-1

1-206934-7

1-206934-9

206934-5

206934-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.