



15-Jan-2018

PCN #:E-17-018691

Subject:T9A series relay

Description of Change: Bobbin structure optimization with adding slots to make bobbin wall thickness symmetrical and align boss location to fix frame.

Reason: Product Improvement. Optimize bobbin structure to make wall thickness symmetrical and fix frame better, no any relay function affect.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:20-Apr-2018

Implementation Date:20-Apr-2018

Product Affected

2-1423091-3

(Alias Part Numbers:

"T9AV1D22-48")

1-1419104-1

(Alias Part Numbers:

"T9AP1D22-18-01")

4-1419148-8

(Alias Part Numbers:

"T9AV1D22-18")

2071229-2

(Alias Part Numbers:

"T9AV2XD16-12")

1423802-1

(Alias Part Numbers:

"T9AV5D22-22-02")

Product Affected

4-1393210-5

(Alias Part Numbers:
"T9AV1D12-22U")

4-1393210-4

(Alias Part Numbers:
"T9AV1D12-22")

4-1419104-2

(Alias Part Numbers:
"T9A-V1L22-24"
"T9AV1L22-24")

1-1419142-9

(Alias Part Numbers:
"T9AV2D12-22")

1423091-6

(Alias Part Numbers:
"T9AV5L12-12")

4-1393210-6

(Alias Part Numbers:
"T9AV5D12-22")

4-1393210-3

(Alias Part Numbers:
"T9AV1D12-12")

1423029-1

(Alias Part Numbers:
"T9AV5D22-22")

1-1423091-8

(Alias Part Numbers:
"T9AV1L12-12")

1423091-9

(Alias Part Numbers:
"T9AV1D22-12")

5-1419148-2

(Alias Part Numbers:
"T9AV5D22-18")

2-2071229-5

(Alias Part Numbers:
"T9AS1D14-9")

4-1419148-7

(Alias Part Numbers:
"T9AV1D12-9")

Product Affected

6-1423091-1

(Alias Part Numbers:
"T9AV2D12-22-01")

2071229-6

(Alias Part Numbers:
"T9AV5L22-12")

1423801-1

(Alias Part Numbers:
"T9AV5D22-22-01")

2-1423091-7

(Alias Part Numbers:
"T9AV1D12-48")

4-1393210-7

(Alias Part Numbers:
"T9AV5D12-22U")

1-1423091-5

(Alias Part Numbers:
"T9AV5D22-24-01")

4-1423091-1

(Alias Part Numbers:
"T9AV1D12-22-01")

8-1423091-7

(Alias Part Numbers:
"T9AV1L22-6")

4-1419148-9

(Alias Part Numbers:
"T9AV1D22-22")

5-1393210-2

(Alias Part Numbers:
"T9AV1D12-18")

2-1419142-0

(Alias Part Numbers:
"T9AV2D12-22U")

1423029-7

(Alias Part Numbers:
"T9AV1D14-12")

5-1419148-0

(Alias Part Numbers:
"T9AV1D22-24")

2-2071229-7

Product Affected

(Alias Part Numbers:
"T9AS1L14-24")

6-1423017-6

(Alias Part Numbers:
"29B591A")

2-1423091-1

(Alias Part Numbers:
"T9AV1L22-12")

1423800-1

(Alias Part Numbers:
"T9AV1D22-22-02")

1-2071229-0

(Alias Part Numbers:
"T9AV1D27-24")

1423891-1

(Alias Part Numbers:
"T9AV1H22-24")

1419137-1

(Alias Part Numbers:
"T9AV2D22-24")

1419137-2

(Alias Part Numbers:
"T9AV5D22-24")

4-1393210-8

(Alias Part Numbers:
"T9AV5D12-24")

1-2071229-9

(Alias Part Numbers:
"T9AS1D14-12-01")

4-1419104-3

(Alias Part Numbers:
"T9AV5L22-24")

1423803-1

(Alias Part Numbers:
"T9AV5D22-22-03")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.