



25-Jun-2021

PCN #:E-21-005720

**Subject:**AMPMODU MTE HEADER ASSEMBLIES

**Description of Change:** ADDENDUM TO PCN E-20-000624 (ATTACHED). ONE OF THE CHANGES NOTED IN PCN E-20-000624 IS NOT BEING IMPLEMENTED DUE TO FINANCIAL IMPLICATIONS. THE TOOLING CHANGE SHOWN IN THE ATTACHED MTE SHROUDED HEADER TOOLING CHANGE FILE IS BEING MADE TO BE AT THE MOLDER'S DISCRETION. SOME PARTS MAY HAVE THIS RECESSED AREA, SOME MIGHT NOT. THERE IS NO PERFORMANCE DIFFERENCE BETWEEN THE PARTS WITH THE RECESSION AND THE PARTS WITHOUT THE RECESSION.

**Reason:** Product Improvement.

**Key Dates:**

**Contact By Date:**30-Jun-2021

**Implementation Date:**30-Jun-2021

<b>Product Affected</b>	<b>Alias Part Number</b>
103669-2	
103669-3	
103669-5	
104361-5	
104361-9	
1-103670-4	
1-103670-9	
2-103670-3	
103908-1	"406746073"
103634-4	
103635-7	

<b>Product Affected</b>	<b>Alias Part Number</b>
1-103635-9	
103906-2	
103906-4	
1-103906-0	
103673-3	
1-103735-0	
1-103735-5	
1-103638-1	"2-42937-3651"
103639-9	
5-103673-5	
6-103639-9	
6-103639-5	
6-103669-0	
5-103639-8	
6-103635-0	
5-103672-4	
5-103635-9	
6-104361-2	
6-103735-0	
5-103635-3	
103672-8	
2-103669-5	
5-103908-1	
2-103673-1	
6-103639-0	
6-103634-1	
6-103635-9	
6-103635-4	
6-103904-1	
6-103735-5	
1-103639-7	
5-103639-2	
1-103735-7	
5-103635-1	
5-103634-2	
103904-1	"2-42938-5376"
103904-2	"2-42938-5377"
103670-8	
103904-4	
103904-5	

**Product Affected****Alias Part Number**

1-103908-0  
1-103908-1  
1-103908-5  
1-103635-3  
103906-3  
103906-8  
1-103906-1  
1-103672-1  
103735-9  
1-103735-1  
1-103735-3  
1-103638-5  
103639-4  
103735-3  
5-103635-8  
5-103669-6  
5-103635-7  
1-103904-0  
6-103635-5  
5-103673-7  
5-103672-5  
5-103669-5  
5-103634-3  
6-103639-3  
5-103904-5  
2-103673-3  
5-103904-6  
6-103735-3  
6-103673-6  
103669-9  
1-103673-3  
1-103673-9  
103904-3  
1-103904-1  
104361-7  
1-103908-7  
1-103635-2  
103906-6  
103673-2  
103735-4

"CW5998-000", "PER-5-103673-7"

<b>Product Affected</b>	<b>Alias Part Number</b>
103735-6	
103735-8	
103639-1	
103639-5	
103639-6	
103735-2	
5-103635-2	
5-103673-6	
5-103634-1	
6-103735-6	
5-103672-7	
7-103635-3	
5-103634-6	
5-103735-5	
2-103908-3	
6-103673-1	
5-103904-2	
5-103904-9	
5-103735-1	
6-103673-3	
5-104361-6	
7-103639-1	
5-103639-4	
6-103673-0	
103672-1	
5-103908-8	
103669-1	
103669-4	
1-103673-1	
1-103670-0	
1-103904-3	
104361-3	
103908-5	
103908-9	
103634-2	
103634-3	
1-103635-1	
103906-5	
103672-9	
1-103638-3	

<b>Product Affected</b>	<b>Alias Part Number</b>
103639-7	
1-103639-1	
6-103669-3	
6-103908-5	
6-103639-4	
5-103635-4	
5-103908-4	
6-103635-3	
5-103639-7	
6-103908-1	
6-104361-9	
5-103669-1	
5-103672-3	
2-103672-9	
5-103904-1	
5-103639-6	
6-103672-5	
5-103904-8	
103672-4	
5-103673-3	
5-103904-3	
6-103673-5	
103669-7	
1-103673-6	
1-103670-1	
104361-2	"406790659"
1-103670-5	
103908-2	
103908-4	
103908-6	
103634-1	
103634-8	
103906-7	
103673-5	
103638-4	
103638-7	
103638-8	"407161207"
7-103735-4	
5-103634-9	
5-104361-8	

**Product Affected****Alias Part Number**

5-103673-4  
7-103673-3  
6-103904-4  
6-103673-4  
5-103669-7  
5-103672-2  
2-103634-7  
5-103673-8  
5-103672-1  
6-103735-9  
5-103634-8  
6-103908-9  
5-103735-4  
5-103735-8  
6-103635-1  
6-103634-2  
5-103904-7  
5-103672-9  
6-104361-1  
5-103639-5  
6-103634-4  
5-104361-3  
5-103672-6  
2-103639-5  
103670-1  
103670-2  
103670-3  
103670-4  
103670-5  
103670-6  
103670-9  
104361-1  
104361-8  
103634-5  
1-103634-3  
1-103634-5  
103635-1  
103635-3  
2-103635-4  
103906-1

"4-40001-6591"

"AMP-0-0103635-3", "E18345-000"

"405986266", "2-42938-4342"

<b>Product Affected</b>	<b>Alias Part Number</b>
103735-7	
103638-6	
103639-2	
1-103639-2	
1-103639-5	
5-103735-2	
5-103735-9	
5-103908-5	
7-103635-4	
103672-3	
1-103673-5	
5-103673-1	
5-103908-7	
5-103908-3	
6-103904-3	
6-103673-9	
6-103634-5	
6-103635-7	
5-103673-9	
5-103669-4	
5-104361-7	
6-103639-1	
103670-7	
103904-7	
104361-4	
103635-2	
103635-4	
103635-5	
1-103906-5	
103735-5	
103638-2	"407085000"
1-103638-0	
6-103634-0	
3-103639-2	
5-103673-2	
6-103908-3	
6-103908-4	
6-103635-6	
6-103669-2	
6-103634-3	

<b>Product Affected</b>	<b>Alias Part Number</b>
6-103639-2	
5-103669-3	
5-103635-5	
6-103908-0	
5-103735-3	
5-103908-2	
6-103735-4	
5-103669-8	
6-103669-5	
5-103634-5	
5-103634-4	
5-103904-4	
5-103908-9	
103672-2	
5-103908-6	
5-103639-1	
2-103669-6	
5-103669-2	
2-103634-9	
103673-7	
103673-8	
103673-9	
103904-9	
1-103670-3	
1-103670-7	
103908-3	"406803577"
103908-7	
1-103908-3	
103635-8	
103635-9	
1-103635-5	
1-103635-7	
1-103906-9	
103672-7	
103673-1	
103673-4	
103673-6	
2-103672-6	
103638-1	
103638-3	



<b>Product Affected</b>	<b>Alias Part Number</b>
103638-5	"407161199"
103638-9	
103639-3	
1-103639-9	
103735-1	
5-104361-5	
103906-9	
5-103639-3	
5-104361-4	
6-103672-9	
5-103639-9	
5-103634-7	
2-103634-5	
6-103639-6	
5-103735-7	
6-103635-2	
1-103735-2	
2-103639-8	
5-104361-9	
5-103635-6	
6-103669-1	
5-103735-6	
6-103672-1	
6-103735-1	
5-104361-2	
5-103669-9	
5-104361-1	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.