


Visual adjustment: Temporary different color for signal connectors

Dear Madam or Sir.

this temporary product change is done to maintain supply. The items listed below will be supplied in a different color variant. Please pass on this product information to your staff and, if reasonable, to your customers.

1. Visual change



2. Reason for change

Due to global supply shortages for plastics, we have to temporarily switch to a different color for black signal connectors to avoid possible longer-term supply interruptions.

Ability

All changes are made solely for reasons of security of supply.

4. Affected articles

3 product families are basically affected: BL 3.50 + BLZP 5.0x + BLF 5.0x. The previous article numbers and product descriptions will remain for this temporary period and will not be adjusted. There is no mixing of different color variants within one packaging unit. Below are the articles that are now actively affected

ArtNo.:	Decription
1955560000	BLZP 5.00HC/03/180 SN BK BX
1615670000	BL 3.50/02/180 SN BK BX
1615690000	BL 3.50/04/180 SN BK BX
1610180000	BL 3.50/06/180 SN BK BX
1077820000	BL 3.50/06/180 SN BK BX SO

We apologise for any inconvenience that may be caused by the visual change. We will do everything possible to return this temporary color adjustment to the original color of black as soon as possible. **If you disagree to this visual change**,

please feedback immediately and in writing form (<u>WWW.Weidmueller.com/contact</u>). However, this will inevitably lead to a significant extension of the original delivery time.

For further questions, please contact your assigned sales office directly.

Yours sincerely

Product Management – Device Connectivity Weidmüller Interface GmbH & Co. KG Klingenbergstraße 26, 32758 Detmold