04-Mar-2021
PCN #:E-21-002561

Subject:SOCKET ASSY, 2-35mm, CRIMP

Description of Change: To increase the retention of the retaining spring on the socket, the inner diameter of the retaining spring and the outer diameter of the socket were both reduced for -4 and -5 to create a tighter fit between the spring and the socket and the height of the retention tines on the spring were increased accordingly to maintain the proper location of the tip of the retention tines with respect to the ledge in the housing that these tines make contact with. For -1 and -2, only the width of socket shoulder shown as dimension K in customer drawing is changed.

Reason: Product Improvement. 1. Product improvement to increase the retention of the retaining spring on the socket to eliminate the possibility of the retaining spring from becoming dislodged from the socket. 2. Product improvement to ensure that all the locking tines on the retaining spring deploy properly in the housing after the socket is inserted into the housing.

Key Dates:
Contact By Date:11-Mar-2021
Implementation Date:11-Mar-2021

Product Affected	Alias Part Number
193673-2	
193673-1	
193673-4	
193673-5	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.

Copyright TE Connectivity Corporation