Product/Process Change Notifications

Amphenol ICC

PCN - 20 007 R2

Amphenol Information Communication and Commercial Products Group

www.amphenol-icc.com

Release Date: April 24 2020

Product Name:	Millipacs			
	Millipacs All Versions			
Product Manager:	Jibu Babu			
Subject:	Notification of Change with Immediate Effectivity			
Distribution:	All Customers			
Type of Change:	Materials Change			
Change Description:	As notified earlier vide PCN 20007 dtd February 25th, 2020 and PCN 20007 R1 dtd March 3rd , 2020 we are adding GXT + as approved plating material for 2mm Millipacs meeting the product performance specifications. PCN 20007 R2 Revision is to notify that we will assign **"new Part numbers for GXT + plating products"**.			
Reason for Change:	**Reason for GXT+ Plating introduction:** Palladium prices have increased significantly over the last several years causing drastic increase in cost of production. We are reviewing the current product pricing. To reduce the impact of palladium metal price spiral on the cost of production, we are implementing GXT+ plating in our process. Your approval for supplies with GXT+ plating will help to limit the product price increase. **Reason for new part numbers for GXT+ plating:** New Part numbers are assigned for GXT+ plating to ensure traceability in supply chain. See PCN20007 R2 Affected Parts.xls file , "Alternative Parts" column for new Part numbers.			
Affected Parts:	See attached PCN20007 R2 Affected Parts.xls file			
Effective Date of Change:	May 10, 2020	*Note: PCN Revision R2 is to update previous PCN20007 R1 March 3, 2020 for following changes.* *1. PCN20007 R2 Affected Parts.xls - removed 88 part numbers from PCN20007 R1 Affected Parts.xls file.* *2. PCN20007 R2 Affected Parts.xls - added Alternate Part numbers for the new GXT+ plating specification.* *3. PCN Effective date revised to May 10, 2020.*		
Last Time Buy Date:	NA			
Last Disty Return Date:	NA			
Last Time Shipment Date	NA			
Datasheet Attached?	Select			
Qual/Test Data Attached?	NA			
Samples Availability Date:	April	20	2020	
Available Alternatives?	Select			
Questions?	*Contact your local AICC Representative, or Product Manager*			
	Jibu Babu			
	914843391946 / Jibu.Babu@fci.com			

Note:
Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN.
Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date	Last Disty Return date	Last Shipment date	Alternative Parts	Product Family	Primary MU	Product Manager	Status
PCN20007R2	HM2C01D0C010N9LF	MATERIALS CHANGE	May 10, 2020			HM2C01D0C010N2LF	560-5HUF-MILLIPACS LF CABLE CONNECTOR	4543-45430	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2C01D2C010N9LF	MATERIALS CHANGE	May 10, 2020			HM2C01D2C010N2LF	560-5HUF-MILLIPACS LF CABLE CONNECTOR	4543-45430	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2C06D0C010N9LF	MATERIALS CHANGE	May 10, 2020			HM2C06D0C010N2LF	560-5HUF-MILLIPACS LF CABLE CONNECTOR	4543-45430	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2C06D2C010N9LF	MATERIALS CHANGE	May 10, 2020			HM2C06D2C010N2LF	560-5HUF-MILLIPACS LF CABLE CONNECTOR	4543-45430	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10121566-103LF	MATERIALS CHANGE	May 10, 2020			20121566-203LF	560-56YF-MILLIPACS 10G VERT. HEADER	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10123492-101LF	MATERIALS CHANGE	May 10, 2020			20123492-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10127112-101LF	MATERIALS CHANGE	May 10, 2020			20127112-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10127112-102LF	MATERIALS CHANGE	May 10, 2020			20127112-202LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10127156-101LF	MATERIALS CHANGE	May 10, 2020			20127156-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10127169-101LF	MATERIALS CHANGE	May 10, 2020			20127169-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10129748-101LF	MATERIALS CHANGE	May 10, 2020			20129748-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10132170-101LF	MATERIALS CHANGE	May 10, 2020			20132170-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10132170-103LF	MATERIALS CHANGE	May 10, 2020			20132170-203LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10137566-101LF	MATERIALS CHANGE	May 10, 2020			20137566-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10140927-101LF	MATERIALS CHANGE	May 10, 2020			20140927-201LF	560-5KBF-MILLIPACS 25G VERTICAL HEADER	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10140928-101LF	MATERIALS CHANGE	May 10, 2020			20140928-201LF	560-5KAF-MILLIPACS 25G RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10142582-101LF	MATERIALS CHANGE	May 10, 2020			20142582-201LF	560-5KBF-MILLIPACS 25G VERTICAL HEADER	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10142583-101LF	MATERIALS CHANGE	May 10, 2020			20142583-201LF	560-5KAF-MILLIPACS 25G RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10143147-101LF	MATERIALS CHANGE	May 10, 2020			20143147-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10147936-101LF	MATERIALS CHANGE	May 10, 2020			20147936-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10148426-101LF	MATERIALS CHANGE	May 10, 2020			20148426-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10148426-102LF	MATERIALS CHANGE	May 10, 2020			20148426-202LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10148532-102LF	MATERIALS CHANGE	May 10, 2020			20148532-202LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10152238-101LF	MATERIALS CHANGE	May 10, 2020			20152238-201LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	10152238-102LF	MATERIALS CHANGE	May 10, 2020			20152238-202LF	560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2A31PG5000N9LF	MATERIALS CHANGE	May 10, 2020			HM2A31PG5000N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2E31PH6090N9LF	MATERIALS CHANGE	May 10, 2020			HM2E31PH6090N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J02PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J02PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J03PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J03PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J07PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J07PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J07PE5128N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE5128N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J07PE51A8N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE51A8N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J07PE51K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE51K0N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J07PEE128N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PEE128N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J08PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J08PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J08PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J08PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J08PE51H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2J08PE51H0N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE5130N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE5130N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE5160N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE5160N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE5168N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE5168N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE51C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE51C0N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE51N8N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE51N8N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE51P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE51P0N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE51P8N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE51P8N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PE51R8N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PE51R8N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PEA158N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PEA158N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PEA210N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PEA210N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J09PEA310N9LF	MATERIALS CHANGE	May 10, 2020			HM2J09PEA310N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J65PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J65PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J65PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J65PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J66PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J66PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J66PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J66PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J70PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J70PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J70PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J70PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J70PEE128N9LF	MATERIALS CHANGE	May 10, 2020			HM2J70PEE128N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J71PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J71PE5110N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J71PE5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2J71PE5118N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J71PEA158N9LF	MATERIALS CHANGE	May 10, 2020			HM2J71PEA158N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2J71PEE128N9LF	MATERIALS CHANGE	May 10, 2020			HM2J71PEE128N2LF	560-5HTF-MILLIPACS RA HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PCH290N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCH290N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PCJ3P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCJ3P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PD5115N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PD51M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD51M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PD5310N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD5310N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDA3K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDA3K1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE129N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE1F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE1F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE1R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE320N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE320N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE391N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE391N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE3F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE3F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDE3U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE3U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDF1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF1G1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDF1G5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF1G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDF2E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF2E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDF2J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF2J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDF310N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF310N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDG190N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG190N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDG3G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG3G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDG3R9N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG3R9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDG3T9N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG3T9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDH2F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH2F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDH311N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH311N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDH331N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH331N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDH3R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH3R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDJ1N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ1N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDJ1N5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ1N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDJ2H1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ2H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDJ341N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ341N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDJ3M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ3M1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDJ3N5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ3N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK1L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK1L0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK261N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK261N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK265N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK265N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK2R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK2R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK2W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK2W0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK3J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK3J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK3K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK3K0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK3N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK3N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDK3R5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK3R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDL235N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDL235N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDL3E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDL3E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDL3R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDL3R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDL3X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDL3X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM295N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM295N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM2C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM2C5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM2E5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM2E5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM2F5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM2F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM311N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM311N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM321N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM321N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDM350N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM350N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN131N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN131N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN1A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN1C1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1C1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN1E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1G1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN1W1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1W1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN271N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN271N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN2C4N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN2C4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN3E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN3H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3H0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN3J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN3U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3U1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN3W5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3W5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDN3Y5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3Y5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP171N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP171N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP1C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP1C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP1W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP1W0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP221N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP221N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP231N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP231N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP235N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP235N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP251N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP251N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP261N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP261N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP2C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP2C5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP2P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP2P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP2T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP2T0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP2U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP2U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP345N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP345N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP3A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP3A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP3A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP3A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP3G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP3G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDP3H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP3H0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR2L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR2L0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR390N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR390N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3C1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3C1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3K1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3L5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDS290N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDS290N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDS2A5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDS2A5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDS370N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDS370N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDS380N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDS380N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDS3E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDS3E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT1E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT1E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT1F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT1F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT1X1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT1X1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT211N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT211N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT221N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT221N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT231N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT231N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT2C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT2E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDT2X1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2X1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDU141N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU141N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE

PCN20007R2	HM2P07PDU1A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU1A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDU1C1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU1C1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDU1E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU1E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDW145N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDW145N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDW2M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDW2M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDW2N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDW2N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PZ5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PZ5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PZF1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PZF1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PZG1A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PZG1A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PC5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PC5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PCH2A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCH2A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PCK220N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCK220N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PD5115N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PD5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PD5151N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PD5151N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDE129N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDE1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDE2A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE2A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDE2T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE2T0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDE310N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE310N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF1G1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDF1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDF1N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF1N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDG3H1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDG3H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDJ381N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDJ381N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDK1H5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDK1H5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDM2G5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDM2G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDM2J5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDM2J5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDN151N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN151N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDN3K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN3K0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDP1E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDP1E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDP2N5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDP2N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDP2W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDP2W0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDS1X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDS1X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDS2U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDS2U1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDU270N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDU270N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDW2E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDW2E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PDW2F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDW2F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PC5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PC5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PC5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PC5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PCK291N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PCK291N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PD5151N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PD5151N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PD5310N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PD5310N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDE121DN9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDE129N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDE3G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE3G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDF1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDF1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDF1H1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDF1H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDF1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDF1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDF3J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDF3J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDG3N9N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDG3N2N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDG3P9N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDG3P9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDH2G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDH2G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDH340N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDH340N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDH3T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDH3T0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDH3U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDH3U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDJ1N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDJ1N0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDJ1N5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDJ1N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDJ320N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDJ320N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDK330N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDK330N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDK3F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDK3F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDK3G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDK3G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDL3C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDL3C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDL3M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDL3M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDM285N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDM285N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDM390N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDM390N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDM3U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDM3U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDN3T1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDN3T1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDP291N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDP291N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDP385N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDP385N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDP3M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDP3M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDP3Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDP3Y0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDR2J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR2J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDR2K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR2K0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDR2X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR2X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDR360N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR360N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDS161N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDS161N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDS1J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDS1J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDS351N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDS351N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDU1M5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDU1M5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDU221N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDU221N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PDU2C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDU2C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PZ5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PZ5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PZ5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PZ5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09SD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09SD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09SZ5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09SZ5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09SZ5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09SZ5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PDG3L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDG3L0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PDJ2P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDJ2P0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PDM3R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDM3R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PDN260N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDN260N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PDN3N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDN3N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PDN3R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDN3R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11SZ5001N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11SZ5001N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11SZ5011N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11SZ5011N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P26PC5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P26PC5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P26PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P26PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P27PDG320N9LF	MATERIALS CHANGE	May 10, 2020			HM2P27PDG320N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P27PDG330N9LF	MATERIALS CHANGE	May 10, 2020			HM2P27PDG330N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P29PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P29PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PDE3L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDE3L0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PDW145N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDW145N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40SZ5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40SZ5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40SZE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40SZE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P47PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P47PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P47PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P47PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P47PDE121DN9LF	MATERIALS CHANGE	May 10, 2020			HM2P47PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P60PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P60PDA1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PDA1L1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P60PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P60PDE1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PDE1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P60PDT2R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PDT2R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P64PDP3C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P64PDP3C5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PA5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PA5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PCT260N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PCT260N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDA3M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDA3M1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDE1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDE1R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDE1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDE1R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDF1G5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDF1G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDF2T5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDF2T5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDH2L5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDH2L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDJ360N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDJ360N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDJ3X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDJ3X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDK311N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDK311N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDM371N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDM371N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDM3H1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDM3H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDM3N5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDM3N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDP335N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDP335N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDR2T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDR2T0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDS220N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDS220N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDT2L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDT2L1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PDT2U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDT2U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PZ5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PZ5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PZ5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PZ5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65SD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65SD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PD5115N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PD5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDE125N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDE125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDF2X5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDF2X5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDG3C1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDG3C1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDJ3F5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDJ3F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDP375N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDP375N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDR3T5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDR3T5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDS3K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDS3K1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PDT2P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDT2P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PDA3C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDA3C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PDE125N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDE125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PDE331N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDE331N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PDK3X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDK3X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PDS241N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDS241N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PZ5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PZ5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P69PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P69PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDE124N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDE1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDE1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDE1U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDE1U1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDF1G1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDH2M5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDH2M5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDJ381N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDJ381N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDN281N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDN281N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDN3F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDN3F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDR2N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDR2N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PDU175N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDU175N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PZE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PZE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE

PCN20007R2	HM2P71PDF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDF1G1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PDK321N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDK321N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PDP3J5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDP3J5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PDS250N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDS250N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PDS3A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDS3A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P73PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P73PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P77PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P77PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P78PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P78PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P78PDS341N9LF	MATERIALS CHANGE	May 10, 2020			HM2P78PDS341N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P79PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P79PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PD5115N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PD5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PDL341N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDL341N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PDL3F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDL3F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PDL3F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDL3F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PDS2T1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDS2T1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P82PD8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P82PD8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P82PD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P82PD8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P83PZF1F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P83PZF1F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P84PZE125N9LF	MATERIALS CHANGE	May 10, 2020			HM2P84PZE125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P85PD8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P85PD8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PD8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PD81H5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD81H5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PD81K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD81K1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDA1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDA1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDC160N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC160N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDF1K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDF1K1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDF1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDF1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDH1E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDH1E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDH3Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDH3Y0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDJ1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDJ1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDJ1W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDJ1W0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDK1K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDK1K0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PDK1N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDK1N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PZC135N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PZC135N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PC8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PC8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PD8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PD8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PD81H5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PD81H5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PD81K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PD81K1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PD81N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PD81N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDA111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDA111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDC161N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDC161N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDF141N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDF141N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDH3X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDH3X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PDJ131N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDJ131N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDC145N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDC145N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDH1J1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDH1J1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDH1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDH1R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDJ121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDJ121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDK150N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDK150N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDK180N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDK180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDK1L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDK1L0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PDK1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDK1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PZJ1P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PZJ1P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PCH170N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PCH170N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG170N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG170N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG180N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG190N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG190N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1H0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1K0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1L0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1N0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDG1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDH120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDH1M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH1M1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDH1P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH1P0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDH3U5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH3U5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDH3W5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH3W5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDK131N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDK131N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDK1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDK1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PDK1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDK1R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PDP255N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDP255N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PDP265N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDP265N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PDP2F5N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDP2F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PDP3F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDP3F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PDT231N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDT231N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN2PDP285N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN2PDP285N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN2PDP2K5N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN2PDP2K5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN3PDE3J5N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN3PDE3J5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA5102N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5102N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA5104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5104N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA510JN9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA510JN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PACA39N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PACA39N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5104N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5107N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5107N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA510JN9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA510JN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PACA10N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PACA10N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PE5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PE5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PE5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R03PA5104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PA5104N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R03PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R03PA510JN9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PA510JN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R05PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R05PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R05PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R05PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R05PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R05PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA510YN9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PA510YN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5300N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5300N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PACA39N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PACA39N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PACAK0N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PACAK0N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PE5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PE5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PE5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R20PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R20PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R20PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R20PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R20PA5104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R20PA5104N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R20PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R20PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R21PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R21PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R21PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R21PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R21PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R21PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R27PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R27PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R29PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R29PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PA510YN9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA510YN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PA51A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA51A0N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PA5300N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA5300N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PACA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PACA20N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PACAJ0N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PACAJ0N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PAFA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PAFA20N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PAGA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PAGA20N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PE5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PE5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PE5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R50PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R50PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R50PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R50PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R62PA510YN9LF	MATERIALS CHANGE	May 10, 2020			HM2R62PA510YN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R64PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R64PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R65PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R65PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R65PA510YN9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PA510YN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R65PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PE5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R66PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R66PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R66PA510YN9LF	MATERIALS CHANGE	May 10, 2020			HM2R66PA510YN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R69PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R69PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R69PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R69PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R70PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R70PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R70PE5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R70PE5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R71PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R71PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R71PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R71PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R71PE5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R71PE5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R77PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R77PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R77PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R77PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R78PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R78PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R78PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R78PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R79PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R79PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R79PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R79PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R81PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R81PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R82PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R82PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R82PA8104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R82PA8104N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R83PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R83PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R83PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R83PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R83PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R83PA8108N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R87PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R87PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R87PA810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PA810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R87PE810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PE810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PA8104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8104N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PA810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PA810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PAEA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PAEA20N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PAGA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PAGA20N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PE8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PE8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PE810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PE810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE

PCN20007R2	HM2R89PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R89PA8104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PA8104N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R89PA810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PA810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R89PE810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PE810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R90PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R90PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R95PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PA8101N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R95PE8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PE8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R95PE810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PE810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S01PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S01PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PD51M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PD51M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PD51M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PD51M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PD51N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PD51N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PD51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PD51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PE51N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PE51N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S02PE51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PE51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S03PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S03PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S05PE51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S05PE51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S05PE51N2N9LF	MATERIALS CHANGE	May 10, 2020			HM2S05PE51N2N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S05PE51N3N9LF	MATERIALS CHANGE	May 10, 2020			HM2S05PE51N3N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S05PE51N7N9LF	MATERIALS CHANGE	May 10, 2020			HM2S05PE51N7N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PD51M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PD51M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PD51M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PD51M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PD51N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PD51N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PD51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PD51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PE5120N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PE5120N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PE51N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PE51N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S10PE51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PE51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S27PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S27PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S27PECA10N9LF	MATERIALS CHANGE	May 10, 2020			HM2S27PECA10N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S27PECA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2S27PECA20N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S30PD51M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PD51M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S30PD51M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PD51M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S30PD51M5N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PD51M5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S30PD51N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PD51N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S30PD51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PD51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S30PE51N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PE51N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S70PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S70PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S70PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S70PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S71PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S71PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2S71PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S71PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PDR3F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ON HOLD
PCN20007R2	HM2P07PDR3G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ON HOLD
PCN20007R2	HM2P07PCH185N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCH185N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PCH191N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCH191N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PCK235N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCK235N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PD5151N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD5151N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PDF1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PDN1Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1Y0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PDU2G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU2G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P08PCH171N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCH171N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P08PCH1A5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCH1A5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P08PDF1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P08PDK1Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDK1Y1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P09PD5115N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PD5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P87PDC161N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC161N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P88PDA1F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDA1F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P95PDF1E1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDF1E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2R87PA8104N9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PA8104N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDA1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDA1L1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDE1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE1R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDG1A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG1A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDG3U9N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG3U9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDH3C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH3C5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDK1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK1L1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDL2C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDL2C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDN3P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDN3X1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN3X1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDP255N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP255N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDP265N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP265N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDP2F5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP2F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PDU1A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU1A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PDE1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE1R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PDP285N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDP285N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PDP2K5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDP2K5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PDR1U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDR1U1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDE1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDE1U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE1U1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDJ3E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDJ3E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDJ3H5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDJ3H5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDK3H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDK3H0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P09PDR210N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR210N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P11PDG3M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PDG3M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P27PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P27PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P27PDJ3R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P27PDJ3R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P60PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PD5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PDA1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDA1L1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PDM3P5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDM3P5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PDT2A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDT2A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PDT2A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDT2A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P66PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P66PDK3E5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDK3E5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P67PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P67PDL380N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDL380N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P67PDU241N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDU241N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P70PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P71PD5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PD5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P71PDA1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDA1L1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P71PDE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P87PD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P88PD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PD8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P89PD8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PD8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P89PD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PD8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P89PDF1J1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDF1J1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P95PCG1X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PCG1X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P95PD8110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PD8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P95PD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PD8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P95PDF1J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDF1J0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P95PDF1J1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDF1J1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2PN1PDF3R5N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDF3R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2PN2PDE129N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN2PDE129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R01PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R01PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R01PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R02PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R02PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R03PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R03PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R03PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R10PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R10PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5101N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R10PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R10PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R30PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R30PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R30PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R30PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R50PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R50PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R65PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R65PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R65PA5118N9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PA5118N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R66PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R66PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R67PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R67PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R67PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R67PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R70PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R70PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R70PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R70PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R70PA510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R70PA510FN2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R71PA5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R71PA5100N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R71PA5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R71PA5108N2LF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R81PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R81PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R81PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R81PA8108N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R87PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PA8108N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R88PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8108N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R89PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R89PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PA8108N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R95PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PA8100N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R95PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PA8108N2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R95PA810FN9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PA810FN2LF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S01PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S01PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S02PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S02PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S07PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S07PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S10PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S10PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S10PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S30PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S30PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2S30PE51N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2S30PE51N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	10103553-103LF	MATERIALS CHANGE	May 10, 2020			20203553-203LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10127112-103LF	MATERIALS CHANGE	May 10, 2020			20127112-203LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10127156-102LF	MATERIALS CHANGE	May 10, 2020			20127156-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10127169-102LF	MATERIALS CHANGE	May 10, 2020			20127169-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10143986-101LF	MATERIALS CHANGE	May 10, 2020			20143986-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10148425-101LF	MATERIALS CHANGE	May 10, 2020			20148425-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10152237-101LF	MATERIALS CHANGE	May 10, 2020			20152237-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10152237-102LF	MATERIALS CHANGE	May 10, 2020			20152237-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10152239-101LF	MATERIALS CHANGE	May 10, 2020			20152239-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	

PCN20007R2	10152239-102LF	MATERIALS CHANGE	May 10, 2020			20152239-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155105-101LF	MATERIALS CHANGE	May 10, 2020			20155105-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155105-102LF	MATERIALS CHANGE	May 10, 2020			20155105-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155106-101LF	MATERIALS CHANGE	May 10, 2020			20155106-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155106-102LF	MATERIALS CHANGE	May 10, 2020			20155106-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155107-101LF	MATERIALS CHANGE	May 10, 2020			20155107-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155107-102LF	MATERIALS CHANGE	May 10, 2020			20155107-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155108-101LF	MATERIALS CHANGE	May 10, 2020			20155108-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155108-102LF	MATERIALS CHANGE	May 10, 2020			20155108-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155109-101LF	MATERIALS CHANGE	May 10, 2020			20155109-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155109-102LF	MATERIALS CHANGE	May 10, 2020			20155109-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155110-101LF	MATERIALS CHANGE	May 10, 2020			20155110-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155110-102LF	MATERIALS CHANGE	May 10, 2020			20155110-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155111-101LF	MATERIALS CHANGE	May 10, 2020			20155111-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155111-102LF	MATERIALS CHANGE	May 10, 2020			20155111-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155112-101LF	MATERIALS CHANGE	May 10, 2020			20155112-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155112-102LF	MATERIALS CHANGE	May 10, 2020			20155112-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155113-101LF	MATERIALS CHANGE	May 10, 2020			20155113-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155113-102LF	MATERIALS CHANGE	May 10, 2020			20155113-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155114-101LF	MATERIALS CHANGE	May 10, 2020			20155114-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155114-102LF	MATERIALS CHANGE	May 10, 2020			20155114-202LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10155115-101LF	MATERIALS CHANGE	May 10, 2020			20155115-201LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2C01D20010N9LF	MATERIALS CHANGE	May 10, 2020			HM2C01D20010N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2C12D2C011N9LF	MATERIALS CHANGE	May 10, 2020			HM2C12D2C011N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2J01PE5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2J01PE5110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2J07PE5170N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE5170N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2J07PE51Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2J07PE51Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2J08PEE128N9LF	MATERIALS CHANGE	May 10, 2020			HM2J08PEE128N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PAF1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PAF1G0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PC5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PC5110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PC5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PC5111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCA3L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCA3L0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCF1G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCF1M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCF1M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCH181N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCH181N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCH1C1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCH1C1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCH1C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCH1C5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCJ275N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCJ275N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCM131N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCM131N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCN240N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCN240N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCU1P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCU1P1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PCW191N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PCW191N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PD51Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PD51Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDA3H1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDA3H1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDA3P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDA3P0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE140N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE140N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE210N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE210N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE220N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE220N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE2A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE2A1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE340N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE340N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE3A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE3A1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDE3N5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDE3N5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF260N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF260N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF2K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF2K0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF2Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF2Y1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF320N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF320N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF370N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF370N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF3C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF3C0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF3L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF3L0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF3W1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF3W1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDF7Y5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDF7Y5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDG1P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG1P1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDG280N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDG280N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDH1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH1R0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDH3J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH3J0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDH3K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDH3K0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDJ265N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ265N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDJ285N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ285N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDJ295N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ295N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDJ3J5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ3J5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDJ3K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDJ3K1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDK110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDK130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDK2M5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK2M5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDK2P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK2P1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDK3U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDK3U1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDL395N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDL395N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDM111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDM161N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDM161N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDN141N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN141N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDN1F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1F1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDN1W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN1W0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDN2L5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN2L5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDN2N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDN2N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDP120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDP120N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDR1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR1U0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDR3Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDR3Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDS310N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDS310N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT140N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT140N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT1F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT1F0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT2CAN9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2CAN2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT2EAN9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2EAN2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT2F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2F0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT2FAN9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2FAN2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT2H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2H0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDT2X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDT2X0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDU1H0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU1H0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDU281N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU281N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDU2T1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU2T1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDU2U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU2U1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDU2W1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDU2W1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDW160N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDW160N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDW2A5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDW2A5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PDW2C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PDW2C5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P07PNL3A5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P07PNL3A5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PC5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PC5110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PCE121N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCE121N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PCF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCF1G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PCF1M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCF1M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PCH1A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCH1A1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PCW1A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PCW1A1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PD5130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PD5130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDA1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDA1L1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE150N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE150N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE230N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE230N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE290N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE290N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE380N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE380N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE3R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE3R0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE3T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE3T0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDE3Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDE3Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDF2M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF2M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDF3E0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF3E0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDF3K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF3K1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDF3M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDF3M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDJ2C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDJ2C5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDJ2J1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDJ2J1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDJ2N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDJ2N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDK1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDK1G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDK1P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDK1P0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDL310N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDL310N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN171N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN171N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN181N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN181N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN1R0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN1W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN1W0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN1W1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN1W1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN2W1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN2W1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDN2X1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDN2X1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDR161N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDR161N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDR1F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDR1F0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDR1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDR1G0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDR2U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDR2U1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDR2Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDR2Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDS2N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDS2N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDS2T1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDS2T1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDT1F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDT1F1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDT1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDT1G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDT280N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDT280N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDU120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDU120N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDU211N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDU211N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDU2M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDU2M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDU2N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDU2N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDU2P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDU2P1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PDW111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PDW111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PKS1U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PKS1U1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PZ5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PZ5110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P08PZ5111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P08PZ5111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PCF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PCF1G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PCF1M1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PCF1M1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PCK2A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PCK2A1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PD51X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PD51X0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDA1L1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDA1L1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDA1L5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDA1L5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDC010N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDC010N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDE3J5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE3J5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDE3P5N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE3P5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDE3W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDE3W0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDF130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDF130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDG2G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDG2G0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDH1T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDH1T0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDN191N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDN191N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDN2Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDN2Y1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDP130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDP130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDR1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR1U0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDR2R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDR2R1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDS2F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDS2F1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	

PCN20007R2	HM2P09PDT1Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDT1Y1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDU111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDU111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P09PDU130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P09PDU130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P11PC5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P11PC5110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P27PDE3X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P27PDE3X0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P27PDF3F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P27PDF3F0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P40PDG3W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDG3W0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P40PDJ341N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDJ341N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P40PDJ371N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDJ371N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P40PDL235N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDL235N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P40PDT2J0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P40PDT2J0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P60PD5110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P60PD5110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P65PCW231N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PCW231N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P65PDA3N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDA3N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P65PDK3Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDK3Y1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P65PDP2Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDP2Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P65PDU2A1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P65PDU2A1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P66PDL321N9LF	MATERIALS CHANGE	May 10, 2020			HM2P66PDL321N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P67PDT2N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P67PDT2N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P70PDL331N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDL331N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P70PDU171N9LF	MATERIALS CHANGE	May 10, 2020			HM2P70PDU171N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P71PDJ1N0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDJ1N0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P71PDK3T1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PDK3T1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P71PZJ331N9LF	MATERIALS CHANGE	May 10, 2020			HM2P71PZJ331N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P80PCF1G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PCF1G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P80PDA341N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDA341N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P80PDA351N9LF	MATERIALS CHANGE	May 10, 2020			HM2P80PDA351N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P82PDG1Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P82PDG1Y1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P84PDF1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P84PDF1R1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PAC135N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PAC135N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PC8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PC8111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PCE1K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PCE1K0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PCE1K1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PCE1K1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PD81A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD81A0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PD81C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD81C0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PD81G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PD81G0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDC1L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC1L0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDC1NAN9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC1NAN2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDC1P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC1P0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDC1U0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC1U0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDC1W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC1W0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDE120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDE120N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDF131N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDF131N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDF1P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDF1P1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDH191N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDH191N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDH1K0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDH1K0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDJ151N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDJ151N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87PDS3G1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDS3G1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P87SD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P87SD8111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PCH170N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PCH170N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PD81F0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PD81F0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDA1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDA1R0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDA1T0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDA1T0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDC1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDC1R0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDC1X0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDC1X0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDC1Y0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDC1Y0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDE110N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDE110N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDF1AGN9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDF1AGN2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDG1U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDG1U1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDH1F1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDH1F1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88PDH1G0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88PDH1G0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P88SD8111N9LF	MATERIALS CHANGE	May 10, 2020			HM2P88SD8111N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P89PDF1R1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDF1R1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P89PDG1Y1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDG1Y1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P89PDH1L0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDH1L0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P89PDH1N1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDH1N1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P89PDH1R0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PDH1R0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P89PZE125N9LF	MATERIALS CHANGE	May 10, 2020			HM2P89PZE125N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PD1J11N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PD1J11N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PD8119N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PD8119N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDF1W0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDF1W0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDF1X1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDF1X1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG120N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG120N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG130N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG130N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG140N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG140N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG150N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG150N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG160N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG160N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG1A0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1A0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG1P0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1P0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDG1U1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDG1U1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDH1C0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH1C0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDH1M0N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH1M0N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDH910N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDH910N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2P95PDK1P1N9LF	MATERIALS CHANGE	May 10, 2020			HM2P95PDK1P1N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2PN1PDE129N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDE129N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2PN1PDG3R9N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDG3R9N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2PN1PDG3T9N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDG3T9N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2PN1PDG3U9N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDG3U9N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2PN1PDH3C5N9LF	MATERIALS CHANGE	May 10, 2020			HM2PN1PDH3C5N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R01PA5500N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5500N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R01PA5600N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5600N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R01PACA35N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PACA35N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R01PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R01PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R02PA5400N9LF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5400N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R03PACA20N9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PACA20N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R03PE5100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R03PE5100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R10PACAM8N9LF	MATERIALS CHANGE	May 10, 2020			HM2R10PACAM8N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R65PE5108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R65PE5108N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R66PA5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R66PA5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R81PAEA10N9LF	MATERIALS CHANGE	May 10, 2020			HM2R81PAEA10N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R82PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R82PA8100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R82PA8108N9LF	MATERIALS CHANGE	May 10, 2020			HM2R82PA8108N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R85PA8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R85PA8100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R87PE8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PE8100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R87PE8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R87PE8101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R88PE8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R88PE8101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R89PE8100N9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PE8100N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R89PE8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R89PE8101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R90PA8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R90PA8101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2R95PE8101N9LF	MATERIALS CHANGE	May 10, 2020			HM2R95PE8101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2S03PE5101N9LF	MATERIALS CHANGE	May 10, 2020			HM2S03PE5101N2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	HM2S71PE510FN9LF	MATERIALS CHANGE	May 10, 2020			HM2S71PE510FN2LF	560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL	4950-49500	JIBU.BABU@FCI.COM	
PCN20007R2	10107426-103LF	MATERIALS CHANGE	May 10, 2020			10107426-203LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2A31PG60W0GFLF	MATERIALS CHANGE	May 10, 2020			HM2A31PG60W0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PK5118GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PK5118N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PK511CGFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PK511CN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PKE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKE127GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE127N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P07PKE180GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PKE2C5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE2C5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKE2E5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE2E5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKE2K5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE2K5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKE2MCGFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKE2MCN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKF1E0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKF1E0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P07PKF1H1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKF1H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKF3X4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKF3X4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKG1A4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKG1A4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKJ2R5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKJ2R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKJ2T5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKJ2T5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKK1M0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKK1M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKM2L5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKM2L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKM2M5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKM2M5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKM2N5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKM2N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKN214GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKN214N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP190GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP190N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP248GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP248N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP275GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP275N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP2E5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP2E5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP2G5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP2G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP2H5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP2H5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP2J5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP2J5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKP355GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKP355N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKR2W5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKR2W5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKR3N5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKR3N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKU1W1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKU1W1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKW1F9GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKW1F9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PKW2G5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PKW2G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PME120GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PME120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PME124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PME124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PME12KGFASLF	MATERIALS CHANGE	May 10, 2020			HM2P07PME12KN2ASLF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PME12KGFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PME12KN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PMF1U0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PMF1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PMF2R7GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PMF2R7N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PMG2J1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PMG2J1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PMK1N5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PMK1N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PML3L5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PML3L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PMP314GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PMP314N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE

PCN20007R2	HM2P07PMP324GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PMP324N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PN5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PN5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNF284GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNF284N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNG1A4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNG1A4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNG220GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNG220N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNG240GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNG240N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNH270GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNH270N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNK1C4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNK1C4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNK2R0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNK2R0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNK354GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNK354N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNK360GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNK360N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNM130GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNM130N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNT114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNT114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNU1A4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNU1A4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNU1F1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNU1F1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNU1G5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNU1G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNU1J5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNU1J5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNU2E4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNU2E4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNU2K0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNU2K0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNW1G5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNW1G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P07PNW2K5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P07PNW2K5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PK5117GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PK5117N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PKA365GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKA365N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PKE125GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKE125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKE127GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKE127N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKE128GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKE128N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKE2F5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKE2F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKF1G0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKF1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKF1H1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKF1H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKF1K9GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKF1K9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P08PKG3Y0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKG3Y0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKH3E5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKH3E5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKJ2U5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKJ2U5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKM2K5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKM2K5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKM2P5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKM2P5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKM2R5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKM2R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKM381GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKM381N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKM3T1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKM3T1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKP1A0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKP1A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P08PKP285GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKP285N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKP2L5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKP2L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKP2M5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKP2M5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKR3P5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKR3P5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PKS1Y0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PKS1Y0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PM5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PM5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PMA331GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PMA331N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PME124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PME124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PN5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PN5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNH280GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNH280N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNJ395GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNJ395N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNJ3L5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNJ3L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNK1C4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNK1C4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P08PNK344GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNK344N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNT114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNT114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P08PNW220GFLF	MATERIALS CHANGE	May 10, 2020			HM2P08PNW220N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PK5119GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PK5119N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P09PKA2G1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKA2G1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKE120GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKE120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKE125GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKE125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKE180GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKE180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKE2G5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKE2G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKF1H1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKF1H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKH3F5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKH3F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PKJ3T5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PKJ3T5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PM5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PM5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PM5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PM5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PME12JGFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PME12JN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PMJ1E4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PMJ1E4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PN5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PN5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P09PNT114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P09PNT114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P11PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P11PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P11PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P11PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P27PN5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P27PN5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P27PNS260GFLF	MATERIALS CHANGE	May 10, 2020			HM2P27PNS260N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P28PN5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P28PN5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P28PNS280GFLF	MATERIALS CHANGE	May 10, 2020			HM2P28PNS280N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P40PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PKA3R1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P40PKA3R1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PKE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P40PKE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PME3M0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P40PME3M0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PNT2W5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P40PNT2W5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P40PNW1G5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P40PNW1G5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PK5115GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PK5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PK511CGFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PK511CN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PKP365GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PKP365N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PKP3L8GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PKP3L8N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PKR3R5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PKR3R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PKU1N1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PKU1N1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P65PMA3X0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PMA3X0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PME120GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PME120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PMH3A1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PMH3A1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P65PMJ3W4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PMJ3W4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PMM364GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PMM364N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PN5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PN5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PN5115GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PN5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PN5119GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PN5119N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PNJ1E1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PNJ1E1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PNL2R5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PNL2R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P65PNM3W4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P65PNM3W4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PKF2U5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PKF2U5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PKF2U9GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PKF2U9N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PKF2W5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PKF2W5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PM5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PM5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PMA3U4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PMA3U4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P66PME124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P66PME124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P67PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PKA3A0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PKA3A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PMA3T4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PMA3T4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PME120GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PME120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PME125GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PME125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P67PN5119GFLF	MATERIALS CHANGE	May 10, 2020			HM2P67PN5119N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PK5111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PK5111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PKE121GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PKE121N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PKE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PKE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE

PCN20007R2	HM2P70PKE127GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PKE127N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P70PKG315GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PKG315N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PKT165GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PKT165N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PKW2H5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PKW2H5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PME124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PME124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P70PME129GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PME129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PME12CGFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PME12CN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PN5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PN5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNA3F5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNA3F5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNE129GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNE129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNE12CGFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNE12CN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNE7Y5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNE7Y5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNF2P4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNF2P4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNM3J5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNM3J5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNM3K5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNM3K5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNM3L5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNM3L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNM3M5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNM3M5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P70PNU17CGFLF	MATERIALS CHANGE	May 10, 2020			HM2P70PNU17CN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PK5115GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PK5115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PKE124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PKE124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PKS1L5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PKS1L5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PME124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PME124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PME125GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PME125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PME129GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PME129N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PMS2P4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PMS2P4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PMS2P5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PMS2P5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PN5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PN5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PNE125GFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PNE125N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P71PNE12CGFLF	MATERIALS CHANGE	May 10, 2020			HM2P71PNE12CN2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P73PN5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P73PN5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PK5110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P80PK5110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PK5114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P80PK5114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PKF1H1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P80PKF1H1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P80PKF1H7GFLF	MATERIALS CHANGE	May 10, 2020			HM2P80PKF1H7N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PKJ3U5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P80PKJ3U5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P80PMA3W1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P80PMA3W1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P82PKA1M1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P82PKA1M1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P82PME1P1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P82PME1P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P87PDC161N9G4LF	MATERIALS CHANGE	May 10, 2020			HM2P87PDC161N2G4LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PK8110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PK8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PK8111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PK8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PK8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PK8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PKJ1R5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PKJ1R5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PM8111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PM8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PME124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PME124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PME1P1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PME1P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PN8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PN8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P87PNA1N4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P87PNA1N4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PK8110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PK8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PK8111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PK8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PK8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PK8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PKF1U0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PKF1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PKJ1Y5GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PKJ1Y5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PKK115GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PKK115N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PKK124GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PKK124N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PKK177GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PKK177N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PM8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PM8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PME1P1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PME1P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PN8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PN8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PNC180GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PNC180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PNE180GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PNE180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PNE1U0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PNE1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P88PNK1T1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P88PNK1T1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PK8110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PK8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PK8111GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PK8111N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PK8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PK8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2P89PM8110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PM8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PME1P1GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PME1P1N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PMG1W4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PMG1W4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PN8114GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PN8114N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P89PNA1P4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P89PNA1P4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P95PK8110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PK8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PKJ180GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PKJ180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PKJ190GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PKJ190N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PKJ1A0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PKJ1A0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PKJ1C0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PKJ1C0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PKJ1F0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PKJ1F0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PKJ1G0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PKJ1G0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PM8110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PM8110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PMF1L4GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PMF1L4N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNE150GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNE150N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNE160GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNE160N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNE170GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNE170N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNE180GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNE180N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNE1U0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNE1U0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNE1W0GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNE1W0N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2P95PNF110GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNF110N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P95PNF120GFLF	MATERIALS CHANGE	May 10, 2020			HM2P95PNF120N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2P96PC8110N9PLF	MATERIALS CHANGE	May 10, 2020			HM2P96PC8110N2PLF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PNF3N5GFLF	MATERIALS CHANGE	May 10, 2020			HM2PN1PNF3N5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2PN1PNF3P5GFLF	MATERIALS CHANGE	May 10, 2020			HM2PN1PNF3P5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2PN1PNF3T5GFLF	MATERIALS CHANGE	May 10, 2020			HM2PN1PNF3T5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2PN1PNL3Y5GFLF	MATERIALS CHANGE	May 10, 2020			HM2PN1PNL3Y5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2PN2PMA1U5GFLF	MATERIALS CHANGE	May 10, 2020			HM2PN2PMA1U5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2PN2PNF3U5GFLF	MATERIALS CHANGE	May 10, 2020			HM2PN2PNF3U5N2LF	560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA5100N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5100N2JLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA5101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5101N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R01PA5108N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R01PA5108N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5100N9CLF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5100N2CLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R02PA5100N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5100N2JLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5101N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5108N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5108N2JLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5108N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5108N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R02PA5109N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R02PA5109N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R03PA5101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R03PA5101N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R03PA5108N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R03PA5108N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5100N9CLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5100N2CLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R10PA5100N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5100N2JLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5100N9MLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5100N2MLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5101N9CLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5101N2CLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5101N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5108N9CLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5108N2CLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5108N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5108N2JLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA5108N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA5108N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R10PA510FN9MLF	MATERIALS CHANGE	May 10, 2020			HM2R10PA510FN2MLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R21PA5100N9MLF	MATERIALS CHANGE	May 10, 2020			HM2R21PA5100N2MLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R21PA5101N9MLF	MATERIALS CHANGE	May 10, 2020			HM2R21PA5101N2MLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R30PA5101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R30PA5101N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	PROTOTYPE
PCN20007R2	HM2R30PA5108N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R30PA5108N2STLF	560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R81PA8100N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R81PA8100N2JLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R81PA8101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R81PA8101N2STLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R81PA8108N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R81PA8108N2JLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R83PA8101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R83PA8101N2STLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PA8100N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8100N2JLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R88PA8101N9STLF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8101N2STLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R88PA8108N9JLF	MATERIALS CHANGE	May 10, 2020			HM2R88PA8108N2JLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	SMARTER SERVICE
PCN20007R2	HM2R95PA8108N9CLF	MATERIALS CHANGE	May 10, 2020			HM2R95PA8108N2CLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE
PCN20007R2	HM2R96PA8100N9PLF	MATERIALS CHANGE	May 10, 2020			HM2R96PA8100N2PLF	560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW	4950-49500	JIBU.BABU@FCI.COM	ACTIVE

HM2P07PDE120N9L1LF	1
HM2P07PDE129N9LLF	2
HM2P07PDG1A1N9L1LF	3
HM2P07PDG1A1N9LLF	4
HM2P07PDG3U9N9LLF	5
HM2P07PDG3W0N9L1LF	6
HM2P07PDH3C5N9LLF	7
HM2P07PDN1Y0N9LLF	8
HM2P07PDP221N9L1LF	9
HM2P07PDP221N9LLF	10
HM2P07PDP231N9LLF	11
HM2P07PDP251N9L1LF	12
HM2P07PDP251N9LLF	13
HM2P07PDP255N9L1LF	14
HM2P07PDP255N9LLF	15
HM2P07PDP261N9L1LF	16
HM2P07PDP261N9LLF	17
HM2P07PDP265N9L1LF	18
HM2P07PDP265N9LLF	19
HM2P07PDP2C5N9LLF	20
HM2P07PDP2F5N9LLF	21
HM2P07PDW240N9L1LF	22
HM2P07PKE124GFLLF	23
HM2P07PKP248GFL1LF	24
HM2P07PKP275GFL1LF	25
HM2P07PKP2G5GFLLF	26
HM2P07PKP2H5GFLLF	27
HM2P07PKW260GFL1LF	28
HM2P08PD5110N9LLF	29
HM2P08PDE120N9L1LF	30
HM2P08PDE121N9L1LF	31
HM2P08PDE121N9LLF	32
HM2P08PDP285N9L1LF	33
HM2P08PDP285N9LLF	34
HM2P08PDP2K5N9LLF	35
HM2P08PDW250N9L1LF	36
HM2P08PKE128GFL1LF	37
HM2P08PKH3E5GFLLF	38
HM2P08PKP285GFL1LF	39
HM2P08PKP2L5GFLLF	40
HM2P08PKP2M5GFLLF	41
HM2P08PNH3W5GFLLF	42
HM2P09PD5110N9L1LF	43
HM2P09PD5110N9LLF	44
HM2P09PDE120N9L1LF	45
HM2P09PDE121N9L1LF	46
HM2P09PDG3P9N9LLF	47
HM2P09PDP291N9L1LF	48
HM2P09PDP291N9LLF	49
HM2P09PDS161N9LLF	50
HM2P09PKH3F5GFLLF	51
HM2P11PDG3M0N9LLF	52
HM2P11PDN260N9L1LF	53
HM2P65PD5110N9L1LF	54
HM2P65PD5111N9L1LF	55
HM2P65PDE120N9L1LF	56
HM2P65PDE121N9LLF	57
HM2P65PDE1R0N9L1LF	58
HM2P65PDM3P5N9LLF	59
HM2P66PD5110N9LLF	60
HM2P66PD5111N9LLF	61
HM2P66PD5115N9LLF	62
HM2P66PDE120N9LLF	63
HM2P66PDH321N9LLF	64
HM2P66PDH325N9LLF	65
HM2P66PK5114GFLLF	66
HM2P70PDE121N9LLF	67
HM2P70PKE124GFLLF	68
HM2P70PKG315GFLLF	69
HM2P70PKT165GFLLF	70
HM2P71PKS1L5GFLLF	71
HM2P87PDJ1M0N9L1LF	72

HM2P87PDJ1M1N9L1LF	73
HM2P87PDJ1M1N9LLF	74
HM2P89PD8110N9L1LF	75
HM2P91PDJ1M0N9L1LF	76
HM2P91PDJ1M1N9L1LF	77
HM2PN1PDF3R5N9LLF	78
HM2PN1PNF3N5GFLLF	79
HM2PN1PNF3P5GFLLF	80
HM2PN1PNL3Y5GFLLF	81
HM2PN2PDE129N9LLF	82
HM2PN2PMA1U5GFLLF	83
HM2PN2PNF3U5GFLLF	84
HM2PN3PDE3J5N9LLF	85
HM2S01PE5100N9L1LF	86
HM2ZA404LF	87
HM2ZA506LF	88

Millipacs Product Line
GXT+ Plating Upgrade



February 2020

Amphenol Information Communications and Commercial Products

FCi Basics

Amphenol ICC

Overview of GXT & GXT+ Plating

FCi Basics

- GXT ® plating is developed more than 30 years ago and was widely used in Millipacs, DIN, Metral, Dsub and other products of Amphenol Basics, HSBP and Consumer Product Portfolio.
- GXT +® plating was developed in 2012 as an upgrade version of current GXT plating. This plating type has been used by many other Amphenol product lines for years.
- Same as GXT ® plating, GXT+® plating also passed all internal and industry standard performance spec. As a conclusion, there is no product performance change between two plating types.
- Plating line is upgraded to handle production of GXT+
- No PN change is proposed with GXT+® supplies

Comparison

FCi Basics



- **GXT+® uses a nanocrystalline Ni deposit that replaces the current Ni layer**
- **The thickness of the hard gold layer remains the same.**
- **Reduction of the PdNi deposit and a high performance environmental barrier is applied.**

Amphenol ICC

Palladium price spiral

FCi Basics





Palladium price changes over the last few months have been drastic. GXT +® plating use less Palladium, so this plating type will be less impacted by the Palladium price increase seen recently

Amphenol ICC

Nano-Crystalline Nickel Technology Advantages

FCi Basics

- Improved corrosion resistance via reduced porosity due to the improved Ni grain structure.
- Improved Plating process control
- Similar or greater plating capacity

Nano-Crystalline-Grain Structure

FCi Basics

Matt Ni Sulfamate



Nano-Crystalline Ni



Amphenol ICC

Environmental barrier layer Poly-α- Olefin Lube

FCi Basics

- As a result of several years R & D, Amphenol has developed a high performance Poly-a- Olefin (PAO) lube to be capable to reduce Au & PdNi thickness w/o compromising product performance.
- The PAO lube has been used for more than 10 years by different product lines in Amphenol.
- **This study validates that PAO does not impact thermal stability, wear resistance, corrosion resistance and contact resistance of the finished product.**

Thermal stability – TGA test

FCi Basics

- **Thermal Gravimetric Analysis (TGA) has shown that the PAO lube is stable in elevated temperatures, as well as through a Lead-Free (LF) reflow process and over molding application.**



TESTS:

- ASTM method E1131-03 was followed with a Nitrogen flow rate of 40 mL/min, 5 minute isothermal, final temperature of 720 degrees centigrade and the parameters listed below:

	Run 1	Run 2	Run 3
Sample size mg	22.97	48.65	31.61
Heating Rate °C/min	5	20	20
Test Data:			
Start of mass loss Temperature °C	122	146	122

Amphenol ICC

Thermal Stability – Evaporation Rate

FCi Basics

- **A thermal age test at 105°C for 238 hrs was conducted and the evaporation rate of this high performance Poly-a-Olefin lube is very low @ <2%. Refer to attached chart:**



	1	2	3	4	5	6
Series1	20	50	137	150	170	238
Series2	0.85%	1.04%	1.82%	1.63%	1.79%	1.91%

Contact Resistance

- **Contact resistance impact from PAO after reflow & thermal aging conditions was evaluated. Measurements yielded results that were essentially equivalent to the four other surface treatments applied. Reflow treatment showed a slightly larger impact and a smaller impact from thermal aging. These affects are minimal and overall PAO is preferred for connector applications.**



Test conditions for Contact Resistance measuremens:

Equipment: Oscilating Tribotester from Tribotechnic with ohmmeter

System: Ball against plan

Static partner: 6 mm diameter Brass ball Hard gold plated

Normal Force: 5N

Thermal ageing: 105°C for 65 hours

LF Reflow: 245°C peak Temperature

Thank You

Product Test Laboratory
FCI USA, ELX Division
825 Old Trail Road
Etters, PA 17319

LABORATORY TEST REPORT

REPORT NO.	DATE OF REPORT	DATES TESTED	TESTED BY	
EL2012-09-019	**25SEP2012**	**04AUG2009-27AUG2009**	**S. Khounevixay**	
REQUESTOR	TITLE		Prepared By/Title	Approved By/Title
N. Zuo	**Millipacs® 15 µ" GXT™ (with lubricant) MFG & Durability Testing**		**J. Kopec Sr. Staff Eng.**	**G. Staudt Staff Eng.**

PURPOSE

This report summarizes the mixed flowing gas (MFG) and durability cycling testing performed on Millipacs header and receptacle connectors plated with 15 µ" GXT plating and lubricated with either PE-10 or PAO (poly alpha Olefin) lubricant.

CONCLUSIONS

All samples successfully met the Telcordia GR-1217-CORE low level contact resistance (LLCR) requirements following both MFG and durability (250 cycles) testing. All samples of both lubricant types were well below the maximum allowable increase in LLCR of 10 mΩ.

SAMPLE DESCRIPTION

Test samples consisted of 110 position Millipacs vertical headers and right angle receptacles plated with 0.38 µm GXT and lubricated with either PE-10 or PAO lubricant. Headers were mated to receptacles possessing the same lubricant only. The sample description table below describes the specific samples tested. Samples were received 8/3/09 and deemed suitable for testing by a member of the product test laboratory staff.

SAMPLE DESCRIPTION

Item	Description	Part #	Lot #	Base Mat'l	Plating Type µm/µ"
1	Millipacs receptacle with PE-10 lube	HM2P01PE5100N9LFA	P292623I15	PBr	0.38/15
2	Millipacs header with PE-10 lube	HM2P07PD5110Z1A	P292623I15	PBr	0.38/15
3	Millipacs receptacle with PAO lube	HM2P01PE5100N9LFB	P292702I16	PBr	0.38/15
4	Millipacs header with PAO lube	HM2P07PD5110Z1B	P292623I15	PBr	0.38/15
5	Millipacs receptacle LLCR test board	SK10027228 Rev. 1	0752	n/a	n/a
6	Millipacs header LLCR test board	SK10027227 Rev. 1	0752	n/a	n/a

TEST DESCRIPTIONS

MFG testing was performed in accordance with Telcordia GR-1217-CORE 12/08 and EIA-364-65A. The LLCR criterion of Telcordia GR-1217 (10 mΩ maximum increase) was applied to both the MFG and durability cycle test sequences. Sample size consisted of 5 mated pair connectors (550 total contacts) for both sample groups.

TEST SEQUENCES

Test Description	Grp. 1	Grp. 2
Initial examination	1	1
LLCR	2,4,6,8,10,12	2,4
Durability cycles – 99x	3,11	
Durability cycles – 250x		3
MFG – 10 days unmated	5	
MFG 10 days mated	7	
Minor disturbance	9	
Final examination	13	

TEST METHODS/REQUIREMENTS

Item	Test Method	Condition	Requirement
LLCR	EIA-364-23C	20mV max 100 ma max	After test – 10 mΩ max. LLCR increase
Durability	EIA-364-09C	5"/minute	No damage
MFG	EIA-364-65A	Class IIIa, 10 days unmated, 10 days mated, 20 ppb Cl2, 100 ppb H2S, 200 ppb NO2, 200 ppb SO2, 30C, 70% rh	10 mΩ max ΔLLCR
Minor Disturbance	EIA-364-09C	5"/minute	0.004" max. displacement

TEST RESULTS

All samples of both PE10 and PAO lubricant sample groups successfully met the Telcordia LLCR requirements throughout the MFG and durability cycle test groups. The statistical summary for the MFG testing is summarized in appendix A.

GROUP 1 MFG TEST RESULTS – PE10 SAMPLES

Step #	Test	Requirement	Step Description	Result	Comments
1	Visual Examination	No damage	Initial	No damage	Passed
2	LLCR	n/a	Initial	n/a	n/a
3	Durability	No damage	99 cycles	No damage	Passed
4	LLCR	10 mΩ max. LLCR increase	After 100 total cycles	1.45 m Ω max. increase	Passed
5	MFG – 10 days Unmated	No damage	10 days mated	No damage	Passed
6	LLCR	10 mΩ max. LLCR increase	After 10 days	2.48 m Ω max. increase	Passed
7	MFG – 10 days mated	No damage	10 days mated	No damage	Passed
8	LLCR	10 mΩ max. LLCR increase	After 10 days	3.36 m Ω max. increase	Passed
9	Minor Disturbance	No damage	After MFG	No damage	Passed
10	LLCR	10 mΩ max. LLCR increase	After 10 days	3.19 m Ω max. increase	Passed
11	Durability	No damage	99 cycles	No damage	Passed
12	LLCR	10 mΩ max. LLCR increase	After 200 total cycles	2.57 m Ω max. increase	Passed
13	Visual Examination	No damage	Final	No damage	Passed

GROUP 1 MFG TEST RESULTS – PAO SAMPLES

Step #	Test	Requirement	Step Description	Result	Comments
1	Visual Examination	No damage	Initial	No damage	Passed
2	LLCR	n/a	Initial	n/a	n/a
3	Durability	No damage	99 cycles	No damage	Passed
4	LLCR	10 mΩ max. LLCR increase	After 100 total cycles	1.27 m Ω max. increase	Passed
5	MFG – 10 days Unmated	No damage	10 days mated	No damage	Passed
6	LLCR	10 mΩ max. LLCR increase	After 10 days	2.98 m Ω max. increase	Passed
7	MFG – 10 days mated	No damage	10 days mated	No damage	Passed
8	LLCR	10 mΩ max. LLCR increase	After 10 days	7.95 m Ω max. increase	Passed
9	Minor Disturbance	No damage	After MFG	No damage	Passed
10	LLCR	10 mΩ max. LLCR increase	After 10 days	4.46 m Ω max. increase	Passed
11	Durability	No damage	99 cycles	No damage	Passed
12	LLCR	10 mΩ max. LLCR increase	After 200 total cycles	4.97 m Ω max. increase	Passed
13	Visual Examination	No damage	Final	No damage	Passed

GROUP 2 DURABILITY TEST RESULTS – PE10 SAMPLES

Step #	Test	Requirement	Step Description	Result	Comments
1	Visual Examination	No damage	Initial	No damage	Passed
2	LLCR	n/a	Initial	n/a	n/a
3	Durability	No damage	250 cycles	No damage	Passed
4	LLCR	10 mΩ max. LLCR increase	After 100 total cycles	2.42 m Ω max. increase	Passed

GROUP 2 DURABILITY TEST RESULTS – PAO SAMPLES

Step #	Test	Requirement	Step Description	Result	Comments
1	Visual Examination	No damage	Initial	No damage	Passed
2	LLCR	n/a	Initial	n/a	n/a
3	Durability	No damage	250 cycles	No damage	Passed
4	LLCR	10 mΩ max. LLCR increase	After 100 total cycles	0.84 m Ω max. increase	Passed

EQUIPMENT

Item	Manufacturer	ID Number	Last Cal.	Cal. Due
Micro-ohmmeter	Keithley	VG7024	DEC2008	DEC2009
Channel Scanner	Keithley	VG7100	N/C	N/C
Micro-ohmmeter	Keithley	VG6106	OCT2008	OCT2009
Channel Scanner	Keithley	VG7145	N/C	N/C
Compression/Tensile Tester	Instron	VG6463	SEP2008	SEP2009
MFG chamber	FCI	VG7537	CBU	CBU
N/C = not calibrated CBU = calibrate before use				

REVISION RECORD

Revision Level	Affected Pages	Description	Revision Date
A	All	Original Release	25SEP2012

APPENDIX A – MFG LLCR STATISTICAL SUMMARY

Table A1 – PE10 MFG ΔLLCR SUMMARY (mΩ)

	Initial (actual)	100X	10 Days Unmated	10 Days Mated	Disturb	200X
AVE	14.51	-0.12	-0.14	-0.02	-0.05	-0.19
MIN	11.04	-2.05	-2.41	-2.95	-2.92	-2.50
MAX	17.76	1.45	2.48	3.36	3.19	2.57
STDEV	1.35	0.47	0.48	0.69	0.64	0.60
COUNT	550	550	550	550	550	550

Table A2 – PAO MFG ΔLLCR SUMMARY (mΩ)

	Initial (actual)	100X	10 Days Unmated	10 Days Mated	Disturb	200X
AVE	14.19	-0.19	0.13	0.67	0.50	0.50
MIN	11.81	-1.83	-1.94	-1.88	-1.70	-2.13
MAX	20.29	1.27	2.98	7.95	4.46	4.97
STDEV	1.26	0.30	0.50	1.16	0.88	0.84
COUNT	550	550	550	550	550	550