# Product/Process Change Notifications

Amphenol ICC

**PCN - 20 007**

Amphenol Information Communication and Commercial Products Group

www.amphenol-icc.com

Release Date: February 25 2020

| | | | | |
|---|---|---|---|---|
| **Product Name:** | Millipacs | | | |
| | Millipacs All Versions | | | |
| **Product Manager:** | Jibu Babu | | | |
| **Subject:** | Notification of Change with Immediate Effectivity | | | |
| **Distribution:** | Global | | | |
| **Type of Change:** | Materials Change | | | |
| **Change Description:** | We propose to add GXT+ as approved plating material (as per details attached) for 2mm Millipacs meeting the product performance specifications. There is no change to the existing plating location nor to the part numbers. | | | |
| **Reason for Change:** | Palladium prices have increased significantly over the last several years causing drastic increase in cost of production. We are reviewing the current product pricing. To reduce the impact of palladium metal price spiral on the cost of production, we are implementing GXT+ plating in our process. Your qualification approval will help us to limit the product price increase. | | | |
| **Affected Parts:** | Refer Attached Affected Parts.xls file | | | |
| **Effective Date of Change:** | April 20, 2020 | | | |
| **Last Time Buy Date:** | NA | | | |
| **Last Disty Return Date:** | NA | | | |
| **Last Time Shipment Date** | NA | | | |
| **Datasheet Attached?** | | | | |
| **Qual/Test Data Attached?** | NA | | | |
| **Samples Availability Date:** | March | 3 | 2020 | |
| **Available Alternatives?** | Select | | | |
| **Questions?** | *Contact your local AICC Representative, or Product Manager* | | | |
| | *Jibu Babu* | | | |
| | *914843391946 / Jibu.Babu@fci.com* | | | |

Note:
Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN.
Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

| PCN Reference | MPN | Change | Effective Date | Last Disty Return date | Last Shipment date | Alternative Parts | Product Family | Primary MU | Product Manager | Status |
|---|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2C01D0C010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HUF-MILLIPACS LF CABLE CONNECTOR | 4543-45430 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2C01D2C010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HUF-MILLIPACS LF CABLE CONNECTOR | 4543-45430 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2C06D0C010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HUF-MILLIPACS LF CABLE CONNECTOR | 4543-45430 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2C06D2C010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HUF-MILLIPACS LF CABLE CONNECTOR | 4543-45430 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10121566-103LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-56YF-MILLIPACS 10G VERT. HEADER | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10123492-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10127112-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10127112-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10127156-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10127169-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10129748-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10132170-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10132170-103LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10137566-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10140927-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5KBF-MILLIPACS 25G VERTICAL HEADER | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10140928-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5KAF-MILLIPACS 25G RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10142582-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5KBF-MILLIPACS 25G VERTICAL HEADER | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10142583-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5KAF-MILLIPACS 25G RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10143147-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10147936-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10148426-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10148426-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10148532-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10152238-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | 10152238-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HZF-10G 5ROW RIGHT ANGLE RECEPTACLE | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2A31PG5000N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2E31PH6090N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J02PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J03PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J07PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J07PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J07PE5128N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J07PE51A8N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J07PE51K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J07PEE128N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J08PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J08PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J08PE51H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE5130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE5160N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE5168N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE51C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE51N8N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE51P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE51P8N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PE51R8N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PEA158N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PEA210N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J09PEA310N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J65PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J65PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J66PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J66PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J70PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J70PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J70PEE128N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J71PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J71PE5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J71PEA158N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2J71PEE128N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HTF-MILLIPACS RA HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PCH290N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PCJ3P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PD5115N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PD51M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PD5310N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDA3K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE129N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE1F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE320N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE391N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE3F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDE3U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDF1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDF1G5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDF2E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDF2J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDF310N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDG190N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDG3G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDG3R9N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDG3T9N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDH2F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDH311N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDH331N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDH3R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDJ1N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDJ1N5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDJ2H1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDJ341N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDJ3M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDJ3N5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK1L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK261N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK265N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK2R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK2W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK3J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK3K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK3N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDK3R5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDL235N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDL3E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDL3R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDL3X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDM295N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDM2C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDM2E5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDM2F5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2P07PDM311N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDM321N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDM350N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN131N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN1A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN1C1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN1E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN1W1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN271N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN2C4N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN3E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN3H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN3J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN3U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDN3W5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP171N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP1C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP1W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP221N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP231N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP235N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP251N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP261N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP2C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP2P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP2U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP345N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP3A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP3A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP3G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP3H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDP3K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR240N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR3C1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR3E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR3K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR3L5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR3U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDS290N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDS2A5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDS370N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDS380N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDS3E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT120N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT1E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT1F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT1X1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT221N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT2C1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT2G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT2E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDT2X1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDU141N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDU1A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDU1C1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDU1E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDW145N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDW2M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDW2N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PZ511N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PZFJG0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PC511N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PCH2A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PCK220N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDS115N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDE151N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDE12N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDE1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDE2A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDE310N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDF1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDF1N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDG3H1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDJ381N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDK1H5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDM2G5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDN151N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDN3K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDP1E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDP2W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDS2U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDS3X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDU270N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDW2E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P08PDW2F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PC5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PC5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PCK291N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PD5151N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PD5310N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDE121DN9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDE129N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDF1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDF1H1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDF1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDG3J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDG3P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDH2G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDH340N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDH3T0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDH3U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDJ1N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDJ1N5N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDJ320N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDK330N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P09PDK3F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | 560.5HQE-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2P09PDK3G0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PD L3C0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDL3M0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDM28SN9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDM390N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDM3U0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDN3T1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDP29IN9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDP38SN9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDP3M0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDP3Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDR2J0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDR2K0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDR2X0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDR360N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDS16I1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDS2S0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDS35I1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDU1M5N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDU21N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PDU2C0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PZ51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09PZ51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09SZ51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P09SZ51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PD51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PDG3L0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PDJ2P0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PDM3R1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PDN260N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11PDN3N1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11SZ50110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P11SZ50111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P28PC51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P28PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P27PDG32N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P27PDG33N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P29PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40PD51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40PDE3L0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40PDW145N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40SZ51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P40SZE121N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P47PD51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P47PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P47PDE121DN9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P60PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P60PDA11N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P60PDE1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P60PDT2R0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P64PD P3C5N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PC51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PCT260N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDA3M1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDE1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDF1G5N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDF27SN9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PH2L5N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDJ3X0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDK311N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDM37J1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDM3H1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDP35N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P65PDR27D0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P66PDT2P1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P66PDA3C0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P66PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P66PDE125N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P66PDE331N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P67PDK3X0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P67PDS241N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P67PZ51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PD51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PDE125N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PDF2X5N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PDG3C1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PDJ3F5N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PDP275N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P68PDS2K1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PD51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PD51111N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDE124N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDE1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDH2K6N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDJ381N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDN3F0N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDN2N1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PDU175N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P70PZ121N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P71PD51110N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P71PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P71PDF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |
| PCN20007 | HM2P71PDK321N9LF | MATERIALS CHANGE | April 20, 2020 | | 560-5HQF-MILLPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | | ACTIVE |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2P71PDP3J5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P71PDS250N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P71PDS3A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P73PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P77PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P78PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P78PDS341N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P79PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PD5115N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PDL341N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PDL3F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PDL3F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P80PDS2T1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P82PD8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P82PD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P83PZF1F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P84PZE125N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P85PD8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PD8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PD81H5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PD81K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDA1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDC160N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDF1K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDF1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDH1E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDH3Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDJ1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDJ1W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDK1K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PDK1N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P87PZC135N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PC8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PD8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PD81H5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PD81K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PD81N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDA111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDC161N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDF141N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDH3X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P88PDJ131N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDC145N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDH1J1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDH1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDJ121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDK150N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDK180N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDK1L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PDK1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P89PZJ1P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PCH170N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG170N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG180N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG190N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDG1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDH120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDH1M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDH1P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDH3U5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDH3W5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDK131N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDK1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P95PDK1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN1PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN1PDP255N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN1PDP265N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN1PDP2F5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN1PDP3F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN1PDT231N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN2PDP285N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN2PDP2K5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2PN3PDE3J5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R01PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R01PA5102N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R01PA5104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R01PA510JN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R01PACA39N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PA5104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PA5107N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PA510JN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PACA10N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R02PE5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R03PA5104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R03PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R03PA510JN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R05PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R05PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R05PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R10PA510YN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R10PA5300N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R10PACA39N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R10PACAK0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R10PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R10PE5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R20PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R20PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R20PA5104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2R20PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R21PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R21PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R21PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R27PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R29PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PA510YN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PA51A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PA5300N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PACA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PACAJ0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PAFA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PAGA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R30PE5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R50PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R50PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R62PA510YN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R64PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R65PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R65PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R65PA510YN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R65PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R66PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R66PA510YN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R69PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R69PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R70PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R70PE5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R71PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R71PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R71PE5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R77PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R77PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R78PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R78PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R79PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R79PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R81PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R82PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R82PA8104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R83PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R83PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R83PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R87PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R87PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R87PA810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R87PE810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PA8104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PA810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PAEA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PAGA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PE8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R88PE810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R89PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R89PA8104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R89PA810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R89PE810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R90PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R95PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R95PE8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2R95PE810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S01PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PD51M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PD51M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PD51N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PD51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PE51N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S02PE51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S03PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S05PE51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S05PE51N2N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S05PE51N3N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S05PE51N7N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PD51M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PD51M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PD51N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PD51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PE5120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PE51N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S10PE51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S27PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S27PECA10N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S27PECA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S30PD51M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S30PD51M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S30PD51M5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S30PD51N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S30PD51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S30PE51N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S70PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S70PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S71PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2S71PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ACTIVE |
| PCN20007 | HM2P07PDR3F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ON HOLD |
| PCN20007 | HM2P07PDR3G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | ON HOLD |
| PCN20007 | HM2P07PCH185N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PCH191N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PCK235N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PD5151N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PDF1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PDN1Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PDU2G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P08PCH171N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P08PCH1A5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P08PDF1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P08PDK1Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P09PD5115N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P87PDC161N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P88PDA1F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P95PDF1E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2R87PA8104N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | PROTOTYPE |
| PCN20007 | HM2P07PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDA1L1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2P07PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDE1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDG1A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDG3U9N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDH3C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDK1L1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDL2C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDN3P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDN3X1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDP255N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDP265N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDP2F5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P07PDU1A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PDE1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PDP285N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PDP2K5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P08PDR1U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDE1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDE1U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDJ3E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDJ3H5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDK3H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P09PDR210N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P11PDG3M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P27PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P27PDJ3R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P60PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PDA1L1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PDM3P5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PDT2A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P65PDT2A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P66PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P66PDK3E5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P67PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P67PDL380N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P67PDU241N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P70PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P71PD5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P71PDA1L1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P71PDE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P87PD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P88PD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P89PD8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P89PD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P89PDF1J1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P95PCG1X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P95PD8110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P95PD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P95PDF1J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2P95PDF1J1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2PN1PDF3R5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2PN2PDE129N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R01PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R01PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R01PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R02PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R02PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R03PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R03PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R03PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R10PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R10PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R10PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R10PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R30PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R30PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R30PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R50PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R65PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R65PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R65PA5118N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R66PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R67PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R67PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R70PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R70PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R70PA510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R71PA5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R71PA5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R81PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R81PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R87PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R88PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R89PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R89PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R95PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R95PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2R95PA810FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HYF-MILLIPACS RA RECEPTACLE SIGNAL 8 ROW | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S01PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S02PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S07PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S10PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S10PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S30PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S30PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | HM2S30PE51N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | SMARTER SERVICE |
| PCN20007 | 10103553-103LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10127112-103LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10127156-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10127169-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10143986-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148425-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148537-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148537-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148538-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148538-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148539-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10148539-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |
| PCN20007 | 10152237-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | 10152237-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10152239-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10152239-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155105-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155105-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155106-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155106-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155107-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155107-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155108-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155108-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155109-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155109-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155110-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155110-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155111-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155111-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155112-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155112-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155113-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155113-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155114-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155114-102LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | 10155115-101LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2C01D20010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2C12D2C011N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2J01PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2J07PE5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2J07PE51Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2J08PEE128N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PAF1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PC5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PC5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCA3L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCF1M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCH181N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCH1C1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCH1C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCJ275N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCM131N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCN240N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCU1P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PCW191N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PD51Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDA3H1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDA3P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE140N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE210N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE220N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE2A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE340N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE3A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDE3N5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF260N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF2K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF2Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF320N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF370N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF3C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF3L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF3W1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDF7Y5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDG1P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDG280N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDH1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDH3J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDH3K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDJ265N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDJ285N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDJ295N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDJ3J5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDJ3K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDK110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDK130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDK2M5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDK2P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDK3U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDL395N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDM111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDM161N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDN141N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDN1F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDN1W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDN2L5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDN2N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDP120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDR1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDR3Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDS310N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT140N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT1F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT2CAN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT2EAN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT2F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT2FAN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT2H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDT2X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDU1H0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDU281N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDU2T1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDU2U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDU2W1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDW160N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDW2A5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PDW2C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P07PNL3A5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PC5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PCE121N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PCF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PCF1M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PCH1A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PCW1A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PD5130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDA1L1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2P08PDE150N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDE230N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDE290N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDE380N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDE3R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDE3T0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDE3Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDF2M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDF3E0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDF3K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDF3M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDJ2C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDJ2J1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDJ2N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDK1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDK1P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDL310N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN171N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN181N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN1W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN1W1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN2W1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDN2X1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDR161N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDR1F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDR1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDR2U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDR2Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDS2N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDS2T1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDT1F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDT1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDT280N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDU120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDU211N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDU2M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDU2N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDU2P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PDW111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PKS1U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PZ5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P08PZ5111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PCF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PCF1M1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PCK2A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PD51X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDA1L1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDA1L5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDC010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDE3J5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDE3P5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDE3W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDF130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDG2G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDH1T0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDN191N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDN2Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDP130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDR1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDR2R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDS2E1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDT010N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDT1Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDU111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P09PDU130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P11PC5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P27PDE3X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P27PDF3F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P40PDG3W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P40PDJ341N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P40PDJ371N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P40PDL235N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P40PDT2J0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P60PD5110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P65PCW231N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P65PDA3N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P65PDK3Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P65PDP2Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P65PDU2A1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P66PDL321N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P67PDT2N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P70PDL331N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P70PDU171N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P71PDJ1N0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P71PDK3T1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P71PZJ331N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P80PCF1G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P80PDA341N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P80PDA351N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P82PDG1Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P84PDF1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PAC135N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PC8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PCE1K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PCE1K1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PD81A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PD81C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PD81G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDC1L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDC1NAN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDC1P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDC1U0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDC1W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDE120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDF131N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDF1P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDH191N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDH1K0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDJ151N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87PDS3G1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P87SD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PCH170N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PD81F0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDA1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDA1T0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDC1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| PCN20007 | HM2P88PDC1X0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDC1Y0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDE110N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDF1AGN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDG1U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDH1F1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88PDH1G0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P88SD8111N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P89PDF1R1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P89PDG1Y1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P89PDH1L0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P89PDH1N1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P89PDH1R0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P89PZE125N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PD1J11N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PD8119N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDF1W0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDF1X1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG120N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG130N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG140N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG150N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG160N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG1A0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG1P0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDG1U1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDH1C0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDH1M0N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDH910N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2P95PDK1P1N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2PN1PDE129N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2PN1PDG3R9N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2PN1PDG3T9N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2PN1PDG3U9N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2PN1PDH3C5N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R01PA5500N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R01PA5600N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R01PACA35N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R01PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R02PA5400N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R03PACA20N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R03PE5100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R10PACAM8N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R65PE5108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R66PA5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R81PAEA10N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R82PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R82PA8108N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R85PA8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R87PE8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R87PE8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R88PE8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R89PE8100N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R89PE8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R90PA8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2R95PE8101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2S03PE5101N9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |
| PCN20007 | HM2S71PE510FN9LF | MATERIALS CHANGE | April 20, 2020 | | | | 560-5HSF-MILLIPACS STRAIGHT RECEPTACLE SIGNAL | 4950-49500 | JIBU.BABU@FCI.COM |