
Eaton
5735 W. Las Positas, Blvd
Suite 100
Pleasanton, CA 94588
www.eaton.com/elx

Product Change Notice


March 24, 2015

CLASSIFICATION OF CHANGE:
Appearance change.

DESCRIPTION OF CHANGE:
The Eaton PowerStor XB and XV Series supercapacitors are receiving a visible change. This change involves adding a groove around the circumference at the center of the length, as shown in the illustration below.



Current Cell Shape



New Cell Shape

REASON FOR CHANGE:
This groove enhances mechanical stability to the electrode structure inside the can and is part of our continuous improvement efforts.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, PERFORMANCE:
There is no change to the form, fit, electrical properties, or function of these supercapacitors.

PARTS NUMBERS/SERIES/FAMILIES AFFECTED:

XB3550-2R5307-R	XB3560-2R5407-R	XB3585-2R5607-R
XV3550-2R7307-R	XV3560-2R7407-R	XV3585-2R7607-R

TIME SCHEDULE:
Start Shipment Date: October 1, 2014 (date code X40). Existing inventory is saleable and should not be returned.
Last Time Buy Date: n/a
Last Time Shipment Date: n/a

SAMPLE AVAILABILITY:
n/a

QUALIFICATION DATA:
n/a

ISSUED BY:

Jason Lee, Global Product Manager - Supercapacitors

If you have any question about this product change, please contact your local Eaton representative.