Product Change Notification

Current Date: 30-Sep-2025

TE Connectivity

Product Change Notification: P-25-028925 **PCN Date:** 30-SEP-25

Customer: TTI Inc (1305175) **Location:** Maisach-gernlinden **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMP SUPERSEAL 1.5 SERIES 2P PL

Description of Changes
Dear Customer, This Product Change Notification (PCN) applies exclusively to customers who purchase the component from TE Connectivity Brazil. We would like to inform you that the component 282057-1, used in the assembly part 282080-1, will be transitioned to an outsourced manufacturing process.

Reason for Changes:	
Dear customer , as result of our continuous strive for improving our process, we hereby inform you about this outsourcing. This outsourcing is executing by following a strict procedure which garantees no negative influence on quality, ability to supply and form-fit-function of this product. Please after receiving this notification, PPAP and samples must be requested by ePPAP System in 10 days.In case ofyou do not request in ePPAP, TE Connectivity will understand and considered that this change was accepted.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
	15-OCT-2025
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211", "8202611296", "8202613264"			

Product Change Notification

Current Date: 30-Sep-2025

TE Connectivity

Product Change Notification: P-25-028925 **PCN Date:** 30-SEP-25

Customer: TTI, Inc. (3057778) **Location:** Maisach-gernlinden **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMP SUPERSEAL 1.5 SERIES 2P PL

Description of Changes
Dear Customer, This Product Change Notification (PCN) applies exclusively to customers who purchase the component from TE Connectivity Brazil. We would like to inform you that the component 282057-1, used in the assembly part 282080-1, will be transitioned to an outsourced manufacturing process.

Reason for Changes:	
Dear customer , as result of our continuous strive for improving our process, we hereby inform you about this outsourcing. This outsourcing is executing by following a strict procedure which garantees no negative influence on quality, ability to supply and form-fit-function of this product. Please after receiving this notification, PPAP and samples must be requested by ePPAP System in 10 days.In case ofyou do not request in ePPAP, TE Connectivity will understand and considered that this change was accepted.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
	15-OCT-2025
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO		TYC282080-1	"CM8390-000", "AMP-0-0282080-1", "2-42939-6211", "8202611296", "8202613264"			