16-Sep-2024

PCN #: P-24-026887

Subject : Tinel Ring Backshells

Description of Change : Additional manufacturing sources.

Reason for Change: Part status change.As part of our continuous strive to aid our lead-time recovery, we hereby inform you about using additional sources for parts in this PCN. This is executed by a strict transfer procedure, guaranteeing no negative influence on quality, ability to supply and FFF. The additional manufacturing locations are under a certified quality management system. An internal release based on our specifications will be executed before any parts will be delivered, which ensures the continued performance criteria.

Key Dates :
Contact By Date:23-Sep-2024
Implementation Date:23-Sep-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CH3059-000	8-1899603-5, TX40AU00-1410		
CH3060-000	8-1899603-6, TX40AU00-1606		
CH3061-000	8-1899603-7, TX40AU00-1612		
CH3622-000	7-1899616-5, TXR40SJ00-1206AIV		
CH3867-000	5-1899623-0, STXR40AU00-2022BI		
CH4881-000	2-1899651-0, STX40AU00-0806		
CH4882-000	2-1899651-1, STX40AU00-1008		
CH4883-000	2-1899651-2, STX40AU00-1210		
CH4884-000	2-1899651-3, TX40AU00-1608		
CH4885-000	2-1899651-4, TX40AU00-1814		
CH4886-000	2-1899651-5, TX40AU00-2014		
CH4887-000	2-1899651-6, TX40AU00-2414		
CH5222-000	2-1899661-0, STXR40AU00-2422BI		
CH5323-000	3-1899668-9, STXR40AB00-2224AI		
CH5547-000	7-1899671-5, STXR40AZ00-1210AI		
CH5653-000	4-1899672-5, TXR40AB00-2414AIJ		
CH6526-000	8-1899679-5, STXR40SJ00-1212AI		
CH6527-000	8-1899679-6, STXR40SJ00-2222AI		
CJ0897-000	STXR40BW00-1614AI2, 3-1899250-1		
CJ0903-000	TXR40BW00-1610AI2, 3-1899250-7		
CJ2394-000	TXR40SC00-2008AI, 2-1899261-7		
CJ3465-000	TXR40SJ00-0805AI		

CJ7005-000	TXR40AU00-1612AI2, 6-1899301-2		
CJ7008-000	TXR40AU00-2212AI2, 6-1899301-5		
CJ7009-000	TXR40AU00-2420AI2, 6-1899301-6		
CJ7137-000	STXR40SC00-2416BI, 4-1899302-9		
CJ7139-000	STXR40AB00-2416BI, 5-1899302-0		
CJ7140-000	TXR40SC00-2020BI, 5-1899302-2		
CJ7141-000	TXR40SC00-2220BI, 5-1899302-3		
CJ7664-000	TXR40SJ00-2408BI		
CJ8793-000	TXR40AU00-1212BI, 3-1899310-3		
CJ9843-000	TXR40AU00-1412AI, 9-1899315-6		
CJ9844-000	TXR40AU00-0808AI, 9-1899315-7		
CJ9852-000	TXR40AU00-1414AI, 1899316-2		
CJ9894-000	TXR40AU00-1422AI, 3-1899316-3		
CL0041-000	TXR40AU00-2206AI, 8-1899316-1		
CL1231-000	TXR40SJ00-2214BI		
CL1430-000	TX40SC00-1806, 6-1899327-0		
CL1870-000	STXR40BW00-1010AI, 3-1899329-6		
CL4970-000	STXR40AB00-1410BI, 3-1899350-9		
CL5724-000	TX40AC00-1212		
CL6211-000	TXR40AC00-2220BI, 4-1899359-2		
CL7829-000	TXR40SC00-1606AI, 5-1899368-4		
CL8991-000	TX40AB00-1805J		
CL8992-000	TXR40AB00-1805AI2J		
CL9268-000	TX40SC00-1008, 9-1899374-1		
CL9269-000	TX40SC00-1412, 9-1899374-2		
CL9702-000	STXR40BW00-0808BI, 7-1899377-9		
CL9703-000	STXR40AU00-2220AI, 8-1899377-0		
CM0157-000	STXR40AU00-2220BI, 1-1899380-2		
CM0185-000	STXR40AU00-2222AI, 5-1899380-9		
CM2132-000	TX40AB00-1207H		
CM2548-000	TX40BW00-1208, 3-1899400-0		
CM3008-000	TXR40AU00-1807BI, 6-1899402-6		
CM3070-000	TXR40AU00-1805BI, 9-1899402-2		
CM3153-000	STXR40AB00-1612BI, 6-1899404-7		
CM3394-000	STXR40AB00-1214BI, 2-1899407-4		
CM3475-000	TXR40AB00-2416AI2-30, 1899408-1		
CM3902-000	STXR40AC00-1216BI, 8-1899411-4		
CM3903-000	STXR40SJ00-0805AI, 8-1899411-5		
CM5744-000	TXR40SJ00-2406AI		
CM5745-000	TX40SJ00-2406		
CM6875-000	TXR40AU00-1807AI, 2-1899431-0		
CM9081-000	9-1899445-4, STXR40SJ00-1007AI		
CM9518-000	STXR40AU00-1010BI, 9-1899448-2		
CN0152-000	TXR40SC00-2420AI, 6-1899454-6		
CN0743-000	TX40SJ00-1010		
CN2389-000	STXR40SJ00-2422AI, 1899470-4		
CN2390-000	STXR40SJ00-2220AI, 1899470-5		
CN2713-000	TXR40AU00-1405BI, 8-1899471-8		
CN3295-000	STXR40AU00-1014AI, 2-1899474-7		
CN4347-000	STXR40BW00-1818AI, 1899479-8		
CN6360-000	STXR40AC00-1010BI, 1899490-3		
CN6361-000	STXR40AU00-2018BI, 1899490-4		
CN8584-000	TX40BW00-1812		
CN9249-000	STXR40AC00-1818BI, 3-1899506-2		
CN9657-000	TXR40SJ00-2006BI		
CN9659-000	TXR40SJ00-2010BI		

CN9661-000	TX40SJ00-2018		
CP1032-000	TXR40SJ00-2406BI		
CP4998-000	TXR40SJ00-1614AI		
CP4999-000	TX40SJ00-1614		
CP5352-000	TXR40SJ00-1614BI		
CP6751-000	TXR40SJ00-1804AI		
CP6752-000	TX40SJ00-1804		
CP6763-000	TXR40SJ00-1604BI		
CS0148-000	TXR40AB00-1007BIJ		
CS0149-000	TXR40AB00-1612BIJ		
CS0234-000	TX40AB00-2412J		
CS0235-000	TX40AB00-2410J		
CS0237-000	TX40AB00-1406J		
CS0238-000	TX40AB00-2210J		
CS0239-000	TX40AB00-2414J		
CS0240-000	TX40AB00-2408J		
CS0256-000	TXR40AB00-1605BIS		
CS0257-000	TX40AB00-1605S		
CS0300-000	TX40AB00-2218J		
CS0355-000	TX40AB00-2420J		
CS3899-000	TXR40AC00-0810AI		
CS6624-000	TX40BW00-1607		
CS6627-000	STX40SJ00-1816		
CU3850-000	STX40AB00-2422		
CV0061-000	6-1899704-4, STXR40AU00-1420BI		
CV0319-000	2-1899711-3, TXR40BW00-1620AI		
CV0367-000	9-1899711-9, STXR40AU00-1618BI		
CV0401-000	4-1899712-7, STXR40AC00-1618BI		
CV0451-000	2-1899717-3, STXR40SJ00-1414AI		
CV0453-000	4-1899717-4, STXR40AB00-0816BI		
CV0508-000	8-1899722-2, STXR40AB00-2424AI		
CV0639-000	9-1899727-3, STXR40SC00-1210BI		
CV1087-000	8-1899743-2, TXR40SC00-1212AI		
CV1156-000	8-1899744-9, STXR40SJ00-1412BI		
CV1157-000	9-1899744-0, STXR40SJ00-1416BI		
CV1543-000	STXR40AZ00-1010BI		
CV1544-000	STXR40AZ00-0808BI		
CV1545-000	STXR40AZ00-1016BI		
CV1546-000	STXR40AZ00-1018BI		
CV1547-000	STXR40AZ00-1008BI		
CV1548-000	STXR40AZ00-1214BI		
CV1549-000	3-1899758-0, STXR40AZ00-1216BI		
CV1719-000	STXR40SJ00-1414BI		
CV1975-000	STXR40BW00-1816AI		
CV3088-000	STXR40SC00-1816BI		
CV4109-000	STXR40SJ00-0808AI		
CV4422-000	STX40AZ00-1412		
CV4462-000	TX40AZ00-0806		
CV4463-000	TX40AZ00-1010		
CV4464-000	TX40AZ00-1210		
CV4465-000	TX40AZ00-1412		
CV4466-000	TX40AZ00-1414		
CV4467-000	TX40AZ00-1418		
CV4468-000	TX40AZ00-2006		
CV4469-000	TX40AZ00-2018		
CV4470-000	TX40AZ00-2416		

CV4471-000	TX40AZ00-2418		
CV5186-000	TX40AZ00-2420		
CV5400-000	STXR40AZ00-0806AI		
CV5402-000	STXR40AZ00-1008AI		
CW0483-000	TX40AZ00-2410		
CW0596-000	TX40AZ00-1607		
CW0597-000	TX40AZ00-1814		
CW0598-000	TX40AZ00-2010		
CW0599-000	TX40AZ00-2408		
CW0608-000	TX40AZ00-1608		
CW1048-000	2-1899772-2, TX40AZ00-1005		
CW1050-000	TX40AZ00-1204		
CW1052-000	TX40AZ00-1205		
CW1054-000	TX40AZ00-1207		
CW1057-000	TX40AZ00-1404		
CW1059-000	TX40AZ00-1406		
CW1062-000	TX40AZ00-1407		
CW1064-000	TX40AZ00-1408		
CW1069-000	TX40AZ00-1604		
CW1071-000	TX40AZ00-1812		
CW1073-000	TX40AZ00-2007		
CW1075-000	TX40AZ00-2207		
CW1077-000	TX40AZ00-2208		
CW1079-000	TX40AZ00-2210		
CW1081-000	TX40AZ00-2216		
CW1827-000	TXR40AZ00-0805BI		
CW1828-000	TX40AZ00-0805		
CW1868-000	STX40AZ00-0808		
CW1869-000	STX40AZ00-1008		
CW1870-000	STX40AZ00-1010		
CW3276-000	TX40AC00-2214L		
CW3703-000	STXR40SC00-1008AI		
CW3752-000	TX40SC00-1204		
CW3753-000	4-1899777-7, TX40SC00-1206		
CW3754-000	STX40SC00-1008		
CW3755-000	TX40SC00-1207		
CW3881-000	STXR40AZ00-0810BI		
CW3882-000	STX40AZ00-0810		
CW3883-000	STXR40AZ00-1212BI		
CW3884-000	STX40AZ00-1212		
CW3886-000	STX40AZ00-1408		
CW3887-000	STXR40AZ00-0807BI		
CW3888-000	STX40AZ00-0807		
CW3889-000	STXR40AZ00-1210BI, STXR40AZ00-1210BI		
CW3903-000	TX40AZ00-2014		
CW3904-000	TX40AZ00-2412		
CW3909-000	TX40AZ00-2212		
CW4029-000	TXR40AB00-1808AIJ		
CW4030-000	TX40AB00-1808J		
CW4198-000	STX40SJ00-1210		
CW4590-000	TX40SC00-2220		
CW4634-000	STXR40AZ00-0806BI		
CW4635-000	STX40AZ00-0806		
CW4636-000	STXR40AZ00-1012BI		
CW4637-000	STX40AZ00-1012		
CW4642-000	TX40AZ00-1008		

CW4645-000	TX40AZ00-1804		
CW4866-000	TXR40AZ00-2212BI		
CW5264-000	TX40SJ00-1610H		
CW5351-000	STX40AC00-1614		
CW5399-000	STX40AC00-1616		
CW5400-000	STX40AC00-1416		
CW5469-000	TXR40BW00-1416AI		
CW5470-000	TX40BW00-1416		
CW5508-000	TX40BW00-1620		
CW5752-000	TX40AC00-1416		
CW6757-000	STX40SJ00-0808		
CW7084-000	TXR40AZ00-2407BI		
CW7085-000	TX40AZ00-2407		
CW9414-000	TX40AZ00-1810		
CX0393-000	TX40AZ00-1610		
CX0395-000	STX40AZ00-1210		
CX7097-000	TX40AU00-2420		
CX7424-000	TX40BW00-1207		
CX9353-000	TX40AZ00-2016		
CX9354-000	TXR40AC00-1207AIS		
CX9355-000	TX40AC00-1207S		
CX9356-000	TXR40AC00-1208AIS		
CX9357-000	TX40AC00-1208S		
CX9358-000	TXR40AC00-1407AIS		
CX9359-000	TX40AC00-1407S		
CX9360-000	TXR40AC00-1408AIS		
CX9361-000	TX40AC00-1408S		
CX9362-000	TXR40AC00-1607AIS		
CX9363-000	TX40AC00-1607S		
CX9364-000	TXR40AC00-1612AIS		
CX9365-000	TX40AC00-1612S		
CX9366-000	TXR40AC00-1810AIS		
CX9367-000	TX40AC00-1810S		
CX9368-000	TXR40AC00-2007AIS		
CX9369-000	TX40AC00-2007S		
CX9370-000	TXR40AC00-2010AIS		
CX9371-000	TX40AC00-2010S		
CX9372-000	TXR40AC00-2014AIS		
CX9373-000	TX40AC00-2014S		
CX9375-000	TX40AZ00-2414		
CX9376-000	TXR40AC00-2420AIS		
CX9377-000	TX40AC00-2420S		
CY0123-000	TX40SC00-1608		
CY0181-000	TXR40SC00-2210AI		
CY0182-000	TX40SC00-2210		
CY0364-000	TX40AZ00-1006		
CY1060-000	TXR40AC00-1216AI		
CY1061-000	TX40AC00-1216		
CY2326-000	TX40AZ00-1208		
CY6474-000	STXR40AB00-1410AI		
CY6475-000	STX40AB00-1410		
CY6655-000	TX40AB00-1206H		
CY6656-000	TX40AB00-1007H		
CY6657-000	TX40AB00-1006H		
CY6659-000	TX40AB00-2406H		
CY6851-000	TX40AB00-2409H		

CY6852-000	TX40AB00-1609H		
CY7547-000	TX40BW00-2010		
CY7548-000	TX40BW00-1407		
CY7549-000	TX40BW00-1006		
CY7550-000	TX40BW00-1408		
CZ0172-000	STXR40AB00-1007BI		
CZ1431-000	TX40SC00-1606		
CZ3764-000	TX40SC00-1212		
CZ3861-000	TX40AZ00-1007		
CZ3862-000	TX40AZ00-2218		
CZ3864-000	TX40AZ00-1612		
CZ4496-000	TX40AZ00-1206		
CZ4499-000	TX40AZ00-1410		
CZ4501-000	TX40AZ00-0804		
CZ6254-000	TX40AB00-2007H		
CZ6255-000	TX40AB00-0806H		
CZ6612-000	TX40AZ00-1004		
CZ6613-000	TX40AZ00-1606		
CZ6615-000	TX40AZ00-2008		
D03267-000	2-1201309-3, TXR40SJ00-2407AI		
D05646-000	8-1201058-4, TX40SJ00-1608		
D06259-000	2-1201877-0, STXR40AU00-1414BI		
D10113-000	4-1202046-1, STXR40AB00-1006BI		
D10462-000	1199662-9, TX40SJ00-1208		
D12336-000	4-1200497-6, TXR40AB00-1005AI2J		
D13022-000	5-1200577-8, TXR40AU00-1418BI		
D15358-000	5-1202086-6, TX40BB00-2016		
D16647-000	TXR40SJ00-2022AI2, 9-1899071-1		
D16791-000	9-1200476-1, TX40AB00-1818H		
D17719-000	TXR40AU00-2412AI		
D20423-000	1-1199662-0, TX40SJ00-2412		
D22277-000	5-1200813-5, STX40SC00-2020		
D23013-000	5-1200264-0, TX40AB00-1208V		
D25609-000	5-1200264-2, TX40AC00-2204		
D27518-000	6-1200416-9, TX40AB00-1820H		
D29422-000	9-1201408-0, TX40AB00-0812		
D32239-000	3-1200503-4, TXR40AU00-2018BI		
D35614-000	4-1200498-0, TX40AB00-2224H		
D36720-000	6-1201022-1, TX40SJ00-1812		
D39183-000	9-1201762-2, STXR40BW00-2218BI		
D41509-000	2-1200971-8, TX40AB00-2020H		
D42660-000	STXR40AU00-0805AI		
D46123-000	6-1201022-3, TX40SJ00-1405		
D47570-000	8-1200579-3, TXR40AU00-2408BI		
D50432-000	1-1200844-8, TX40AB00-2024H		
D51546-000	3-1200869-7, TX40AB00-1612H		
D54449-000	1201986-2, TXR40AB00-1220AI		
D55685-000	6-1200264-2, TX40AC00-1616		
D56660-000	5-1201309-0, TX40SJ00-2407		
D60466-000	6-1200264-3, TX40SJ00-1007V		
D60778-000	5-1202086-8, TX40BB00-2416		
D64149-000	7-1201144-8, TX40SJ00-1808		
D65072-000	9-1201257-1, TXR40SJ00-1210BI		
D66390-000	TX40AB00-1607AI		
D69099-000	2-1201858-4, STXR40AU00-1416BI		
D72333-000	5-1200503-8, TXR40SJ00-1007BI		

D73068-000	4-1199815-9, TXR40SC00-1005AI		
D74953-000	1-1200515-4, TXR40AU00-1206BI2		
D74963-000	3-1200302-0, TX40AB00-1608J		
D75695-000	1-1200076-9, TX40AB00-2008H		
D76190-000	5-1200498-9, TX40AB00-1618H		
D86784-000	2-1200356-9, TXR40AQ00-1208BI		
D90475-000	8-1200168-0, TX40AC00-1407		
D94834-000	8-1200345-4, STXR40AC00-2420BI		
D95689-000	8-1200168-2, TX40AC00-1622		
D96203-000	1-1201256-9, STXR40AU00-1016BI		
D99886-000	6-1201756-1, STXR40SJ00-1210BI		
E03717-000	8-1201311-8, TXR40SJ00-1806AI		
E05179-000	7-1201309-1, TXR40SJ00-2218BI		
E06155-000	STXR40AU00-0806AI, 4-1899110-8		
E06441-000	5-1202046-7, STX40AB00-2014		
E10812-000	5-1201192-4, TX40SJ00-1207		
E11036-000	1-1200543-8, TX40AB00-1416H		
E12362-000	2-1201342-1, TXR40SC00-1612BI		
E13126-000	5-1201224-7, TX40SJ00-2004		
E14679-000	9-1200434-6, TXR40AC00-1818AI		
E14777-000	9-1200579-8, TXR40AU00-2208BI		
E15605-000	1-1201258-7, TX40SJ00-2212		
E15706-000	7-1200262-7, TX40AB00-2407H		
E20560-000	8-1200262-2, TX40SB00-1207		
E21077-000	8-1201022-4, TX40SJ00-1204		
E22151-000	1200416-3, TX40AB00-1210H		
E22534-000	8-1201833-9, TXR40AU00-2210BI		
E23830-000	8-1201488-2, STX40AB00-1616		
E24676-000	7-1201224-8, TXR40SJ00-0807AI		
E25587-000	7-1201294-1, STX40AB00-2018		
E27266-000	3-1200844-6, TX40AB00-2218H		
E30519-000	1200163-2, TX40AB00-1414		
E30535-000	1-1199941-4, TX40SC00-1810		
E31253-000	TXR40SJ00-2024AI2, 9-1899071-2		
E34784-000	1-1200364-4, TX40AB00-2405H		
E34996-000	6-1202046-0, STX40AB00-1006		
E37033-000	STXR40AU00-0806BI		
E38504-000	3-1201442-2, TX40SJ00-0808		
E38853-000	4-1201402-9, STXR40AU00-0810BI		
E39922-000	TXR40AU00-2218AI		
E40833-000	1-1201143-9, TX40AB00-1212H		
E41951-000	TXR40AU00-2416AI		
E42098-000	1200809-4, TXR40AB00-2424BI		
E43122-000	9-1200262-1, TX40AB00-2222		
E43492-000	9-1200818-2, TXR40AB00-1620BI		
E47329-000	5-1201076-1, STXR40AU00-1014BI		
E50616-000	3-1201258-1, TXR40SJ00-1816BI		
E51022-000	5-1200748-2, TXR40AU00-1012BI		
E51094-000	8-1200441-8, STXR40AB00-0807BI		
E52109-000	6-1201192-6, TXR40SJ00-1214BI		
E56247-000	9-1200496-2, TXR40AB00-1807AI2J		
E56977-000	TX40AB00-1208J		
E56982-000	1-1201312-8, TXR40SJ00-1806BI		
E60541-000	3-1200273-3, TXR40AC00-2212AI2		
E60810-000	2-1201059-6, TX40SJ00-1008		
E61834-000	6-1201795-0, TXR40AB00-2422AI		

E64076-000	STXR40AU00-1416AI		
E64620-000	2-1201059-8, TX40SJ00-2210		
E64702-000	9-1200441-4, STXR40AC00-2210BI		
E65731-000	9-1200168-8, TX40AB00-2404		
E65733-000	7-1199862-5, TXR40AB00-1805AI2		
E65775-000	1200263-3, TX40AB00-2424		
E67325-000	9-1201188-8, STXR40AU00-1216BI		
E70569-000	3-1199662-5, TX40SJ00-0805		
E70861-000	5-1201014-0, TX40SJ00-2408		
E72051-000	4-1200995-3, TXR40AU00-2206BI		
E72069-000	9-1200441-9, STXR40AB00-1818BI		
E72192-000	1200499-8, TX40AB00-2428H		
E73202-000	6-1201756-6, STXR40SJ00-1008BI		
E73689-000	6-1200548-0, STXR40AB00-1618BI		
E74691-000	1-1201099-9, TX40SJ00-1404		
E77044-000	TXR40SJ00-2020AI2, 9-1899071-0		
E77241-000	2-1200364-6, TX40AB00-2016H		
E77690-000	6-1201828-9, TX40AB00-1016H		
E80544-000	1200169-6, TX40AC00-1005		
E80859-000	2-1200522-7, TXR40AB00-1605AI2J		
E82460-000	6-1201969-1, TXR40AU00-1614AI		
E84784-000	3-1200366-8, TX40AB00-2208H		
E85725-000	1-1200169-1, TX40AC00-2422		
E87285-000	5-1201014-5, TX40SJ00-2016		
E93680-000	3-1201059-2, TXR40SJ00-1008BI		
EF4710-000	TX40AZ00-2012		
EF6868-000	STXR40AZ00-1614BI		
EF6869-000	STX40AZ00-1614		
EF6875-000	TX40BW00-1405		
EF8347-000	TXR40AZ00-1418BI		
EF8350-000	TXR40AZ00-1420BI		
EF9133-000	TXR40AZ00-1007AI2		
EF9134-000	TXR40AZ00-1012BI		
EF9135-000	TXR40AZ00-1014BI		
EF9136-000	TXR40AZ00-1016BI		
EF9138-000	TXR40AZ00-1216BI		
EF9140-000	TXR40AZ00-1416BI		
EF9141-000	TXR40AZ00-1422BI		
EF9142-000	TXR40AZ00-1618BI		
EF9143-000	TXR40AZ00-1818BI		
EF9144-000	TXR40AZ00-1820BI		
EF9145-000	TXR40AZ00-1824BI		
EF9287-000	TX40AZ00-0812		
EF9288-000	TX40AZ00-0808		
EF9395-000	TXR40AZ00-2006BI		
EF9400-000	TXR40AZ00-2222BI		
EG0014-000	TXR40AZ00-2220BI		
EG0456-000	TX40BW00-2410		
EG0819-000	TX40AZ00-1212		
EG1388-000	STXR40AZ00-0814BI		
EG1389-000	STX40AZ00-0814		
EG1390-000	STXR40AZ00-1014BI		
EG1391-000	STX40AZ00-1014		
EG1433-000	TX40BW00-1410		
EG1434-000	TX40BW00-1414		
EG1435-000	TX40BW00-1618		

EG1673-000	TX40AZ00-1806		
EG1941-000	TXR40AZ00-2224BI		
EG2011-000	STX40AZ00-1018		
EG2057-000	TXR40AC00-2006AI		
EG2058-000	TX40AC00-2006		
EG2234-000	TXR40AC00-0818AI		
EG2235-000	TX40AZ00-1016		
EG2243-000	TX40AZ00-1214		
EG2246-000	TXR40AB00-1610BIJ		
EG2249-000	STX40AZ00-1016		
EG3261-000	TXR40AZ00-0818BI		
EG3506-000	STXR40AC00-1418BI		
EG3507-000	STX40AC00-1418		
EG4773-000	STXR40AZ00-1010AI		
EG4774-000	STXR40AZ00-1212AI		
EG4775-000	STXR40AZ00-1414BI		
EG4776-000	STXR40AZ00-1816AI		
EG4777-000	STXR40AZ00-1818AI		
EG5103-000	STXR40AB00-2222AI		
EG5566-000	STXR40AZ00-0812BI		
EG5567-000	STX40AZ00-0812		
EG5674-000	STXR40AB00-1014AI		
EG6461-000	TX40AB00-0804J		
EG6463-000	TXR40AB00-1410BIJ		
EG6468-000	TXR40AB00-2218BIJ		
EG7241-000	TXR40AB00-1814BIJ		
EG7245-000	TXR40AB00-0804BIJ		
EG7655-000	STXR40AB00-0812AI		
EG8423-000	STXR40BW00-0808AI		
EH1699-000	TXR40SC00-1816BI		
EH2558-000	TXR40AB00-1014BI		
EH8414-000	STXR40SJ00-0807AI		
EJ0956-000	STXR40BW00-0807AI		
EJ2001-000	STX40AZ00-1414		
EJ3154-000	STXR40BW00-1616AI		
EK1839-000	STXR40AZ00-0805BI		
EK2088-000	TXR40AB00-2416BIJ		
EK5767-000	TX40BW00-1612		
EK7486-000	TX40AU00-0806		
EK9353-000	STXR40AZ00-0805AI		
EK9354-000	STXR40AZ00-0807AI		
EK9355-000	STXR40AZ00-0810AI		
EK9356-000	STXR40AZ00-1012AI		
EK9357-000	STXR40AZ00-1614AI		
EK9358-000	STXR40AZ00-1814AI-OBS, STXR40AZ00-1814AI		
EL4368-000	STXR40AZ00-1414AI		
EL4369-000	STXR40AZ00-1418AI		
EL4370-000	STXR40AZ00-2018AI		
EL4371-000	STXR40AZ00-2022AI		
EL4401-000	STXR40AZ00-1412AI		
EL4402-000	STXR40AZ00-1416BI		
EL6109-000	STXR40AZ00-2020BI		
EL6110-000	STXR40AZ00-2422AI		
EL6119-000	STXR40AZ00-0808AI		
EL7613-000	STX40SC00-1816		
EM0361-000	STXR40AZ00-1412BI		

EM0362-000	STXR40AZ00-1824AI		
EM0896-000	TX40AC00-0804L		
EM1496-000	STX40AB00-2222		
EM3293-000	STXR40BW00-1414AI		
EM4409-000	TXR40AN00-0804AI		
EM4410-000	TX40AN00-0804		
EM4800-000	TXR40AB00-1805AIJ		
EM4854-000	STX40AC00-0807		
EM4855-000	STX40AC00-1008		
EM4856-000	STX40AC00-1010		
EM4857-000	STX40AC00-1412		
EM5192-000	STXR40BW00-1418AI		
EM5232-000	STXR40BW00-2222AI		
EM6142-000	STX40AB00-1012		
EM6453-000	STXR40BW00-1420AI		
EM7229-000	TX40BW00-1810		
EM8058-000	TX40AB00-1422		
EP4264-000	TX40AZ00-2020		
EP6149-000	TX40AB00-1210J		
EP7835-000	TX40AB00-2024		
EP8837-000	TX40BW00-2412		
EP8838-000	STX40BW00-0805		
EP8839-000	STX40BW00-1008		
EP8840-000	STX40BW00-1210		
EP8841-000	STX40BW00-1212		
EP8842-000	STX40BW00-1412		
F00649-000	1-1200169-6, TX40AB00-1618		
F01921-000	4-1200362-8, TX40AB00-1408H		
F03319-000	1-1201197-4, STXR40AU00-1210BI		
F04001-000	3-1200522-6, TX40AB00-2212H		
F11862-000	3-1200522-8, TX40AB00-1605J		
F13394-000	9-1200588-2, TXR40AU00-1414BI2		
F14415-000	4-1200808-9, STX40SC00-2424		
F15862-000	2-1200263-2, TX40SB00-1610		
F22891-000	3-1201267-7, TX40SJ00-1412		
F23228-000	7-1200027-3, TX40AB00-2418H		
F25941-000	6-1200543-0, TX40AB00-1810J		
F27092-000	9-1200550-9, TXR40AB00-0807BI		
F27620-000	1-1201834-8, STXR40AU00-1214BI		
F29128-000	6-1202086-4, TXR40BB00-1408AI		
F30601-000	4-1200273-7, TX40AC00-1605		
F31645-000	STXR40BW00-2422AI		
F33650-000	1201364-1, TXR40BW00-1612CI		
F41449-000	1-1201023-8, TX40SJ00-1005		
F43384-000	6-1201014-6, TX40SJ00-2216		
F45982-000	1-1201023-9, TX40SJ00-2416		
F48921-000	TXR40AU00-2216AI		
F49008-000	TXR40AU00-1012AI		
F52183-000	TXR40AU00-1810AI		
F59062-000	STXR40AU00-0812BI		
F60636-000	1-1200262-1, TX40AB00-1608H		
F65123-000	7-1201756-0, TXR40SJ00-1607BI		
F67064-000	9-1200882-9, TXR40AB00-2018H		
F67086-000	4-1201201-0, TX40AB00-1814H		
F68760-000	3-1201403-9, TXR40AU00-2224BI		
F69513-000	STXR40BW00-2020AI		

F70619-000	7-1200474-2, TX40AB00-1208H		
F73234-000	1-1200262-7, TX40SC00-1004		
F74467-000	3-1200498-1, TX40AB00-1807J		
F75852-000	8-1200133-2, TX40AB00-2012H		
F80362-000	8-1201409-3, TXR40AB00-0812BI		
F80639-000	5-1200343-1, TX40SJ00-2414		
F81893-000	7-1200843-1, TX40AB00-1008H		
F81948-000	8-1200815-8, TX40AB00-1818		
F83814-000	8-1201655-3, STXR40AU00-1614BI		
F84581-000	7-1200995-6, TXR40AU00-2416BI		
F85809-000	5-1199662-6, TX40SJ00-1210		
F86200-000	4-1201834-1, TX40AB00-1012H		
F86646-000	3-1200514-0, TXR40AU00-1614BI		
F94576-000	9-1200497-9, TX40AB00-1005J		
F99908-000	4-1201827-3, TXR40SJ00-1616AI2		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by Accuris based on content provided by TE Connectivity.

Copyright TE Connectivity Corporation