Product Change Notification

Current Date: 07-Jul-2025

TE Connectivity

Product Change Notification: PCN-25-249416 **PCN Date:** 03-JUL-25

Customer: TTI Inc (1305175) **Location:** Maisach-gernlinden **Agreement:** TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
RECEPTACLE ASSEMBLY 5H TYPE (0.5MM BOSS LENGTH) FOR 0.8FH ON TAPING

General Description of Changes
Drafting Error.

Reason for Changes:
Un Reeling Direction mentioned in the drawing was wrong, updated the drawing with proper Un Reeling Direction.

PCN Attributes:	
Product Category:	**Kind of Change:**
Connectors	Drawing
Change Feature:	**Potential Customer Impact:**
Drawing Change	
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Ship Date of Changed Items** (Changed Parts Only):
	09-JUL-2025
Last Ship Date of Changed Items (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	**Date of First Samples:**

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Note: This PCN contains only document changes, these changes do not affect the form, fit or function of the parts referenced.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Affected Revision
5177985	5177985-1	TYC5177985-1	R6