08-Feb-2012
PCN #:E-11-024333

Subject:250 & 312 SERIES FASTON RECEPTACLE

Description of Change: In an effort to standardize manufacturing practices, TE Connectivity has completed a review of our current tin plating thickness standards on FASTON Receptacles. This review has resulted in our decision to reduce the tin plating thickness on selected part numbers from the current requirement to 40 micro inches minimum. Other than thickness, no change is being made to the tin plating specification. It is also important to note that TE Connectivity offers several other industry accepted product families that have plating thicknesses in the 20-40 microinch range.

Reason: Product improvement. Cost reduction

Impact of Change:form - fit - function

Key Dates:
Contact By Date:29-Mar-2012
Implementation Date:29-Mar-2012

Product Affected

170092-2
170032-4
170083-2
170032-5
170089-2
170213-5
170183-2
(Alias Part Numbers:
"0-0170183-2")
170092-4
170032-6

Product Affected

170384-2
170046-2
170096-2
170342-2
170046-4
170191-3
170031-2
170258-2
60873-1
61187-1
170224-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.

Copyright Tyco Electronics Corporation