

## Product Change Notification

[Home](#)

The information below reflects a change that is being implemented.

Notice Date: 07/15/2002  
Product Category: MPLAB  
Notification Subject: MPLAB v5.70 Released  
Notification Body:

MPLAB v5.70 is released to the Microchip web site at  
<http://www.microchip.com/1010/pline/tools/picmicro/devenv/mplabi/mplab5x/index.htm>

MPLAB v5.70 will be included software with all shipped development systems. MPLAB v5.62 is moved to the archival portion of the Microchip web site.

For more information on the individual component changes, the README files for all MPLAB components are also available for separate download.

This release formalizes full support for the MPLAB ICE 2000 Processor modules listed here:

PCM16XR0/R1  
PIC16F870 PIC16F871  
PCM16XS0/S1/S2  
PIC16F73 PIC16F76  
PIC16F74 PIC16F77  
PIC16F72 (S2 only)  
PCM16XW0  
PIC16C781 PIC16C782  
PCM18XC0/C1  
PIC18F242 PIC18F252  
PIC18F442 PIC18F452  
PCM18XD0  
PIC18F248 PIC18F258  
PIC18F448 PIC18F458

PRO MATE II support is extended to cover these parts:

PIC16F873A PIC16F874A  
PIC16F876A PIC16F877A  
PIC18F6620 PIC18F6720  
PIC18F8620 PIC18F8720

MPLAB SIM, MPASM, and MPLINK now support these parts:

PIC12F629 PIC12F675

-----  
Tools and Version Numbers for MPLAB v5.70  
-----

Dev. Version - SW Version - FW  
Tool (Software DLL) (Operating System)  
-----

MPLAB(R) IDE 5.70  
MPASM(tm) Assembler 3.20  
MPLINK(tm) Object Linker 3.10  
MPLIB(tm) Object Librarian 3.10  
MPLAB SIM Simulator 7.70  
MPLAB ICE In-Circuit Emulator 2.60

PICMASTER(R) Emulator 3.45  
MPLAB ICD In-Circuit Debugger 1.44 2.31  
MPLAB ICD 2 In-Circuit Debugger 1.02 1.02  
PICSTART(R) Plus Programmer 2.60 3.00  
PRO MATE(R) II Device Programmer 5.80 5.80  
PROCMD 1.60

Close