

Product/Process Change Notifications



PCN - 21 102

Amphenol Information Communication and Commercial Products Group
www.amphenol-icc.com

Release Date: September 07 2021

Product Name:	HPL 563 - AIRMAX VS	
	AIRMAX	
Product Manager:	Chris Liu	
Subject:	Notification of Planned Change	
Distribution:	Affected customers	
Type of Change:	Location Change	
Change Description:	<p>Amphenol is transferring our existing Airmax VS production in Senai, Malaysia to our factory in Dongguan China. For the VS vertical receptacle series , products will transfer "as is" to Dongguan. For any right angle headers and receptacles or vertical headers, Amphenol plans to migrate customers to VS2 series, which is a backwards compatible, higher performing product. We will support that transfer at the same cost you pay today. For any demand of VS right angle headers and receptacles or vertical headers that remain in VS series after Feb 2022, production prices will increase 6% on shipments to cover the additional production related costs. This transfer to complete by 2022 Feb.</p>	
Reason for Change:	<p>Given the decline in global demand for Airmax coupled with rising production costs, Amphenol is transferring our existing Airmax production in Senai, Malaysia to our factory in Dongguan China. Dongguan is the primary production site for Airmax globally and is a vertically integrated, world class production facility. In addition to Airmax, Dongguan also produces ExaMAX, ExaMEZZ and the XCede HD family of backplane products.</p>	
Affected Parts:	Refer affected PN list	
Effective Date of Change:	26 February ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	Yes	
Qual/Test Data Attached?	No	
Samples Availability Date:	15 October ,2021	
Available Alternatives?		
Questions?	<i>Contact your local AICC Representative, or Product Manager</i>	
	<i>Chris Liu / Product Manager</i>	
	<i>Chris.Liu@fci.com</i>	

Note:
 Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date	Last Disty Return date	Last Shipment date	Alternative Parts	Product Family	Primary MU	Product Manager	Status
PCN21102	10016527-101LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10016527-111LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10016535-001	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10016537-101LF	LOCATION CHANGE	February 26, 2022				563-5GUF-5 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10025613-101LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10025613-111LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10028264-101LF	LOCATION CHANGE	February 26, 2022				563-5JJF-4 PAIR VERT RECEP	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10028436-101LF	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10028436-111	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	MEMO
PCN21102	10028436-111LF	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10029391-101LF	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10029391-111	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	MEMO
PCN21102	10029391-111LF	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034249-101LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034249-111LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034249-501LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034251-101LF	LOCATION CHANGE	February 26, 2022				563-5G1F-3 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034264-101LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034264-111LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034475-101	LOCATION CHANGE	February 26, 2022				563-5JBF-5 PAIR RA RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10034475-101LF	LOCATION CHANGE	February 26, 2022				563-5JBF-5 PAIR RA RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10035754-101	LOCATION CHANGE	February 26, 2022				563-5JEF-4 PAIR RA RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	MEMO
PCN21102	10035754-101LF	LOCATION CHANGE	February 26, 2022				563-5JEF-4 PAIR RA RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10039850-101	LOCATION CHANGE	February 26, 2022				563-5G1F-3 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10039850-101LF	LOCATION CHANGE	February 26, 2022				563-5G1F-3 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10039851-101LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10039851-111LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10040862-101LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10040862-111LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10040993-101LF	LOCATION CHANGE	February 26, 2022				563-5GUF-5 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10041460-101LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10041746-101LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10043546-101LF	LOCATION CHANGE	February 26, 2022				563-5G1F-3 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045073-101	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045073-101LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045074-101LF	LOCATION CHANGE	February 26, 2022				563-5JIF-5 PAIR RA HEADERS	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045266-101LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045266-111LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	MEMO
PCN21102	10045267-101LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045267-111LF	LOCATION CHANGE	February 26, 2022				563-5GZF-3 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045271-101LF	LOCATION CHANGE	February 26, 2022				563-5G1F-3 PAIR VERT RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10045548-101LF	LOCATION CHANGE	February 26, 2022				563-5JBF-5 PAIR RA RECEPTACLE	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10052824-101LF	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	ACTIVE
PCN21102	10052824-111	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	MEMO
PCN21102	10052824-111LF	LOCATION CHANGE	February 26, 2022				563-5GTF-4 PAIR RA HEADER	4340-47400	CHRIS.LIU@FCI.COM	PRE-PRODUCTION

