

Product Name:	569 - D-SUB	
	Solder bucket, Straight and Right angled Version 09-37 Position connector	
Product Manager:	Renish Baby	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Packaging change	
Change Description:	Packaging changed from Honeycomb to Tray with packing quantity change. MOQ, MPQ details are modified, as shown in the Affected parts.xls file.	
Reason for Change:	For improvement of the quality of packaging.	
Affected Parts:	Refer attached sheet1	
Effective Date of Change:	01 August ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	NA	
Qual/Test Data Attached?	NA	
Samples Availability Date:	01 August ,2022	
Available Alternatives?		
Questions?	<i>Contact your local Amphenol Representative, or Product Manager</i>	
	<i>Renish Baby / Product Manager</i>	
	<i>Renish.Baby@fci.com</i>	

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN22087	DBP25P364LORLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBP25P364TXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBP25P364TXLORLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBP25S364LORLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBP25S364TLORLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBPO25P365GTXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBPO25S365GTLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBPV25S365GTLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DCP37S384LORLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	865609PLTX205LF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	865609SLT205LF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	8656L09SLTLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	8656F15SLTLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DEPO09P565MTXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DEO09S564GTXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DEO09S564GTLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DEPL09S564GTLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBT25S564TXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DBPO25P865MTXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE
PCN22087	DC37P564MTXLF	PACKAGING CHANGE	AUGUST 1, 2022					4950-49500	RENISH.BABY@FCI.COM	ACTIVE


Engineering Change Notification

ACPI

PRODUCTS: D-SUB solder bucket, Straight and Right angle Version (09-37 Posn.) Packaging change to Tray

Site CCB No./Global PCN No.-

Before Change



After Change



- Description of Change.**
- Honey comb packaging to be replaced by Tray packaging
 - MOQ and MPQ also modified

Implementation of Change. 01-08-2022