

Product/Process Change Notifications

PCN - 17 021



Release Date: April 26 2017

Product Name:	Millipacs		
	Millipacs 5 Row Right Angle Header		
Product Manager:	Verghese John		
Subject:	Notification of Planned Change		
Distribution:	Global		
Type of Change:	Design Change		
Change Description:	Removal of End Ribs in Millipacs Right Angle Header Connector		
Reason for Change:	Continuous improvement in product to avoid possibility of rib breakage. Functionally this rib does not have any impact on the product		
Affected Parts:	See attached affected parts list		
Effective Date of Change:	July 31, 2017		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	No		
Qual/Test Data Attached?	No		
Samples Availability Date:	July	31	2017
Available Alternatives?	Select		
Questions?	<i>Contact your local AFCI Representative, or Product Manager</i>		
	<i>Verghese John</i>		
	<i>Tel: +91 484 4090814 / email: verghese.john@fci.com</i>		

Note:

Customers should contact Product Manager (or their local AFCI Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .



MILLIPACS RIGHT ANGLE HDR CONNECTORS

DESIGN CHANGE

25-MARCH-2017


Amphenol
FCi

MILLIPACS RIGHT ANGLE HEADER CONNECTORS

TYPE- B&C :- PART NUMBER STARTING WITH HM2J08, HM2J70, HM2J71, HM2J09

BEFORE

AFTER




These thin End ribs will be removed. This will not affect the functionality of the connector in any way

MILLIPACS RIGHT ANGLE HEADERS


TYPE- A&AB CONNECTORS :- PART NUMBER STARTING WITH HM2J07,HM2J65&HM2J66

This area will be changed liked this, since this rib does not have any impact on the functionality of the connector

BEFORE



AFTER



These thin End ribs will be removed. This will not affect the functionality of the connector in any way