

## Product/Process Change Notifications



# PCN - 18 076

Amphenol Information Communication and Commercial Products Group  
[www.amphenol-icc.com](http://www.amphenol-icc.com)

Release Date: October 24 2018

<b>Product Name:</b>	Millipacs		
	Millipacs Standard Header Stub Connectors		
<b>Product Manager:</b>	Jithin George		
<b>Subject:</b>	Notification of Change with Immediate Effectivity		
<b>Distribution:</b>	Affected Customers		
<b>Type of Change:</b>	Design Change		
<b>Change Description:</b>	Millipacs Header Contacts retention design changed from Single Dimple to Double Dimple Design		
<b>Reason for Change:</b>	To increase the product robustness		
<b>Affected Parts:</b>	See attached Affected parts.xls file		
<b>Effective Date of Change:</b>	November 30, 2018		
<b>Last Time Buy Date:</b>	NA		
<b>Last Disty Return Date:</b>	NA		
<b>Last Time Shipment Date</b>	NA		
<b>Datasheet Attached?</b>	No		
<b>Qual/Test Data Attached?</b>	NA		
<b>Samples Availability Date:</b>	November	27	2018
<b>Available Alternatives?</b>	Select		
<b>Questions?</b>	<i>Contact your local AICC Representative, or Product Manager</i>		
	<i>Jithin George / Product Manager</i>		
	<i>91 9967592316 / Jithin.George@fci.com</i>		

Note:  
 Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN.  
 Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .



























PCN18076	HM2PN1PKR2W5GF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2PN3PDP291N9	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2A31PG60J0N9LF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P08PMK385GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P08PMK395GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P08PMK3A5GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P08PMK3C5GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P11PDE121N9LF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P65PKG184GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P87PD111N9LF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P88PMJ1K5GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P95PMJ1J5GFLLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P66PDE121N9LLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P66PDE125N9LLF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P68PKF2U5GF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P68PKF2U9GF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2PC1500PE9REPAIR	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2PN3PDP11N5N9	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P66PDH321N9LF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P66PDH325N9LF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P95PDJ1H0N9LF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P07PKJ3A1GF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P70PK51J1GF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>
PCN18076	HM2P71PK51J1GF	DESIGN CHANGE	November 30, 2018			560-5HQF-MILLIPACS STRAIGHT HEADER SIGNAL	4950-49500	<a href="mailto:JITHIN.GEORGE@FCI.COM">JITHIN.GEORGE@FCI.COM</a>



# Millipacs Header

## Double Dimple

Single Dimple

Double Dimple

