


Product/Process Change Notifications



PCN - 18 100

Amphenol Information Communication and Commercial Products Group
www.amphenol-icc.com

Release Date: November 28 2018

Product Name:	Millipacs			
	Millipacs 5 Row Receptacle			
Product Manager:	Jithin George			
Subject:	Notification of Change with Immediate Effectivity			
Distribution:	VariousCustomers			
Type of Change:	Packaging Change			
Change Description:	Packing Lid design optimised for better gripping of Connector			
	Existing Lid Modified Lid 			
Reason for Change:	Packaging Improvement			
Affected Parts:	See attached Affected parts.xls file			
Effective Date of Change:	December 15, 2018		Note: Change over in phased manner till diluting existing stock with no mix up in supply lots.	
Last Time Buy Date:	NA			
Last Disty Return Date:	NA			
Last Time Shipment Date	NA			
Datasheet Attached?	Yes			
Qual/Test Data Attached?	NA			
Samples Availability Date:	November	28	2018	
Available Alternatives?	Select			
Questions?	Contact your local AICC Representative, or Product Manager			
	Jithin George / Product Manager			
	91 9967592316 / Jithin.George@fci.com			

Note:

Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN.
 Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date	Last Disty Return date	Last Shipment date	Alternative Parts	Product Family	Primary MU	Product Manager	Status
PCN18100	HM2R01PA5100AALF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5100L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5100N9JLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5101N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5101N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5102N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5104N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5108N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA510JN9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PACA39N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R01PA5100E9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PA5101Z1LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PA5108L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PA5108Z1LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PA5500N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PA5600N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PACA35N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PE5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R01PA5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R01PA5108N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R01PA510FN9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R02PA5100AALF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5100E9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5100L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5100N9JLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5101AALF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5101E9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5101L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5101N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5101N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5104N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5107N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5108L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5108N9JLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5108N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5109N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA510FN9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA510JN9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PACA10N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PE5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PE5108N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R02PA5101Z1LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R02PA5108E9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R02PA5400N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R02PA5100N9CLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R02PA5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R02PA5108N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R02PA5101N9	PACKAGING CHANGE	December 15, 2018				REMOVED FROM GPS	-	UNASSIGNED	TO BE REMOVED
PCN18100	HM2R03PA5100AALF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5100L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5101AALF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5101N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5104N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5108L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5108N9STLF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA510FAALF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA510FN9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA510JN9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R03PA5100E9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R03PACA20N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R03PE5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	MEMO
PCN18100	HM2R03PA5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R03PA5101N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R03PA5108N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	SMARTER SERVICE
PCN18100	HM2R03PA5101N9	PACKAGING CHANGE	December 15, 2018				REMOVED FROM GPS	-	UNASSIGNED	TO BE REMOVED
PCN18100	HM2R05PA5100L9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R05PA5100N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R05PA5101N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R05PA5108N9LF	PACKAGING CHANGE	December 15, 2018				560-5HRF-MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN18100	HM2R06P1LF	PACKAGING CHANGE	December 15, 2018				560-5HVF-MILLIPACS ACCESSORIES	4950-49500	JITHIN.GEORGE@FCI.COM	ACTIVE

[illegible]

[illegible]

MPACS Std Receptacle Packaging

FCi Basics

Lid Design Change (BLISTERDEKHM2R-10150280-02-101)

