

Product/Process Change Notifications



PCN - 19 034 R1

Amphenol Information Communication and Commercial Products Group
www.amphenol-icc.com

Release Date: May 20 2019

Product Name:	Minitek PWR		
	HPL 514 with 2.5, 3.0, 4.2, 5.7 pitch connectors		
Product Manager:	Jithin George		
Subject:	Notification of Planned Change		
Distribution:	Affected Customers		
Type of Change:	Location Change		
Change Description:	To support growing demand, we are making AICC Cochin Site as the Primary site for the attached list of part numbers. Parts not listed and cable assemblies will be catered by AICC Nantong Site.		
Reason for Change:	With the consolidation of product line related activities in a single site, we can offer good service levels and most optimum product solutions		
Affected Parts:	See Affected parts.xls file		
Effective Date of Change:	July 31, 2019	<i>Note: Revision R1 for original PCN19034 dtd 24th April 2019 issued for following updates.</i> <u>Affected Parts.xls file</u> - Number of parts reduced from 1636 to 1608, with some parts are retained at Amphenol ICC Nantong site for local support. <u>Effective date</u> changed from June 15, 2019 to July 31, 2019	
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	No		
Qual/Test Data Attached?	No		
Samples Availability Date:	July	31	2019
Available Alternatives?	Select		
Questions?	Contact your local AFCI Representative, or Product Manager		
	Jithin George		
	+91 484 4090813 Jithin.George@fci.com		

Note:

Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

[illegible]

PCN19034R1	10127721-223GLF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10127721-243LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	ACTIVE
PCN19034R1	10136656-0331LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45430	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136656-0531LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136656-0631LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136656-0931LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0221TLF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0241LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0242LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0321TLF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0542LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0631LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136654-0632LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136655-0231LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136655-0642LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137867-0331LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137867-0341LF	LOCATION CHANGE	31-Jul-19				514-5U3F-MINITEK PWR3.0 HEADER	4543-45430	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-03121LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-03221LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-04121LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-04221LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-04424LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-05121LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-05221LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10137784-05424LF	LOCATION CHANGE	31-Jul-19				514-5UAF-MINITEK PWR4.2 HCC HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-03121LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-031231LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-03221LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-04121LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-04221LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-05121LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-051231LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45431	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10136646-05221LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45481	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10127720-043LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45432	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10127720-063LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45482	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10131318-06512GR1F	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45433	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10131318-08212G0LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45483	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10127819-04411LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45434	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10127819-14411PLF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45484	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10122956-BC1001U	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45435	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10122956-H100002U	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45485	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10122956-H10002U	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45436	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10127815-061LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45486	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10143250-132LF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4543-45437	JITHIN.GEORGE@FCI.COM	MEMO
PCN19034R1	10147820-06211PLF	LOCATION CHANGE	31-Jul-19				514-5U0F-MINITEK PWR4.2 HEADER	4548-45487	JITHIN.GEORGE@FCI.COM	MEMO
	1608									