



30-Nov-2010

PCN #:P-10-003660

Subject:semi automatic machine launch 12 position SSC

Description of Change: Replace outdated machine to increase productivity and reduce downtime of parts to customer. Semi-Automatic machine will have all the inline checks that the initial machine had.

Reason: Unavailability of obsoleted machine parts on 12 position Sealed Sensor Machine. Downtime will be reduced and delivery time should improve due to age of machine. Capability studies and PPAP documentation will be available, upon request, by customers affected by this change. Please contact your Tyco Electronics SE for further details regarding level of PPAP documentation.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:13-Dec-2010

Implementation Date:13-Dec-2010

Product Affected

184291-1

184115-1

184056-1

184286-1

184097-1

184414-1

184455-1

184099-1

The dates on the product change notification (PCN) are best estimate dates

determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.