



29-Mar-2011

**PCN #:**E-11-005557

**Subject:**Housing CST-100 and MTA-100 header

**Description of Change:** fill in pocket

**Reason:** Product improvement. Header is cracking and by filling in the void the cracking is eliminated.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**30-Jun-2011

**Implementation Date:**30-Jun-2011

**Product Affected**

- 3-644893-4
- 3-644729-4
- 3-644893-3
- 2-647421-8
- 3-644893-6
- 4-644893-3
- 3-644898-6
- 3-647068-5
- 3-1744079-3
- 3-644730-4
- 3-644898-3
- 3-647543-3
- 3-644898-2
- 4-644898-0
- 3-1744078-8
- 3-644893-2

**Product Affected**

644898-2

644893-5

644893-4

644893-3

644893-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the

Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.