


Product Change Notification

TRANSFORMERS





September, 2016

Change to Manufacturing Process for Select LAN Transformers

Bourns is making changes to the manufacturing process for the LAN transformer part numbers PT51374CEL, PT61020EL, PT61022XEL, PT76787PEL, SM13043EL, SM13066EL, SM51295PEL, SM51607EL and SM51612EL. The center tabs of the transformer coils will be insulated with epoxy resin to reduce the chance of electrical shorting. For your convenience, Table 1 shows the change.

The form of the transformer will be changing while the fit remains unchanged. The function, quality and reliability of the transformer should be enhanced.

Table 1

Part Number	Coil Center Tab	
	Current	Revised
PT51374CEL	Uninsulated Coil Center Tab 	Insulated Coil Center Tab 
PT61020EL		
PT61022XEL		
PT76787PEL		
SM13043EL		
SM13066EL		
SM51295PEL		
SM51607EL		
SM51612EL		


Implementation dates are as follows:

*Date that manufacturing of existing products will cease: **March 11, 2017***

*Date that deliveries of modified products will begin: **March 12, 2017***

*First date code using the above changes: **1711***

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

Table 1		
Coil Center Tab		
Part Number	<i>Current</i>	<i>Revised</i>
PT51374CEL PT61020EL PT61022XEL PT76787PEL SM13043EL SM13066EL SM51295PEL SM51607EL SM51612EL	Uninsulated coil center tab 	Insulated coil center tab 