




PRODUCT CHANGE NOTIFICATION

MAGNETICS



Bourns® Model PAD001/002, PLN060/071, PS13002, PT131xxL, PT610xxPEL, PT76787PEL, SM13xxxEL/XEL/CEL/PEL, SM51xxxPEL/EL and SM75xxxPEL Series SMD Transformers

Manufacturing Site Relocation

Riverside, California – January 10, 2024 – Bourns has learned that a certain Bourns' sub-supplier was added to the Uyghur Forced Labor Prevention Act Entity List (the "UFLPA List") by the United States Department of Homeland Security ("DHS").

This sub-supplier is contesting its inclusion on the UFLPA List and is working with its legal team to provide required documentation for removal from the UFLPA List.

Before the US Uyghur Forced Labor Prevention Act came into effect on June 21, 2022, Bourns did its due diligence in investigating and documenting compliance of its supply chain. Bourns has a signed certificate from the affected sub-supplier to support prior purchases. Bourns had also dispatched its audit team to the sub-supplier's plant to audit labor used in manufacturing to make sure that no persecuted ethnic minority employees were employed on conditions supporting finding of forced labor.

In compliance with United States and other applicable laws and keeping with Bourns' Code of Ethics and Conduct, Bourns immediately stopped all purchases from the sub-supplier and all shipments of Bourns® products containing materials from this sub-supplier.

To minimize production disruption for our customers due to this sub-supplier related stop purchase and stop ship, effective January 22, 2024, the manufacturing site for the [Bourns® Model PAD001/002, PS13005, PT131xxL, PT610xxPEL, PT76787PEL, SM13xxxEL/XEL/CEL/PEL, SM51xxxPEL/EL and SM75xxxPEL Series SMD Transformers](#) will be relocated to another manufacturing facility.

A list of affected part numbers is included on the following page.

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC24003

Affected Part Numbers		
PAD001-T764117S	PT61018PEL	SM13126PEL
PAD001-T764120S	PT61020EL	SM13139EL
PAD002-T764111S	PT61021XEL-5	SM13142EL
PAD002-T764113S	PT61022XEL	SM13143EL
PS13005	PT76787PEL	SM51589PEL
PT13113L	SM13043EL	SM51594EL
PT13124L	SM13047XCEL	SM51607EL
PT13141L	SM13064EL	SM51612EL
PT13144L	SM13077XEL	SM51625EL
PT61017PEL	SM13086CEL	SM75056PEL
PT61017XPEL	SM13112EL	SM75057PEL
PT61017XPEL-1	SM13117EL	SM75858PEL

There will be no product design changes as a result of the manufacturing site relocation.

The affected part numbers produced at the new manufacturing location will meet the same data sheet specifications.

The form, fit, function, quality, reliability and country of origin of the affected parts as standalone components will remain the same.

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance in customers' applications.

Traceability will be maintained through lot code and date code.

Implementation dates are as follows:

Date deliveries of products manufactured at a new manufacturing site will begin: **January 22, 2024**

First date code for such deliveries from new manufacturing site: **2404**

If you have any questions or need additional information, please feel free to contact [Bourns Customer Service/Inside Sales](#).