



Product Update Memo

SENSORS & CONTROLS PRODUCTS

August, 2006

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team

RoHS Compliance - Aluminum Bar Stock Shortage

Sensors & Controls Division is currently experiencing extended lead times for RoHS compliant aluminum bar stock. Every effort is being made to expedite current material orders; however, we do not have sufficient material to fill all immediate orders.

The following models use aluminum bar stock for bushings and/or shafts:

3400	3590	6534	6638	85/86
3435	3700/01	6537	6657	91 thru 96
3540/01	3750/51	6538	6674	99
3543/45	3851/52/56	6574	81/82	EM14
3500/01	51/52/53	6637	83/84	EN

As a result, we have several line items going overdue.

Our planners are working on recovery dates based on delivery of material. Additional information will be forthcoming. We apologize for the delays and inconvenience caused by this material shortage.

Regards,
Sensors & Controls Management Team