



October 6, 2010

Last October the decision was made to eliminate the end discs from the 200 volt parts and under, we are reintroducing this change.

In order to better conform to the rest of the industry, Cornell Dubilier has removed the insulating end disk on the following cataloged snap-in product. This removal applies only to the 380LX, 381LX, 382LX, 383LX, 380LQ, 381LQ, 381LR, and 381EL product 200 volts working and below.

When operated at these low voltages, the end disk serves no purpose. This removal eliminates the possibility of moisture being trapped under the end disk during board cleaning.

Should the end disk be required, add a +D to the end of the part number.

Thank you,

Jim Navarro

Snap-in Marketing Manager