

Product Change Notice

Date:	February 4, 2022
Overview:	Label change for select part numbers
Reason for Change:	Production location change
Affected Part No(s):	Please see part number listing on page 2 of this PCN
Design Change Detail:	Production of select part numbers is moving from Hungary to China, so the product labels will be updated accordingly. Please see page 2 of this PCN for the part number listing.
Effective Date:	Shipments beginning April 1, 2022
Last Time Buy Deadline:	N/A
Pricing:	Per current price file
ebm-papst employee:	Jeannine Zenobi
Attachments:	Part number listing
Comments:	The entire production line is being moved so all product specifications will remain the same; only the manufacturing location on the label will change

Affected Part Numbers

4856ZWU	RL90-18/50-034
4656ZWU-924	RL90-18/06-038
4656ZWU	4656EAU-003
4656ZWU-963	4656ZWU-006
4656EZ-975	4656EZU
RG90-18/56	4656EA-021
RET78-34/56-011	4586ZU-024
RET85-42/56-017	4656ZU-025
RET85-42/56-070	4856ZWU-065
RG125-19/56	4660N
RG125-19/06	4650 NU
RER125-19/56	4656 NU
RER125-19/56U-164	8556 VWU
RER125-19/56U-169	3656 U-714
4656N	3856 U-726
RL90-18/50	4586 ZWU-843
RL90-18/00	4606ZWU-845
RL90-18/56	4656 ZH
RL90-18/06	4606 ZH
RL90-18/00-033	4606 ZWU-879

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. - Orig, Released 08/28/14	Retention Period - 1 year	Dept. Owner - Sales/Marketing

ebm-papst Part Number
4856ZWU
4656ZWU-924
4656ZWU
4656ZWU-963
4656EZ-975
RG90-18/56
RET78-34/56-011
RET85-42/56-017
RET85-42/56-070
RG125-19/56
RG125-19/06
RER125-19/56
RER125-19/56U-164
RER125-19/56U-169
4656N
RL90-18/50
RL90-18/00
RL90-18/56
RL90-18/06
RL90-18/00-033
RL90-18/50-034
RL90-18/06-038
4656EAU-003
4656ZWU-006
4656EZU
4656EA-021
4586ZU-024
4656ZU-025
4856ZWU-065
4660N
4650 NU
4656 NU
8556 VWU
3656 U-714
3856 U-726
4586 ZWU-843
4606ZWU-845
4656 ZH
4606 ZH
4606 ZWU-879