

Product Change Notice


Date:	March 14, 2023
Overview:	We have changed the screws for the terminal box cover on select AC fans / blowers
Reason for Change:	Design optimization
Affected Part No(s):	Please see part listing on page 2 of this PCN
Design Change Detail:	The Phillips head screw has been replaced by a Torx T20 (Taptide II)
Effective Date:	Running change that began in February of 2023. Depending on existing inventory at ebm-papst Inc. in Farmington, CT, it may take some time for this change to be realized.
Last Time Buy Deadline:	N/A
Pricing:	No change
ebm-papst employee:	Jeannine Zenobi
Attachments:	Affected part numbers and screw design / placement images
Comments:	The screws on the terminal box cover must be removed to connect the wires inside the terminal box, and this change will require a different screwdriver


Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing

Affected Part Numbers

8300100239	G2D140-AC08-16	G2E160-AY50-95
8300100426	G2D146-BF04-24	G2E160-AY50-98
01920-1-7612	G2D146-BF06-10	G2E160-AY50-99
01922-1-7612	G2D160-AF02-09	G2E160-BY50-25
01953-1-7612	G2D160-AF02-15	G2E180-AA09-36
35001-1-7612	G2D160-AF02-28	G2E180-EH03-24
A2D200-AA04-29	G2D160-AF02-34	R2D180-AF04-10
A2D200-AA04-41	G2D160-AF02-37	R2D225-AG02-23
A2D200-AA04-48	G2D160-AF02-40	R2D225-AG02-31
A2D250-AA06-44	G2D160-AF02-41	R2D225-AG02-34
A2D250-AA06-71	G2D180-AE02-14	S2D170-BA04-08
A2D250-AA06-84	G2D180-AE02-15	S2D315-BQ08-34
CEG485-HB50-01	G2D180-AE02-29	S2E200-BF02-31
CHG090-AA05-10	G2D180-BD06-05	S2E300-BP02-35
CHG090-AA06-11	G2E108-AA01-56	S4D350-AA06-19
CHG090-AA07-12	G2E108-AA01-72	S4S250-AA02-17
CHW050-AA02-75	G2E108-AG63-68	W2D300-CP02-49
CLC000-AB01-02	G2E120-AR77-54	W2D300-CP08-43
CLC000-AB01-03	G2E120-AR77-D5	W2E200-CF02-27
D2E140-AI03-13	G2E146-BF01-47	W2E250-CE65-34
G2D120-AA04-09	G2E146-BF03-53	
G2D120-AA04-10	G2E160-AY47-64	

Screw Design / Placement

bisheriges Design previous design	zukünftiges Design future design
	
Kreuzschlitz Cross recess	Torx T20 Taptite II



Affected Part Numbers

8300100239
8300100426
01920-1-7612
01922-1-7612
01953-1-7612
35001-1-7612
A2D200-AA04-29
A2D200-AA04-41
A2D200-AA04-48
A2D250-AA06-44
A2D250-AA06-71
A2D250-AA06-84
CEG485-HB50-01
CHG090-AA05-10
CHG090-AA06-11
CHG090-AA07-12
CHW050-AA02-75
CLC000-AB01-02
CLC000-AB01-03
D2E140-AI03-13
G2D120-AA04-09
G2D120-AA04-10
G2D140-AC08-16
G2D146-BF04-24
G2D146-BF06-10
G2D160-AF02-09
G2D160-AF02-15
G2D160-AF02-28
G2D160-AF02-34
G2D160-AF02-37
G2D160-AF02-40
G2D160-AF02-41
G2D180-AE02-14
G2D180-AE02-15
G2D180-AE02-29
G2D180-BD06-05
G2E108-AA01-56
G2E108-AA01-72
G2E108-AG63-68
G2E120-AR77-54
G2E120-AR77-D5
G2E146-BF01-47
G2E146-BF03-53
G2E160-AY47-64
G2E160-AY50-95
G2E160-AY50-98
G2E160-AY50-99
G2E160-BY50-25
G2E180-AA09-36
G2E180-EH03-24
R2D180-AF04-10
R2D225-AG02-23
R2D225-AG02-31
R2D225-AG02-34

S2D170-BA04-08
S2D315-BQ08-34
S2E200-BF02-31
S2E300-BP02-35
S4D350-AA06-19
S4S250-AA02-17
W2D300-CP02-49
W2D300-CP08-43
W2E200-CF02-27
W2E250-CE65-34