

Product Change Notice

PCN#: EE-PCN15007
September, 15 2015

CLASSIFICATION OF CHANGE:

Assembly Site.

DESCRIPTION OF CHANGE:

The assembly for select power inductors will include an additional manufacturing location. A marking code of CG is in the date code to identify the manufacturing plant.

REASON FOR CHANGE:

The addition of the assembly site supplements existing capacity to enhance our ability to better serve customers.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS FAMILIES AFFECTED:

DR1030
DR1040
DR1050

Specific part numbers are listed on the following page.

TIME SCHEDULE:

Start Shipment Date: Nov 2015. Existing inventory is to be used as is.

Last Time Buy Date: n/a

Last Time Shipment Date: n/a

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Paul Wiener, Global Product Manager –Magnetics

CONTACT INFORMATION:

For questions or comments, please contact your local Eaton sales representative.

PARTS NUMBERS AFFECTED:

DR1030-1R1-R	DR1030-3R9-R	DR1030-8R2-R	DR1030-220-R	DR1030-680-R	DR1030-121-R
DR1030-1R8-R	DR1030-5R2-R	DR1030-100-R	DR1030-330-R	DR1030-820-R	DR1030-151-R
DR1030-2R8-R	DR1030-6R8-R	DR1030-150-R	DR1030-470-R	DR1030-101-R	
DR1040-1R5-R	DR1040-5R2-R	DR1040-100-R	DR1040-330-R	DR1040-820-R	DR1040-221-R
DR1040-2R5-R	DR1040-7R0-R	DR1040-150-R	DR1040-470-R	DR1040-101-R	DR1040-331-R
DR1040-3R8-R	DR1040-8R2-R	DR1040-220-R	DR1040-680-R	DR1040-151-R	
DR1050-R80-R	DR1050-6R8-R	DR1050-180-R	DR1050-470-R	DR1050-121-R	DR1050-331-R
DR1050-1R5-R	DR1050-8R2-R	DR1050-220-R	DR1050-560-R	DR1050-151-R	DR1050-391-R
DR1050-2R2-R	DR1050-100-R	DR1050-270-R	DR1050-680-R	DR1050-181-R	DR1050-471-R
DR1050-3R3-R	DR1050-120-R	DR1050-330-R	DR1050-820-R	DR1050-221-R	DR1050-561-R
DR1050-4R7-R	DR1050-150-R	DR1050-390-R	DR1050-101-R	DR1050-271-R	DR1050-681-R
DR1050-821-R	DR1050-102-R				