

Product Change Notification

PCN Tracking Number:	RLPCN111401
Product Category:	Electromechanical relays
Affected Product:	RY, JY, SY, A series,
Date:	08 April 2011

Description of Change:

Additional supplier for Polycarbonate material used in the listed relays.

Series and Part numbers:

RY: All Part numbers, Changed parts: Bobbin, Card and Basemold.

JY: All Part numbers, Changed parts: Bobbin and Baseblock.

SY: All Part numbers, Changed part: Bobbin.

A : All Part numbers, Changed part: Bobbin.

Details of change:

Current resin suppliers	After change resin suppliers
Mitsubishi Engineers Plastics Co	Mitsubishi Engineers Plastics Co <i>Additional:</i> Teijin Panlite TEIJIN CHEMICALS LTD

Reason for change:

Short of supply for the current Polycarbonate material, due to Tohoku Earthquake /Tsunami aftermath.

Start of using additional resin type:

June 2011, or after depletion of current material stock.

Reliability data will be available by end of April 2011.

Customer response:

Please send your comments, requests for additional information or support to your Fujitsu account manager.

Disclosure information:

None of this information shall be disclosed or forwarded to other suppliers or distributed outside your company, without approval from Fujitsu Components Europe B.V. Distributors are advised to forward this PCN to their customers who are buying the listed Relays.

This PCN information will also be available on <https://extranet.fceu.fujitsu.com>