

## Product/Process Change Notifications



# PCN - 15 081-R.1

Release Date: August 18 2015

<b>Product Name:</b>	Mezzostak			
	0.5 MM BTB			
<b>Product Manager:</b>	Paul Liu			
<b>Subject:</b>	Notification of Planned Change			
<b>Distribution:</b>	General			
<b>Type of Change:</b>	Location Change			
<b>Change Description:</b>	Nantong will set up semi-auto machine to produce Mezzostak high volume P/Ns. Low runner parts will be manufactured in the manual assembly line.			
<b>Reason for Change:</b>	FCI Dongguan is no longer supporting Mezzostak. So FCI Nantong will be supporting the parts in future. This change helps us to be in alignment with FCI dedication on customer orientation  <b>By R.1</b> : Part number 10106814-093012LF is added to the affected list.			
<b>Affected Parts:</b>	Attached list			
<b>Effective Date of Change:</b>	November 9, 2015			
<b>Last Time Buy Date:</b>	NA			
<b>Last Disty Return Date:</b>	NA			
<b>Last Time Shipment Date</b>	NA			
<b>Datasheet Attached?</b>	NA			
<b>Qual/Test Data Attached?</b>	NA			
<b>Samples Availability Date:</b>	November	9	2015	
<b>Available Alternatives?</b>	N/A			
<b>Questions?</b>	<i>Contact your local FCI Representative, or Product Manager</i>			
	<i>Paul Liu</i>			
	<i>Paul Liu@fci.com</i>			

Note:  
 Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date.  
 PCN is considered approved by the customer if no communication is received within 3 weeks

PCN	Item Number	Change	Effective Date	Last Time Buy Date	Last Disty return date	Replacement Part	Alternate Part	Comments
PCN15081	10106813-021112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-023112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-024112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-031112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-033112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-034112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-041112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-043112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-044112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-051112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-053112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-054112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-061112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-063112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-064112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-071112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-073112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-074112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106813-174112LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-021002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-023002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-024002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-031002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-033002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-034002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-041002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-043002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-044002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-051002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-053002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-054002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-061002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-063002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-064002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-071002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-073002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-074002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-083002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-083202LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-093002LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-093012LF	LOCATION CHANGE	9-Nov-15					
PCN15081	10106814-093202LF	LOCATION CHANGE	9-Nov-15					