

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives and Distributors

Date: November 19, 2015

Subject: 87 Series Keypad Dome Contact Change

This Product Advisory Notice is to alert you that Grayhill is changing the dome contact for all 87 Series Standard and Custom Keypads.

Description of Change

Due to a supply chain issue on the current dome contact used on this keypad assembly, Grayhill will be temporarily changing the dome contact to a drop in equivalent dome effective immediately. This dome contact change will have no effect on the published specifications for this keypad series.

Reason for Change

The current supply chain issue has already delayed shipments by 8 weeks and threatens to delay them an additional 12 weeks. An alternative dome contact was immediately available from one of our existing suppliers. After extensive testing of both the dome and representative keypad assemblies, the alternate was approved for production.

Effective Date

November 19, 2015



PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

Part Numbers Affected

| | | | | |
|---------------|---------------|---------------|---------------|---------------|
| 87AB3-201 | 87YY3201A-681 | 87YY3201A-710 | 87YY3204A-524 | 87YY3206A-521 |
| 87AC3-201 | 87YY3201A-682 | 87YY3201A-711 | 87YY3204A-529 | 87YY3206A-522 |
| 87BB3-201 | 87YY3201A-683 | 87YY3201A-712 | 87YY3204A-531 | 87YY3206A-523 |
| 87BC3-201 | 87YY3201A-684 | 87YY3201A-713 | 87YY3204A-546 | 87YY3612A-510 |
| 87CC3-201 | 87YY3201A-685 | 87YY3201A-714 | 87YY3204A-552 | 87YY3616A-514 |
| 87DC3-201 | 87YY3201A-686 | 87YY3201A-715 | 87YY3204A-553 | 87YY3616A-515 |
| 87EC3-201 | 87YY3201A-687 | 87YY3201A-716 | 87YY3204A-570 | 87YY3616A-519 |
| 87FC3-201 | 87YY3201A-688 | 87YY3201A-717 | 87YY3204A-571 | 87YY3616A-529 |
| 87GC3-201 | 87YY3201A-689 | 87YY3201A-718 | 87YY3204A-572 | 87YY3616A-530 |
| 87HC3-201 | 87YY3201A-690 | 87YY3201A-719 | 87YY3204A-573 | 87YY3616A-534 |
| 87YY3201A-507 | 87YY3201A-691 | 87YY3202A-520 | 87YY3204A-574 | 87YY3616A-539 |
| 87YY3201A-544 | 87YY3201A-692 | 87YY3202A-532 | 87YY3204A-575 | 87YY3616A-541 |
| 87YY3201A-545 | 87YY3201A-693 | 87YY3202A-549 | 87YY3205A-509 | 87YY3616A-543 |
| 87YY3201A-546 | 87YY3201A-694 | 87YY3203A-546 | 87YY3205A-510 | 87YY5000-1 |
| 87YY3201A-547 | 87YY3201A-698 | 87YY3203A-547 | 87YY3205A-515 | 87YY5004 |
| 87YY3201A-548 | 87YY3201A-700 | 87YY3203A-548 | 87YY3205A-519 | 87YY5007 |
| 87YY3201A-583 | 87YY3201A-701 | 87YY3203A-549 | 87YY3205A-520 | |
| 87YY3201A-586 | 87YY3201A-702 | 87YY3203A-550 | 87YY3205A-526 | |
| 87YY3201A-587 | 87YY3201A-703 | 87YY3203A-566 | 87YY3205A-532 | |
| 87YY3201A-613 | 87YY3201A-704 | 87YY3203A-567 | 87YY3206A-513 | |
| 87YY3201A-659 | 87YY3201A-705 | 87YY3204A-502 | 87YY3206A-514 | |
| 87YY3201A-660 | 87YY3201A-706 | 87YY3204A-504 | 87YY3206A-517 | |
| 87YY3201A-661 | 87YY3201A-707 | 87YY3204A-505 | 87YY3206A-518 | |
| 87YY3201A-671 | 87YY3201A-708 | 87YY3204A-513 | 87YY3206A-519 | |
| 87YY3201A-680 | 87YY3201A-709 | 87YY3204A-520 | 87YY3206A-520 | |

Action Required

Please forward this notification to the appropriate person(s) in your organization. No other action is required. However, if you would like to receive a copy of the test reports, please contact your Grayhill, Inc. Sales Associate.

