

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: Grayhill Customers
Date: February 28, 2018
Subject: Re-tooling 60A, 60AD and 67C Series Mounting Nut

This Product Advisory Notice is to alert you that there is a coming change to all Grayhill Series 60A, 60AD and 67C joystick encoders. ***Please forward this notification to the appropriate person(s) in your organization.***

Description of Change

Grayhill has re-tooled the 60A and 60AD series mounting nut due to excessive wear on the existing tool.

Grayhill has successfully completed qualification testing on joysticks built with the mounting nut from the new tool. The qualification consisted of an approved supplier PPAP and push-out force testing.

Reason for Change

The mounting nut had to be re-tooled since the old tool is reaching its end of life.

Effective Date

3-1-18

Part Numbers Affected

This change effects all 60A, 60AD and 67C Part Numbers

Action Required

If you have questions, please contact your Grayhill, Inc. Sales Associate for further information at 708.354.1040.

