

Product Change Notification / ASER-28GLZI333

_				
_	_	•	_	_
	Э.	-	0	•
u	а.	L	_	-

04-Apr-2022

Product Category:

USB Hubs

PCN Type:

End of Life

Notification Subject:

eSign E000100139: End of Life (EOL) of selected USB5532Bxxx, USB5533Bxxx, USB5534Bxxx and USB5537Bxxx device families.

Affected CPNs:

ASER-28GLZI333_Affected_CPN_04042022.pdf ASER-28GLZI333_Affected_CPN_04042022.csv

Notification Text:

PCN Status: End of Life (EOL) Notification

Microchip Parts Affected: Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN_#_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The USB5532Bxxx, USB5533Bxxx, USB5534Bxxx and USB5537Bxxx device families will be moving to End of Life (EOL) status effective today. These catalog part numbers will no longer be offered after September 30, 2022. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your Local Sales Representative Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates Customers affected by this EOL notice are advised to place last time buy (LTB) orders

as follows:

Last date for bookings (LTB): April 30, 2022

Last date for shipments (LTS): September 30, 2022

Revision History:April 4, 2022: Issued the EOL notification

Attachments:

PCN_ASER-28GLZI333_Suggested Replacements.pdf PCN_ASER-28GLZI333_Suggested Replacements.xlsx

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN</u> home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

 $ASER-28GLZI333-eSign\ E000100139; End\ of\ Life\ (EOL)\ of\ selected\ USB5532Bxxx,\ USB5533Bxxx,\ USB5534Bxxx\ and\ USB5537Bxxx\ device\ families.$

Affected Catalog Part Numbers (CPN)

USB5532B-5000JZX

USB5532B-5000JZXTR

USB5533B-5000JZX

USB5533B-5000JZXTR

USB5534B-5000JZX

USB5534B-5000JZXTR

USB5534B-4100JZX

USB5534B-4100JZXTR

USB5537B-5000AKZE

USB5537B5000AKZETR

USB5537B-4100AKZE

USB5537B4100AKZETR

Date: Monday, April 04, 2022

PCN_ASER-28GLZI333				
EOL Catalog Part Number (CPN)	Replacement CPN	Notes about Recommended Replacement parts		
USB5532B-5000JZX	USB5532B-6080JZX			
USB5532B-5000JZXTR	USB5532B-6080JZXTR			
USB5533B-5000JZX	USB5533B-6080JZX			
USB5533B-5000JZXTR	USB5533B-6080JZXTR	All USB5532Bxxx, USB5533Bxxx,		
USB5534B-5000JZX	USB5534B-6080JZX	USB5534Bxxx and USB5537Bxxx		
USB5534B-5000JZXTR	USB5534B-6080JZXTR	products being EOL'd have a pin		
USB5534B-4100JZX	USB5534B-6080JZX	compatible replacement part on a		
USB5534B-4100JZXTR	USB5534B-6080JZXTR	newer mask set.		
USB5537B-5000AKZE	USB5537B-6080AKZE	Contact Your Local Sales Office		
USB5537B5000AKZETR	USB5537B-6080AKZETR			
USB5537B-4100AKZE	USB5537B-6080AKZE			
USB5537B4100AKZETR	USB5537B-6080AKZETR			