

## Product Change Notification

The information below reflects a change that is being implemented.

Notice Date: 11/17/2005

Product Category: dsPIC; PIC16xxx; PIC17xxx; PIC18xxx

Notification Subject: Change #604 - Qual. of 6700HA Mold Compound for 44L/64L TQFP Packages at MTHAI Assembly

### Notification Body:

#### Microchip Part#s Affected

DSPIC30F3011  
DSPIC30F3014  
DSPIC30F4011  
DSPIC30F4013  
DSPIC30F5011  
DSPIC30F5015  
PIC16C63A, PIC16FR63A, PIC16LC63A, PIC16LFR63A  
PIC16C64A, PIC16LC64A  
PIC16C65A, PIC16FR65A, PIC16LC65A  
PIC16C65B, PIC16LC65B  
PIC16C662, PIC16LC662  
PIC16C67, PIC16FR67, PIC16LC67, PIC16LFR67  
PIC16C74A, PIC16FR74A, PIC16LC74A, PIC16LFR74A  
PIC16C74B, PIC16LC74B  
PIC16C765  
PIC16C77, PIC16FR77, PIC16LC77, PIC16LFR77  
PIC16C774, PIC16LC774  
PIC16C923, PIC16LC923  
PIC16C924, PIC16LC924  
PIC16C925, PIC16LC925  
PIC16C926, PIC16LC926  
PIC16CR65  
PIC16CR66  
PIC16CR67  
PIC16CR76  
PIC16CR77  
PIC16F59  
PIC16F74, PIC16LF74  
PIC16F747, PIC16LF747  
PIC16F77, PIC16LF77  
PIC16F777, PIC16LF777  
PIC16F871, PIC16LF871  
PIC16F874, PIC16LF874  
PIC16F874A, PIC16LF874A

PIC16F877, PIC16LF877  
PIC16F877A, PIC16LF877A  
PIC16F917  
PIC16F946  
PIC17C42A, PIC17FR42A, PIC17LC42A, PIC17LFR42A  
PIC17C43, PIC17FR43, PIC17LC43, PIC17LFR43  
PIC17C44, PIC17FR44, PIC17LC44, PIC17LFR44  
PIC17C752, PIC17LC752  
PIC17C756A, PIC17LC756A  
PIC18C442, PIC18LC442  
PIC18C452, PIC18LC452  
PIC18C601, PIC18LC601  
PIC18C658, PIC18LC658  
PIC18F4220, PIC18LF4220  
PIC18F4221, PIC18LF4221  
PIC18F4320, PIC18LF4320  
PIC18F4321, PIC18LF4321  
PIC18F4331, PIC18LF4331  
PIC18F4410, PIC18LF4410  
PIC18F4415, PIC18LF4415  
PIC18F442, PIC18F4439, PIC18LF442 , PIC18LF4439  
PIC18F4420, PIC18LF4420, PIC18LF4423  
PIC18F4425, PIC18LF4425  
PIC18F4431, PIC18LF4431  
PIC18F4455, PIC18LF4455  
PIC18F448, PIC18LF448  
PIC18F4480, PIC18LF4480  
PIC18F4481, PIC18LF4481  
PIC18F4510, PIC18LF4510  
PIC18F4515, PIC18LF4515  
PIC18F452, PIC18F4539, PIC18LF452 , PIC18LF4539  
PIC18F4520, PIC18LF4520, PIC18LF4523  
PIC18F4525, PIC18LF4525  
PIC18F4550, PIC18LF4550  
PIC18F458, PIC18LF458  
PIC18F4580, PIC18LF4580  
PIC18F4581, PIC18LF4581  
PIC18F4585, PIC18LF4585  
PIC18F4586, PIC18LF4586  
PIC18F4610, PIC18LF4610  
PIC18F4620, PIC18LF4620  
PIC18F4680, PIC18LF4680  
PIC18F4681, PIC18LF4681  
PIC18F6310, PIC18LF6310  
PIC18F6390, PIC18LF6390  
PIC18F6410, PIC18LF6410  
PIC18F6490, PIC18LF6490  
PIC18F6520, PIC18LF6520  
PIC18F6525, PIC18LF6525  
PIC18F6527, PIC18LF6527  
PIC18F6585, PIC18LF6585  
PIC18F65J10  
PIC18F65J15  
PIC18F6620, PIC18LF6620  
PIC18F6621, PIC18LF6621  
PIC18F6622, PIC18LF6622

PIC18F6627, PIC18LF6627  
PIC18F6680, PIC18LF6680  
PIC18F66J10  
PIC18F66J15  
PIC18F6720, PIC18LF6720  
PIC18F6722, PIC18LF6722  
PIC18F67J10

Description of Change:  
NEW MOLD COMPOUND

Impacts to Data Sheet:  
NONE

Reason for Change:  
IMPROVED MANUFACTURABILITY

Estimated Change Implementation Date(s):  
DECEMBER, 2005

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date  
Code, Device Marking, Ship Container Marking)  
COO, DATE CODE

---