

Product / Process Change Notification JLIO-7MCTR5

[Home](#)

The information below reflects a change that is being implemented.

Notice Date: 12/17/2008

Product Category: Battery Management; Linear Devices; Mixed Signal Devices; Power Management; Thermal Management

Notification Subject: CCB#869: QUALIFICATION OF 8L & 10L MSOP WITH 8200T EPOXY AND G600 MOLD COMPOUND AT UTL ASSEMBLY

Notification Body:

PCN Status:
Initial Notification

Microchip Part#s Affected (please see the link for these files at the end of this PCN):
[CCB#869 _Microchip Catalog Part#s Affected.xls](#)
[CCB#869 _Microchip Catalog Part#s Affected.pdf](#)

Description of Change:
Change in bill of materials

Pre-Change:
Mold compound: KMC 184-7
Die attach epoxy: 84-1LMISR4

Post-Change:
Mold compound: G600
Die attach epoxy: 8200T

Impacts to Data Sheet:
None

Reason for Change:
To improve manufacturability

Change Implementation Status:
In progress

Estimated Change Implementation Date(s):

February 28th, 2009 (Date Code: 0909)

NOTE: Please be advised that during a transition period you may receive parts with either bill of materials, due to existing inventory of the original bill of materials.

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date Code, Device Marking, Ship Container Marking)
Traceability code

Microchip Catalog Part#s Affected

MCP1256-E/UN
MCP1256T-E/UN
MCP1257-E/UN
MCP1257T-E/UN
MCP1257T-E/UNV01
MCP1258-E/UN
MCP1258T-E/UN
MCP1259-E/UN
MCP1259T-E/UN
MCP1653R-E/UN
MCP1653RT-E/UN
MCP1653S-E/UN
MCP1653ST-E/UN
MCP3423-E/UN
MCP3423T-E/UN
MCP4232-103E/UN
MCP4232-104E/UN
MCP4232-502E/UN
MCP4232-503E/UN
MCP4232T-103E/UN
MCP4232T-104E/UN
MCP4232T-502E/UN
MCP4232T-503E/UN
MCP4242-103E/UN
MCP4242-104E/UN
MCP4242-502E/UN
MCP4242-503E/UN
MCP4242T-103E/UN
MCP4242T-104E/UN
MCP4242T-502E/UN
MCP4242T-503E/UN
MCP4252-103E/UN
MCP4252-104E/UN
MCP4252-502E/UN
MCP4252-503E/UN
MCP4252T-103E/UN
MCP4252T-104E/UN
MCP4252T-502E/UN
MCP4252T-503E/UN
MCP4262-103E/UN
MCP4262-104E/UN
MCP4262-502E/UN
MCP4262-503E/UN
MCP4262T-103E/UN
MCP4262T-104E/UN
MCP4262T-502E/UN
MCP4262T-503E/UN
MCP4632-103E/UN
MCP4632-104E/UN
MCP4632-502E/UN
MCP4632-503E/UN

Microchip Catalog Part#s Affected

MCP4632T-103E/UN
MCP4632T-104E/UN
MCP4632T-502E/UN
MCP4632T-503E/UN
MCP4642-103E/UN
MCP4642-104E/UN
MCP4642-502E/UN
MCP4642-503E/UN
MCP4642T-103E/UN
MCP4642T-104E/UN
MCP4642T-502E/UN
MCP4642T-503E/UN
MCP4652-103E/UN
MCP4652-104E/UN
MCP4652-502E/UN
MCP4652-503E/UN
MCP4652T-103E/UN
MCP4652T-104E/UN
MCP4652T-502E/UN
MCP4652T-503E/UN
MCP4662-103E/UN
MCP4662-104E/UN
MCP4662-502E/UN
MCP4662-503E/UN
MCP4662T-103E/UN
MCP4662T-104E/UN
MCP4662T-502E/UN
MCP4662T-503E/UN
MCP6S93-E/UN
MCP6S93T-E/UN
MCP73833-6SI/UN
MCP73833-AMI/UN
MCP73833-B6I/UN
MCP73833-BZI/UN
MCP73833-CNI/UN
MCP73833-FCI/UN
MCP73833-G8I/UN
MCP73833-GPI/UN
MCP73833-NVI/UN
MCP73833-YAI/UN
MCP73833T-6SI/UN
MCP73833T-AMI/UN
MCP73833T-B6I/UN
MCP73833T-BZI/UN
MCP73833T-CNI/UN
MCP73833T-FCI/UN
MCP73833T-G8I/UN
MCP73833T-GPI/UN
MCP73833T-NVI/UN
MCP73833T-YAI/UN
MCP73834-6SI/UN

Microchip Catalog Part#s Affected

MCP73834-B6I/UN
MCP73834-CNI/UN
MCP73834-FCI/UN
MCP73834-G8I/UN
MCP73834-GPI/UN
MCP73834-NVI/UN
MCP73834-YAI/UN
MCP73834T-6SI/UN
MCP73834T-B6I/UN
MCP73834T-CNI/UN
MCP73834T-FCI/UN
MCP73834T-G8I/UN
MCP73834T-GPI/UN
MCP73834T-NVI/UN
MCP73834T-YAI/UN
MCP73837-FCI/UN
MCP73837-FJI/UN
MCP73837-NVI/UN
MCP73837T-FCI/UN
MCP73837T-FJI/UN
MCP73837T-NVI/UN
MCP73838-FCI/UN
MCP73838-FJI/UN
MCP73838-NVI/UN
MCP73838T-FCI/UN
MCP73838T-FJI/UN
MCP73838T-NVI/UN
MCP73842-820I/UN
MCP73842-840I/UN
MCP73842T-820I/UN
MCP73842T-840I/UN
TC1303A-PP3EUN
TC1303A-PP3EUNTR
TC1303A-ZA0EUN
TC1303A-ZA0EUNTR
TC1303A-ZI0EUN
TC1303A-ZI0EUNTR
TC1303A-ZP0EUN
TC1303A-ZP0EUNTR
TC1303A-ZS0EUN
TC1303A-ZS0EUNTR
TC1303B-AG0EUN
TC1303B-AG0EUNTR
TC1303B-IA0EUN
TC1303B-IA0EUNTR
TC1303B-PA0EUN
TC1303B-PA0EUNTR
TC1303B-PF0EUN
TC1303B-PF0EUNTR
TC1303B-PG0EUN
TC1303B-PG0EUNTR

Microchip Catalog Part#s Affected

TC1303B-PI0EUN
TC1303B-PI0EUNTR
TC1303B-VS0EUN
TC1303B-VS0EUNTR
TC1303B-ZA0EUN
TC1303B-ZA0EUNTR
TC1303B-ZI0EUN
TC1303B-ZI0EUNTR
TC1303B-ZP0EUN
TC1303B-ZP0EUNTR
TC1303B-ZS0EUN
TC1303B-ZS0EUNTR
TC1303C-VP0EUN
TC1303C-VP0EUNTR
TC1303C-ZA0EUN
TC1303C-ZA0EUNTR
TC1303C-ZI0EUN
TC1303C-ZI0EUNTR
TC1303C-ZP0EUN
TC1303C-ZP0EUNTR
TC1303C-ZS0EUN
TC1303C-ZS0EUNTR
TC1304-VI0EUN
TC1304-VI0EUNTR
TC1304-ZA0EUN
TC1304-ZA0EUNTR
TC1304-ZI0EUN
TC1304-ZI0EUNTR
TC1304-ZP0EUN
TC1304-ZP0EUNTR
TC1304-ZS0EUN
TC1304-ZS0EUNTR
TC1313-1H0EUN
TC1313-1H0EUNTR
TC1313-1P0EUN
TC1313-1P0EUNTR
TC1313-ZA0EUN
TC1313-ZA0EUNTR
TC1313-ZI0EUN
TC1313-ZI0EUNTR
TC1313-ZP0EUN
TC1313-ZP0EUNTR
TC1313-ZS0EUN
TC1313-ZS0EUNTR
TC654EUN
TC654EUNTR
TC655EUN
TC655EUNTR
TC664EUN
TC664EUNTR
TC665EUN

Microchip Catalog Part#s Affected
TC665EUNTR

Microchip Catalog Part#s Affected

MCP1256-E/UN
MCP1256T-E/UN
MCP1257-E/UN
MCP1257T-E/UN
MCP1257T-E/UNV01
MCP1258-E/UN
MCP1258T-E/UN
MCP1259-E/UN
MCP1259T-E/UN
MCP1653R-E/UN
MCP1653RT-E/UN
MCP1653S-E/UN
MCP1653ST-E/UN
MCP3423-E/UN
MCP3423T-E/UN
MCP4232-103E/UN
MCP4232-104E/UN
MCP4232-502E/UN
MCP4232-503E/UN
MCP4232T-103E/UN
MCP4232T-104E/UN
MCP4232T-502E/UN
MCP4232T-503E/UN
MCP4242-103E/UN
MCP4242-104E/UN
MCP4242-502E/UN
MCP4242-503E/UN
MCP4242T-103E/UN
MCP4242T-104E/UN
MCP4242T-502E/UN
MCP4242T-503E/UN
MCP4252-103E/UN
MCP4252-104E/UN
MCP4252-502E/UN
MCP4252-503E/UN
MCP4252T-103E/UN
MCP4252T-104E/UN
MCP4252T-502E/UN
MCP4252T-503E/UN
MCP4262-103E/UN
MCP4262-104E/UN
MCP4262-502E/UN
MCP4262-503E/UN
MCP4262T-103E/UN
MCP4262T-104E/UN
MCP4262T-502E/UN
MCP4262T-503E/UN
MCP4632-103E/UN
MCP4632-104E/UN
MCP4632-502E/UN

MCP4632-503E/UN
MCP4632T-103E/UN
MCP4632T-104E/UN
MCP4632T-502E/UN
MCP4632T-503E/UN
MCP4642-103E/UN
MCP4642-104E/UN
MCP4642-502E/UN
MCP4642-503E/UN
MCP4642T-103E/UN
MCP4642T-104E/UN
MCP4642T-502E/UN
MCP4642T-503E/UN
MCP4652-103E/UN
MCP4652-104E/UN
MCP4652-502E/UN
MCP4652-503E/UN
MCP4652T-103E/UN
MCP4652T-104E/UN
MCP4652T-502E/UN
MCP4652T-503E/UN
MCP4662-103E/UN
MCP4662-104E/UN
MCP4662-502E/UN
MCP4662-503E/UN
MCP4662T-103E/UN
MCP4662T-104E/UN
MCP4662T-502E/UN
MCP4662T-503E/UN
MCP6S93-E/UN
MCP6S93T-E/UN
MCP73833-6SI/UN
MCP73833-AMI/UN
MCP73833-B6I/UN
MCP73833-BZI/UN
MCP73833-CNI/UN
MCP73833-FCI/UN
MCP73833-G8I/UN
MCP73833-GPI/UN
MCP73833-NVI/UN
MCP73833-YAI/UN
MCP73833T-6SI/UN
MCP73833T-AMI/UN
MCP73833T-B6I/UN
MCP73833T-BZI/UN
MCP73833T-CNI/UN
MCP73833T-FCI/UN
MCP73833T-G8I/UN
MCP73833T-GPI/UN
MCP73833T-NVI/UN
MCP73833T-YAI/UN

MCP73834-6SI/UN
MCP73834-B6I/UN
MCP73834-CNI/UN
MCP73834-FCI/UN
MCP73834-G8I/UN
MCP73834-GPI/UN
MCP73834-NVI/UN
MCP73834-YAI/UN
MCP73834T-6SI/UN
MCP73834T-B6I/UN
MCP73834T-CNI/UN
MCP73834T-FCI/UN
MCP73834T-G8I/UN
MCP73834T-GPI/UN
MCP73834T-NVI/UN
MCP73834T-YAI/UN
MCP73837-FCI/UN
MCP73837-FJI/UN
MCP73837-NVI/UN
MCP73837T-FCI/UN
MCP73837T-FJI/UN
MCP73837T-NVI/UN
MCP73838-FCI/UN
MCP73838-FJI/UN
MCP73838-NVI/UN
MCP73838T-FCI/UN
MCP73838T-FJI/UN
MCP73838T-NVI/UN
MCP73842-820I/UN
MCP73842-840I/UN
MCP73842T-820I/UN
MCP73842T-840I/UN
TC1303A-PP3EUN
TC1303A-PP3EUNTR
TC1303A-ZA0EUN
TC1303A-ZA0EUNTR
TC1303A-ZI0EUN
TC1303A-ZI0EUNTR
TC1303A-ZP0EUN
TC1303A-ZP0EUNTR
TC1303A-ZS0EUN
TC1303A-ZS0EUNTR
TC1303B-AG0EUN
TC1303B-AG0EUNTR
TC1303B-IA0EUN
TC1303B-IA0EUNTR
TC1303B-PA0EUN
TC1303B-PA0EUNTR
TC1303B-PF0EUN
TC1303B-PF0EUNTR
TC1303B-PG0EUN

TC1303B-PG0EUNTR
TC1303B-PI0EUN
TC1303B-PI0EUNTR
TC1303B-VS0EUN
TC1303B-VS0EUNTR
TC1303B-ZA0EUN
TC1303B-ZA0EUNTR
TC1303B-ZI0EUN
TC1303B-ZI0EUNTR
TC1303B-ZP0EUN
TC1303B-ZP0EUNTR
TC1303B-ZS0EUN
TC1303B-ZS0EUNTR
TC1303C-VP0EUN
TC1303C-VP0EUNTR
TC1303C-ZA0EUN
TC1303C-ZA0EUNTR
TC1303C-ZI0EUN
TC1303C-ZI0EUNTR
TC1303C-ZP0EUN
TC1303C-ZP0EUNTR
TC1303C-ZS0EUN
TC1303C-ZS0EUNTR
TC1304-VI0EUN
TC1304-VI0EUNTR
TC1304-ZA0EUN
TC1304-ZA0EUNTR
TC1304-ZI0EUN
TC1304-ZI0EUNTR
TC1304-ZP0EUN
TC1304-ZP0EUNTR
TC1304-ZS0EUN
TC1304-ZS0EUNTR
TC1313-1H0EUN
TC1313-1H0EUNTR
TC1313-1P0EUN
TC1313-1P0EUNTR
TC1313-ZA0EUN
TC1313-ZA0EUNTR
TC1313-ZI0EUN
TC1313-ZI0EUNTR
TC1313-ZP0EUN
TC1313-ZP0EUNTR
TC1313-ZS0EUN
TC1313-ZS0EUNTR
TC654EUN
TC654EUNTR
TC655EUN
TC655EUNTR
TC664EUN
TC664EUNTR

TC665EUN
TC665EUNTR