



A Leading Provider of Microcontrollers & Analog Semiconductors

Product Change Notification - CYER-31WSMC085

Date: 26 Mar 2012

Product Category: Memory

Device Family:  

Notification subject: CCB 1061.01 Final Notification: Qualification of 48B WFBGA package at LPI assembly site.

Notification text:

PCN Status:
Final notification

Microchip Parts Affected:
See attachments of affected catalog part numbers (CPN) labeled as...
PCN_CYER-31WSMC085_Affected_CPN.xls
PCN_CYER-31WSMC085_Affected_CPN.pdf

Description of Change:
Qualification of 48B WFBGA package at LPI assembly site.

Impacts to Data Sheet:
None

Reason for Change:
To Improve On-Time Delivery Performance

Change Implementation Status:
Complete

Estimated First Ship Date:
April 16, 2012 (date code: 1216)

NOTE: Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

Markings to Distinguish Revised from Unrevised Devices:
Traceability code

Revision History:
June 2, 2011: Issued initial notification.
March 27, 2012: Issued final notification. Attached the qualification report. Revised the estimated first ship date from 12/1/2011 to 4/16/2012.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

SST39LF400A
SST39VF200A
SST39VF400A
SST39VF800A
SST39WF1601
SST39WF1602
SST39WF400A
SST39WF400B
SST39WF800A
SST39WF800B