


**Product Change Notification - CYER-05DBLC684**

---

**Date:** 06 Sep 2012  
**Product Category:** Analog (Linear & Mixed Signal) AND Interface; 8-bit Microcontrollers; 16-bit Microcontrollers and Digital Signal Controllers; Memory, RF and Security  
**Device Family:**   
**Notification subject:** CCB 1046.02 Final Notice: Qualification of 14L TSSOP package at MMT (ALPH) assembly site.  
**Notification text:**

**PCN Status:**  
Final notification

**Microchip Parts Affected:**  
See attachments of affected catalog part numbers (CPN) labeled as...  
PCN\_CYER-05DBLC684\_Affected\_CPN.xls  
PCN\_CYER-05DBLC684\_Affected\_CPN.pdf

**Description of Change:**  
Qualification of 14L TSSOP package at MMT (ALPH) assembly site.

**Impacts to Data Sheet:**  
None

**Reason for Change:**  
To improve on time delivery performance

**Change Implementation Status:**  
In Progress

**Estimated First Ship Date:**  
September 12, 2012 (date code: 1237)

**NOTE:** Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

**Markings to Distinguish Revised from Unrevised Devices:**  
Traceability code

**Revision History:**  
April 11, 2012: Issued initial notification.

September 6, 2012: Issued final notification. Attached qualification report. Revised the estimated first ship date from 8/18/2012 to 9/12/2012.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

**Attachment(s):** [PCN\\_CYER-05DBLC684\\_Qual\\_Report.pdf](#)  
[PCN\\_CYER-DBLC684\\_Affected\\_CPN.xls](#)  
[PCN\\_CYER-DBLC684\\_Affected\\_CPN.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

MCP42100  
MCP4231  
MCP4241  
MCP4251  
MCP4261  
MCP4332  
MCP4342  
MCP4352  
MCP4362  
MCP4432  
MCP4442  
MCP4452  
MCP4462  
MCP4631  
MCP4641  
MCP4651  
MCP4661  
MCP4902  
MCP4912  
MCP4922  
MCP6004  
MCP6024  
MCP6034  
MCP6044  
MCP604  
MCP6054  
MCP6064  
MCP6074  
MCP609  
MCP6144  
MCP619  
MCP6234  
MCP6244  
MCP624  
MCP6274  
MCP6284  
MCP6294  
MCP634  
MCP6404  
MCP6444  
MCP6544  
MCP6549  
MCP654  
MCP6564

MCP6569  
MCP660  
MCP664  
MCP6G04  
MCP6H04  
MCP6L04  
MCP6L4  
MCP6L74  
MCP6L94  
MCP6S26  
PIC12LF1840T48A  
PIC16F1503  
PIC16F1823  
PIC16F1824  
PIC16F1825  
PIC16F505  
PIC16F506  
PIC16F526  
PIC16F610  
PIC16F616  
PIC16F630  
PIC16F636  
PIC16F676  
PIC16F684  
PIC16F688  
PIC16C505  
PIC24F04KA200  
PIC24F04KL100  
PIC24F08KL200  
24AA512  
24FC512  
24LC512  
HCS370  
MCP2022  
MCP2022A  
MCP2030  
MCP3004  
MCP3204  
MCP3302  
MCP3424  
MCP3428  
MCP42010  
MCP42050